



Release Notes for Cisco Configuration Professional 2.0

October 20, 2009

These release notes support Cisco Configuration Professional (Cisco CP) version 2.0. They should be used with the documents listed in the “[Related Documentation](#)” section.

These release notes are updated as needed. To ensure that you have the latest version of these release notes, go to <http://www.cisco.com/go/ciscocp>. In the Support box, click **General Information > Release Notes**, and then find the latest release notes for your release.

Contents

This document contains the following sections:

- [Introduction](#)
- [System Requirements](#)
- [New and Changed Information](#)
- [Limitations and Restrictions](#)
- [Important Notes](#)
- [Caveats](#)
- [Related Documentation](#)



Introduction

Cisco CP is a GUI-based device management tool for Cisco access routers. Cisco CP simplifies router, firewall, IPS, VPN, unified communications, WAN, and basic LAN configuration through GUI-based, easy-to-use wizards. Cisco CP is installed on a PC.

Routers that are ordered with Cisco CP are shipped with Cisco Configuration Professional Express (Cisco CP Express) installed in router flash memory. Cisco CP Express is a light weight version of Cisco CP, that you can use to configure LAN and WAN interfaces and minimal IOS security features.

System Requirements

This sections describes PC and router system requirements. It contains the following parts:

- [PC System Requirements](#)
- [Router System Requirements](#)
- [Cisco CP Ordering Options](#)

PC System Requirements

[Table 1](#) lists the system requirements for a PC running Cisco CP. Although the Cisco CP application requires JRE to run, the Cisco CP Express application included with Cisco CP can run under the native Java Virtual Machine in the supported browsers, and also JRE.

Table 1 *PC System Requirements*

System Component	Requirement
Processor	2 GHz processor or faster
Random Access Memory	1 GB
Hard disk available memory	400 MB
Operating System	Any of the following: <ul style="list-style-type: none"> • Microsoft Windows Vista Business Edition • Microsoft Windows Vista Ultimate Edition • Microsoft Windows XP with Service Pack 2 or later • Mac OSX 10.5.6 running Windows XP using VMWare 2.0
Browser	Internet Explorer 6.0 or above
Screen Resolution	1024 X 768
Java Runtime Environment	JRE versions minimum 1.5.0_11 upto 1.6.0_16 are supported.
Adobe Flash Player	Version 10.0 or later, with Debug set to No
Secure Shell (SSH)	Required for secure connections with the router. Versions up to 1.99 are supported.

Router System Requirements

Router System Requirements are described in the following parts:

- [Supported Routers](#)
- [Supported Phones](#)
- [Supported Network Modules](#)
- [Supported Interface Cards](#)
- [Supported Adapters, Processing Engines, and Service Engines](#)
- [Cisco IOS Releases](#)
- [Required IP Address Configuration Information](#)
- [Router Configuration Requirements](#)

Supported Routers

[Table 2](#) and [Table 3](#) list the routers that Cisco CP supports.

Table 2 *Supported Integrated Services Routers (ISR)*

Cisco 800 Series	Cisco 1800 Series	Cisco 2800 Series	Cisco 3800 Series	Cisco 7000 Series
CISCO815	CISCO1801	Cisco 2801	Cisco 3825	Cisco 7204VXR
CISCO815-VPN-K9	CISCO1801-M	Cisco 2811	Cisco 3825-NOVPN	Cisco 7206VXR
	CISCO1801/K9	Cisco 2821	Cisco 3845	Cisco 7301
	CISCO1801-M/K9	Cisco 2851	Cisco 3845-NOVPN	
	CISCO1801WM-AGE/K9			
	CISCO1801W-AG-E/K9			
	CISCO1801W-AG-B/K9			
	CISCO1801W-AG-C/K9			
	CISCO1801W-AG-N/K9			
CISCO851-K9	CISCO1802			
CISCO851W-G-A-K9	CISCO1802/K9			
CISCO851W-G-E-K9	CISCO1802W-AG-E/K9			
CISCO851W-G-J-K9				
CISCO857-K9	CISCO1803/K9			
CISCO857W-G-A-K9	CISCO1803W-AG-B/K9			
CISCO857W-G-E-K9	CISCO1803W-AG-E/K9			

Table 2 **Supported Integrated Services Routers (ISR) (continued)**

Cisco 800 Series	Cisco 1800 Series	Cisco 2800 Series	Cisco 3800 Series	Cisco 7000 Series
CISCO871-K9	CISCO1805-D			
CISCO871-SEC-K9	CISCO 1805-D/K9			
CISCO871W-G-A-K9	CISCO1811/K9			
CISCO871W-G-E-K9	CISCO1811W-AG-B/K9			
CISCO871W-G-J-K9	CISCO1811W-AG-C/K9			
	CISCO1811W-AG-N/K9			
CISCO876-K9	CISCO1812/K9			
CISCO876-SEC-K9	CISCO1812 W-AG-E/K9			
CISCO876-SEC-I-K9	CISCO1812 W-AG-C/K9			
CISCO876W-G-E-K9				
CISCO877-K9	CISCO1841			
CISCO877-M-K9				
CISCO877-SEC-K9				
CISCO877W-G-A-K9				
CISCO877W-G-E-K9				
CISCO877W-G-E-M-K9				
CISCO878-K9	C1861-UC-4FXO-K9			
CISCO878-SEC-K9	C1861-UC-2BRI-K9			
CISCO878W-G-A-K9	C1861-SRST-B/K9			
CISCO878W-G-E-K9	C1861-SRST-C-B/K9			
	C1861-SRST-C-F/K9			
	C1861-SRST-F/K9			

Table 3 **Supported Integrated Services Routers - G2 (ISR- G2)**

Cisco 800 Series	Cisco 1900 Series	Cisco 2900 Series	Cisco 3900 Series
CISCO861-K9	CISCO1941/K9	CISCO2901/K9	CISCO3925/K9
CISCO861W-GN-A-K9	CISCO1941W-A/K9	CISCO2911/K9	CISCO3945/K9
CISCO861W-GN-E-K9	CISCO1941W-E/K9	CISCO2921/K9	
CISCO861W-GN-P-K9	CISCO1941W-P/K9	CISCO2951/K9	
CISCO867-W-GN-A-K9	CISCO1941W-N/K9		
CISCO867-W-GN-E-K9			
CISCO881-K9			
CISCO881W-GN-A-K9			
CISCO881W-GN-E-K9			
CISCO881W-GN-P-K9			
CISCO881G-K9			
CISCO881GW-GN-A-K9			
CISCO881GW-GN-E-K9			
CISCO881G-S-K9			
CISCO881G-V-K9			
CISCO881G-A-K9			
CISCO881SRST-K9			
CISCO881SRSTW-GN-A-K9			
CISCO881SRSTW-GN-E-K9			
CISCO886-K9			
CISCO886W-GN-E-K9			
CISCO886G-K9			
CISCO886GW-GN-E-K9			
CISCO887-K9			
CISCO887W-GN-A-K9			
CISCO887W-GN-E-K9			
CISCO887M-K9			
CISCO887MW-GN-E-K9			
CISCO887G-K9			
CISCO887GW-GN-A-K9			
CISCO887GW-GN-E-K9			

Table 3 ***Supported Integrated Services Routers - G2 (ISR- G2)***

Cisco 800 Series	Cisco 1900 Series	Cisco 2900 Series	Cisco 3900 Series
CISCO888-K9			
CISCO888W-GN-A-K9			
CISCO888W-GN-E-K9			
CISCO888G-K9			
CISCO888GW-G-AN-K9			
CISCO888GW-G-EN-K9			
CISCO888SRST-K9			
CISCO888SRSTW-GN-A-K9			
CISCO888SRSTW-GN-E-K9			
CISCO891-K9			
CISCO891W-AGN-A-K9			
CISCO891W-AGN-N-K9			
CISCO892-K9			
CISCO892W-AGN-E-K9			

Supported Phones

Table 4 lists the phones that Cisco CP supports:

Table 4 **Supported Phones**

Supported Phones	Supported Expansion Modules	Supported Conference Stations
7902G	7914	7935
7905	7915-12	7936
7906G	7915-24	7937G
7910G	7916-12	
7911G	7916-24	
7912G		
7920		
7921G		
7931G		
7940G		
7941G		
7941G-GE		
7942G		
7945G		
7960G – expansion module compatible (7914)		
7961G – expansion module compatible (7914)		
7961G-GE		
7962G – expansion module compatible (7915,7916)		
7965G – expansion module compatible (7915,7916)		
7970G – expansion module compatible (7914)		
7971G – expansion module compatible (7914)		
7975G – expansion module compatible (7915,7916)		
7985G		
ATA		
CIPC – Cisco IP Communicator		

Supported Network Modules

Table 5 and Table 6 list the network modules that Cisco CP supports.

Table 5 **Supported Network Modules**

Network Modules	Enhanced Network Modules	Wide Area Application Services (WAAS) Modules	Advanced Integration Modules (AIMs)	Voice Network Modules
NM-4T	NME-IPS-K9	NME-WAE-502-K9	AIM-VPN/BP II PLUS	NM-HD-1V
NM-1FE2W-V2	NME-16ES-1G-P	NME-WAE-522-K9	AIM-VPN/EP II PLUS	NM-HD-2V
NM-1FE-FX-V2	NME-X-23ES-1G-P	NME-WAE-302-K9	AIM-VPN/HP II PLUS	NM-HD-2VE
NM-2FE2W-V2	NME-XD-24ES-1S-P		AIM-VPN/SSL-1	NM-HDA-4FXS
NM-1FE-FX	NME-XD-48ES-2S-P		AIM-VPN/SSL-2	NM-HDV2
NM-4A/S	NME-VMSS-16		AIM-VPN/SSL-3	NM-HDV2-1T1/E1
(synchronous only)	NME-VMSS-HP-16		AIM-IPS-K9	NM-HDV2-2T1/E1
NM-8A/S	NME-VMSS-HP-32		AIM-CUE	EVM-HD-8FXS/DID
(synchronous only)			AIM2-CUE-K9	EM-HDA-8FXS
NM-CIDS-K9				EM-HDA-4FXO
NM-16ESW				EM2-HDA-4FXO
NM-16ESW-1GIG				EM-HDA-3FXS/4FXO
NM-16ESW-PWR				EM-HDA-6FXO
NM-16ESW-PWR-1 GIG				EM-4BRI-NT/TE
NMD-36ESW-PWR				NM-CUE
NMD-36ESW-PWR-2GIG				NM-CUE-EC
				NME-CUE
				EM3-HDA-8FXS/DID

Table 6 **Supported Cisco SRE Internal Service Modules and EtherSwitch Modules**

Cisco SRE Internal Service Modules	EtherSwitch Modules
ISM-SRE-300-K9	SM-ES2-16-P
	SM-ES2-24
	SM-ES2-24-P
	SM-D-ES2-48
	SM-ES3-16-P
	SM-ES3G-16-P
	SM-ES3-24-P
	SM-ES3G-24-P
	SM-D-ES3-48-P
	SM-D-ES3G-48-P

Supported Interface Cards

[Table 7](#), lists the interface cards that Cisco CP supports.

Table 7 **Supported Cards**

WAN Interface Cards (WICs)	High-speed WAN Interface Cards (HWICs)	Voice Interface Cards
WIC-1T	HWIC-1T	VIC2-4FXO
WIC-2T	HWIC-2T	VIC2-2FXS
WIC-2A/S (Frame Relay, PPP, HDLC, no asynchronous)	HWIC-4T	VIC2-2FXO
WIC-1ADSL	HWIC-2A/S	VIC2-2BRI-NT/TE
WIC-1DSU-T1-V2	HWIC-4A/S	VIC-2DID
WIC-1B-S/T-V3	HWIC-4ESW	VIC-4FXS/DID
WIC-1AM	HWIC-4ESW-POE	VIC3-4FXS/DID
WIC-2AM	HWIC-8A	VIC3-2FXS/DID
WIC-4ESW	HWIC-8A/S-232	VWIC2-1MFT-T1/E
WIC-1SHDSL-V2	HWIC-D-9ESW	VWIC2-2MFT-T1/E1
WIC-1SHDSL-V3	HWIC-D-9ESW-POE	
WIC 1ADSL-DG	HWIC-1DSU-T1	
WIC 1ADSL-I-DG	HWIC-16A	
	HWIC-ADSL-B/ST	
	HWIC-ADSLI-B/ST	
	HWIC-1ADSL	
	HWIC-1ADSLI	
	HWIC-1ADSL-M (WIC card with Annex M)	
	HWIC-2SHDSL	
	HWIC-4SHDSL	
	HWIC1-ADSL-M	
	HWIC-1CABLE-D-2	
	HWIC-1CABLE-E/J-2	
	HWIC-1FE	
	HWIC-2FE	
	HWIC-AP-AG-A	
	HWIC-AP-AG-E	
	HWIC-AP-AG-J	
	HWIC-AP-G-A	
	HWIC-AP-G-E	
	HWIC-AP-G-J	
	HWIC-3G-GSM	
	HWIC-3G-CDMA-S	
	HWIC-3G-CDMA-V	

Supported Adapters, Processing Engines, and Service Engines

Table 8 lists the adapters, processing engines, and service engines that Cisco CP supports.

Table 8 *Supported Adapters, Processing Engines, and Service Engines*

Port Adapters on Cisco 7000 Series Routers	Service Adapters on Cisco 7000 Series Routers	Network Processing Engines and Network Service Engines on Cisco 7000 Series Routers
PA-2FE-TX	SA-VAM	NPE-225
PA-2FE-FX	SA-VAM2	NPE-400
PA-8E	SA-VAM2+	NPE-G1
PA-4E	C7200-VSA	NPE-G2
		NSE-1

Cisco IOS Releases

Cisco CP is compatible with the Cisco IOS releases listed in Table 9.

Table 9 *Cisco CP-Supported Routers and Cisco IOS Versions*

Router Model	Earliest Cisco CP-Supported Cisco IOS Versions
Cisco 815	• 12.4(11)T
Cisco 850 series	• 12.4(9)T
Cisco 861	• 12.4(20)T
Cisco 867	• 15.0(1)M
Cisco 870 series	• 12.4(9)T
Cisco 881	• 12.4(20)T
Cisco 886	• 15.0(1)M
Cisco 887	• 15.0(1)M
Cisco 888	• 12.4(20)T
Cisco 890 series	• 15.0(1)M
Cisco 1801 Cisco 1802 Cisco 1803	• 12.4(9)T
Cisco 1805	• 12.4(15)XY
Cisco 1811 Cisco 1812	• 12.4(9)T
Cisco 1841	• 12.4(9)T
Cisco 1861	• 12.4(20)T
Cisco 1941 Cisco 1941W	• 15.0(1)M
Cisco 2800 series	• 12.4(9)T

Table 9 Cisco CP-Supported Routers and Cisco IOS Versions (continued)

Router Model	Earliest Cisco CP-Supported Cisco IOS Versions
Cisco 2900 series	<ul style="list-style-type: none"> 15.0(1)M
Cisco 3800 series	<ul style="list-style-type: none"> 12.4(9)T
Cisco 3900 series	<ul style="list-style-type: none"> 15.0(1)M
Cisco 7000	<ul style="list-style-type: none"> 12.4(9)T

Determining the Cisco IOS Release

To determine the release of Cisco IOS software currently running on your Cisco router, log in to the router and enter the **show version EXEC** command. The following sample output from the **show version** command indicates the Cisco IOS release on the second output line:

```
Router> show version
Cisco Internetwork Operating System Software
IOS (tm) C1700 Software (c1700-k8sv3y7-mz) Version 12.2(13)ZH
```

Required IP Address Configuration Information

[Table 10](#) provides the required IP address configuration for the PC. Use this information to complete the section “Task 4: Configure the IP Address On the PC” in the *Cisco Configuration Professional Quick Start Guide*.

Table 10 Required PC IP Address Configurations

Router Model	DHCP Server	Required PC IP Address Configuration
Cisco 815, Cisco 85x, Cisco 86x, Cisco 87x, Cisco 88x, Cisco 89x, Cisco 180x, Cisco 1805, Cisco 1811 and 1812	Yes	Obtain an IP address automatically.
Cisco 1841, Cisco 1861, Cisco 28xx, Cisco 38xx	No	Static IP address from 10.10.10.2 to 10.10.10.6 Subnet Mask: 255.255.255.248

Router Configuration Requirements

In order to run Cisco CP, a router configuration must meet the requirements shown in [Table 11](#).

Table 11 Router Configuration Requirements

Feature	Requirement	Configuration Example
Secure access	SSH and HTTPS	Router(config)# ip http secure-server Router(config)# line vty 0 4 Router(config-line)# transport input ssh
Nonsecure access	Telnet and HTTP	Router(config)# ip http server Router(config)# line vty 0 4 Router(config-line)# transport input telnet
User privilege level	15	Router(config)# username cisco privilege 15 secret 0 cisco

The default configuration file meets all Cisco CP requirements. The default configuration file has the name `cpconfig-model_number.cfg`. For example, the configuration file for the Cisco 860 and Cisco 880 routers is `cpconfig-8xx.cfg`.

Cisco CP Ordering Options

[Table 12 on page 13](#) describes the ordering options under which Cisco CP can be ordered. Cisco Configuration Professional Express (Cisco CP Express) is a product that is shipped in router flash memory when the router is ordered with Cisco CP.

Table 12 Cisco CP Ordering Options



Ordering Options	Description
CCP-CD	Cisco CP: Shipped on CD Cisco CP Express: Shipped in router flash memory SSL Client: Shipped in router flash memory Default Configuration File: Shipped in router flash memory and in NVRAM
CCP-CD-NOCF	Cisco CP: Shipped on CD Cisco CP Express: Shipped in router flash memory SSL Client: Shipped in router flash memory Default Configuration File: Shipped in router flash memory  Note This ordering option does not provide the default configuration file for Cisco 800 series routers.
CCP-EXPRESS	Cisco CP: Not shipped Cisco CP Express: Shipped in router flash memory SSL Client: Shipped in router flash memory Default Configuration File: Shipped in router flash memory and in NVRAM

Table 12 *Cisco CP Ordering Options*

Ordering Options	Description
CCP-EXPRESS-NOCF	<p>Cisco CP: Not shipped</p> <p>Cisco CP Express: Shipped in router flash memory</p> <p>SSL Client: Shipped in router flash memory</p> <p>Default Configuration File: Shipped in router flash memory</p> <p> Note This ordering option does not provide the default configuration file for Cisco 800 series routers.</p>
ISR-CCP-CD=	<p>Cisco CP: Shipped on CD</p> <p>Spare SKU: Mapped to ISR-CCP-CD</p>
ISR-CCP-CD	<p>Cisco CP: Shipped on CD</p> <p>Cisco CP Express: Shipped in router flash memory</p> <p>SSL Client: Shipped in router flash memory</p> <p>Default Configuration File: Shipped in router flash memory and in NVRAM</p>
ISR-CCP-CD-NOCONF	<p>Cisco CP: Shipped on CD</p> <p>Cisco CP Express: Shipped in router flash memory</p> <p>SSL Client: Shipped in router flash memory</p> <p>Default Configuration File: Shipped in router flash memory</p>
ISR-CCP-EXP	<p>Cisco CP: Not shipped</p> <p>Cisco CP Express: Shipped in router flash memory</p> <p>SSL Client: Shipped in router flash memory</p> <p>Default Configuration File: Shipped in router flash memory and in NVRAM</p>
ISR-CCP-EXP-NOCONF	<p>Cisco CP: Not shipped</p> <p>Cisco CP Express: Shipped in router flash memory</p> <p>SSL Client: Shipped in router flash memory</p> <p>Default Configuration File: Shipped in router flash memory</p>

New and Changed Information

This section contains new information about Cisco CP, and any information about Cisco CP that has changed.

This section contains the following parts:

- [New Features](#)
- [New Hardware Support](#)

New Features

Cisco CP 2.0 supports the following new features:

- **Import and Export Community**—The Import and Export Communities feature allows you to save (export) the information about all the communities in Cisco CP to a file on your PC, and then import that information from your PC into Cisco CP.
- **License Management**—The Cisco License Management feature allows you to register and manage feature licenses by securely communicating with the Cisco Product License Registration portal (Cisco licensing portal) to obtain the license, and then allows you to install and deploy the license on a selected device.
- **User Profile**—Earlier you were allowed to access only certain domains or screens. For example, the security administrator was allowed access only to the security screens and the network administrator had access only to the routing screens. With the User Profile feature, you can choose a view for each router. The views are Routing, Security, Voice, Default and so on. You can select read or read-write for each feature displayed in the view.
- **Template Support**—Using this feature, you can generate a template from the running configuration of a device, modify parameters as needed, and apply to the same or another device.
- **Cellular WAN**—This feature supports Third Generation (3G) Wireless High-Speed WAN interface Card (HWIC). The HWIC will function as any other WAN interface on Cisco 1841, 28xx, and 38xx routing platforms. For 881G, 886G, 887G, and 888G, this feature is available in a PCMCIA form. Cisco CP 2.0 provides the following features to support 3G HWIC:
 - Creating a cellular interface for CDMA (Sprint), CDMA (Verizon) and GSM HWICs
 - Editing the existing cellular interface
 - Deleting the cellular interface configurations
 - Monitoring the cellular interfaces
- **Module Configuration**—The new Internal Service Modules (ISM) allows installation and uninstallation of Cisco Unity Express and AXP applications. Cisco CP 2.0 displays the modules available and also the currently installed application. Cisco CP 2.0 also provides functionalities to change the application or install a new application on the module.
- **Module Power Management**—This feature allows you to turn power on and off for the new ISM modules.
- **Flash File Management**—ISR-G2 routers have two flashes. In that case, you need to select the flash you want to save in.
- **Dial Plan**—All dial plan related features are enhanced so that apart from basic common use cases, you can also change some of the advanced configuration options for dial plans. These include Incoming Dial Plan, Outgoing Dial Plan, Intersite VoIP, Gateway VoIP, and SRST Rerouting.
- **Trunk Group**—Cisco CP 2.0 allows creation of trunk group by associating multiple trunks to create the group. Cisco CP also provide the functionality to create dial-peer and associate it to trunk group. This reduces the number of CLIs generated for dial-plan feature when dial-plan has to be applied to multiple trunks.

- **Advanced Global Parameters**—The Advanced Global Parameters feature allows you to enable or disable VoIP parameters and to manage Voice Class Codec entries.
 - **Voice Class Codec**—The Voice Class Codec feature enables a Cisco device to connect to other VoIP devices without having prior knowledge about the codec that is used in a call-setup.
 - **VoIP Parameters**—The VoIP Parameters feature allows you to enable or disable connections between specific types of end points; and to enable or disable supplementary services. Supplementary services are used for call transferring, call forwarding, and message waiting indication (MWI) capabilities across a VoIP network.
- **CME as SRST**—Cisco Unified CME 4.0 provides fallback functionality to IP phones that are registered to Call Manager. When connectivity to the Call Manager is lost or when the server goes down, the phones re-home and register with CME which is configured to provide SRST services. This solution provides access to all the features that CME normally provides while the phones are in fallback mode without any additional licensing cost.
- **Extension Templates** - The Extension Templates feature allows you to apply a standard set of features such as Pickup Group Number, Call Forward Busy Number, and Call Forward No Answer Number to extensions.

New Hardware Support

The new devices supported are:

- CISCO1941/K9
- CISCO1941W-A/K9
- CISCO1941W-E/K9
- CISCO1941W-P/K9
- CISCO1941W-N/K9
- CISCO2901/K9
- CISCO2911/K9
- CISCO2921/K9
- CISCO2951/K9
- CISCO3925/K9
- CISCO3945/K9

The new network modules supported are:

- SM-ES2-16-P
- SM-ES2-24
- SM-ES2-24-P
- SM-D-ES2-48
- SM-ES3-16-P
- SM-ES3G-16-P
- SM-ES3-24-P
- SM-ES3G-24-P
- SM-D-ES3-48
- SM-D-ES3G-48-P
- ISM-SRE-300-K9
- AIM2-CUE-K9
- EM3-HDA-8FXS/DID

Limitations and Restrictions

This section describes restrictions and limitations that may apply to Cisco CP. It contains the following parts:

- [Cisco CP Requirements to Run on Microsoft Windows Vista](#)
- [Cisco CP Minimum Screen Resolution](#)
- [Restrictions for Cisco 7204VXR, Cisco 7206VXR, and Cisco 7301 Routers](#)
- [Cisco CP and Internet Explorer 8](#)

Cisco CP Requirements to Run on Microsoft Windows Vista

In order to run Cisco CP under Microsoft Windows Vista, Cisco CP must be installed in Administrator mode. You can do this by following the Microsoft Windows instructions to create an administrative account, and then logging on to the PC using that account name and password before installing Cisco CP. Failure to do this will require you to right-click on the Cisco CP icon or menu item, and choose “Run as administrator” each time you want to run Cisco CP.

Cisco CP Minimum Screen Resolution

Cisco CP requires a screen resolution of at least 1024 x 768.

Restrictions for Cisco 7204VXR, Cisco 7206VXR, and Cisco 7301 Routers

The following restrictions apply to Cisco CP running on Cisco 7204VXR, Cisco 7206VXR, and Cisco 7301 Routers:

- The Cisco CP Express application is not supported. You must use the Cisco IOS CLI to give the router an initial configuration that will enable you to connect to the router using a browser.
- WAN configuration is not supported. Cisco CP supports configuration of Ethernet and Fast Ethernet interfaces.
- The Cisco CP Reset feature is not available.
- No default configuration file is supplied. To run Cisco CP, you must provide a configuration that includes the commands necessary to support operation of Cisco CP.

Cisco CP and Internet Explorer 8

In some systems (Windows XP and Windows Vista), with IE8 installed, Cisco CP may not work as expected. This is due to a reported IE 8 caching issue.

IE8 reinstall or clearing the cache does not help. Any Flash based application like Cisco CP will see this issue.

A workaround today is to create another user account with appropriate privileges and run Cisco CP in that user account.

A fix will be made available in Cisco CP 2.1.

Important Notes

This section contains important information for Cisco CP. It contains the following sections:

- [Cisco IOS Enforces One-Time Use of Default Credentials](#)
- [Cisco CP Merge and Replace Configuration Functions Fail Under Some Conditions](#)
- [Cisco CP Security Dashboard May Display Threats Unrelated to Your Cisco IOS IPS Installation](#)
- [Cisco CP May Lose Connection to Network Access Device](#)
- [Popup Blockers Disable Cisco CP Online Help](#)
- [Disable Proxy Settings](#)
- [Security Alert Dialog May Remain After Cisco CP Launches](#)
- [Screencasts for Cisco CP Features](#)

Cisco IOS Enforces One-Time Use of Default Credentials

To address CSCsm25466, Cisco IOS images included with recent shipments of Cisco 800, Cisco 1800, Cisco 2800, and Cisco 3800 routers, enforce the one-time use of the default user name and password provided in the Cisco CP configuration file. If you bypass Cisco CP or Cisco CP Express and use a console or Telnet connection to log into the router, the login and exec banners warn you that you must change the user name “cisco” and password “cisco” before you log off of the router. If you do not change the credentials as directed, you will not be able to log on to the router the next time that you attempt to do so.

The following Cisco IOS releases enforce the one-time use of the default credentials:

- 12.4(11)T or later
- 12.4(11)SW, 12.4(11)SW1, 12.4(11)XV, 12.4(11)XJ
- 12.4(9)T5, 12.4(9)T6
- 12.3(21), 12.3(22)

Follow the procedure in this section to secure the router by creating a new username and password, to remove the login banner and exec banner warnings, and to save the configuration changes to the router startup configuration.



Note

If you login to the router using a Telnet or a console connection but do not complete the steps in this procedure, be aware of the following:

- If you do not change the default username and password, and then log off the router, you will not be able to log into the router again without entering the **reload** command. No additional warning is given before you log off.
- If you do not change the default username and password, but do enter the **write memory** command before ending the session, future logins will be disabled. In this case, you will need to follow the password recovery procedure at the following link:

http://www.cisco.com/en/US/products/sw/iosswrel/ps1831/products_tech_note09186a00801746e6.shtml

To secure the router, remove the banner warnings and save the changes to the router startup config, complete the following steps:

- Step 1** Connect the light blue console cable, included with your router, from the blue console port on your router to a serial port on your PC. Refer to your router’s hardware installation guide for instructions.
- Step 2** Connect the power supply to your router, plug the power supply into a power outlet, and turn on your router. Refer to your router’s quick start guide for instructions.
- Step 3** Use HyperTerminal or a similar terminal emulation program on your PC, with the terminal emulation settings of 9600 baud, 8 data bits, no parity, 1 stop bit, and no flow control, to connect to your router.
- Step 4** When prompted, enter the username **cisco**, and password **cisco**.
- Step 5** Enter configuration mode by entering the following command:

```
yourname# configure terminal
```

Step 6 Create a new username and password by entering the following command:

```
yourname(config)# username username privilege 15 secret 0 password
```

Replace *username* and *password* with the username and password that you want to use.

Step 7 Remove the default username and password by entering the following command:

```
yourname(config)# no username cisco
```

Step 8 To remove the login banner, enter the following command:

```
yourname(config)# no banner login
```

The login banner warning will no longer appear.

Step 9 To remove the exec banner, enter the following command:

```
yourname(config)# no banner exec
```

The exec banner warning will no longer appear.

Step 10 Leave configuration mode, by entering the following command:

```
yourname(config)# end
```

Step 11 Copy the configuration changes to the startup configuration by entering the following command:

```
yourname# copy running-config startup-config
```

When logging into the router in the future, use the username and password that you created in [Step 6](#).

Cisco CP Merge and Replace Configuration Functions Fail Under Some Conditions

The problem described here is caveat CSCsj21989. If you attempt to merge configuration changes made using the Cisco CP Config Editor feature, or replace the running configuration with a configuration from the Config Editor, the router configuration will not be changed if there is a network device with a Network Address Translation (NAT) IP address, or a cache engine in the connection between the PC and the router. If you need to make changes to the router configuration that you would normally make using the Cisco CP Config Editor, use the Cisco IOS CLI instead.

Cisco CP Security Dashboard May Display Threats Unrelated to Your Cisco IOS IPS Installation

Some (or all) of the top threats you obtain using the Cisco CP Security Dashboard may not pertain to your Cisco IOS IPS installation. After you deploy the signatures applicable to the top threats displayed by the Cisco CP Security Dashboard, the dashboard may still display some (or all) top threats with a red icon because applicable signatures could not be found. Those remaining top threats are unrelated to your Cisco IOS IPS installation and not a danger to your router running Cisco IOS software.

Cisco CP May Lose Connection to Network Access Device

This note concerns the Network Admission Control (NAC) feature.

If the PC used to invoke Cisco CP returns a posture state (Healthy, Infected, Checkup, Quarantine, or Unknown) and if the group policy on the ACS server attached to the posture token assigned to the PC has a redirect URL configured, the connection between Cisco CP and the router acting as the Network Access Device (NAD) may be lost. The same problem can occur if an exception list entry attached to a policy with a redirect URL is configured with the IP address or MAC address of the PC.

If you try to reinvoke Cisco CP from this PC, you will not be able to do so because the browser will be redirected to the location specified in the redirect URL.

There are two workarounds for this problem:

- Ensure that the PC that you use to invoke Cisco CP attains a posture token which has an associated group policy on the ACS server that is not configured with a redirect URL.
- Alternatively, use Cisco CP to create a NAC exception list entry with the IP address or MAC address of the PC you use to invoke Cisco CP. Note that the exception list entry created for the PC should be associated to an exception policy which does not have a redirect URL configured in it.

For more information, see the links in the Cisco CP NAC online help pages.

Popup Blockers Disable Cisco CP Online Help

If you have enabled popup blockers in the browser you use to run Cisco CP, online help will not appear when you click the help button. To prevent this from happening, you must disable the popup blocker when you run Cisco CP. Popup blockers may be enabled in search engine toolbars, or may be standalone applications integrated with the web browser.

Microsoft Windows XP with Service Pack 2 blocks popups by default. In order to turn off popup blocking in Internet Explorer, go to **Tools > Pop-up Blocker > Turn Off Pop-up Blocker**.

If you have not installed and enabled third-party pop up blockers, go to **Tools > Internet Options > Privacy**, and uncheck the **Block popups** checkbox.

Disable Proxy Settings

Cisco CP will not start when run under Internet Explorer with proxy settings enabled. To correct this problem, choose **Internet Options** from the Tools menu, click the **Connections** tab, and then click the **LAN settings** button. In the LAN Settings window, disable the proxy settings.

Security Alert Dialog May Remain After Cisco CP Launches

When Cisco CP is launched using HTTPS, a security alert dialog box that informs you of possible security problems and asks you if you want to proceed with program launch may appear. This can happen if the router does not have the following global configuration command in the running configuration:

```
ip http timeout-policy idle 600 life 86400 requests 10000
```

Screenscasts for Cisco CP Features

Instead of online help, we have provided screenscasts for the following Cisco CP 2.0 features:

- User Profiles
- Templates
- Cellular WAN
- CME as SRST
- Dial Plan (updated to include Trunk Groups)
- Module Configuration
- Module Power Management
- Extension Templates
- License Management (For this feature, we have provided online help as well as a screenscast.)

These screenscasts are located at:

http://www.cisco.com/en/US/docs/net_mgmt/cisco_configuration_professional/scrests/ccpsc.html

You must have internet access to view the screenscasts.

Cisco Configuration Professional Is Already Running Message

If Cisco CP has not been shut down properly, and you try to relaunch it, you may see the following message: “Cisco Configuration Professional is already running. Only one occurrence can run at a time.” To correct this problem and relaunch Cisco CP, do the following:

-
- | | |
|---------------|---|
| Step 1 | Press Ctrl Alt Delete , and click Task Manager . |
| Step 2 | In the Windows Task Manager dialog, click Processes . |
| Step 3 | In the Image Name column, highlight the processes CiscoCP.exe , CiscoCPEngine.exe , IEC2.exe , and SplashScreen.exe . |
| Step 4 | Click End Process . |
| Step 5 | Wait 30 seconds, and then restart Cisco CP. |
-

Technical Support Logs Do Not Appear on Desktop

If the technical support logs folder does not appear on the desktop, there may be installed Java applications preventing this feature from working properly. To check, go to **Start > Control Panel > Add or Remove Programs**, and scan the list for Java applications. Remove the Java applications that you can, and try again.

Discovery Never Completes

Because of Microsoft Windows Java caching issues, Cisco CP is sometimes unable to complete discovery of a device. To fix this issue, complete the following steps:

-
- Step 1** Choose **Application > Exit** to shut down Cisco CP.
 - Step 2** Go to **Start > Control Panel > Java**. The General tab is displayed.
 - Step 3** In the Temporary Internet Files box, click **Delete Files**.
 - Step 4** In the displayed dialog, leave all file types checked, and click **OK**.
 - Step 5** Click **OK** in the Java control panel to close it.
 - Step 6** Restart Cisco CP.
-

Caveats

Caveats describe unexpected behavior in Cisco CP. This section contains the following:

- [Resolved Caveats from Cisco CP 1.4](#)
- [Open Caveats—Cisco CP 2.0](#)

Resolved Caveats from Cisco CP 1.4

[Table 13](#) lists caveats that are resolved in Cisco CP 2.0.

Table 13 *Resolved Caveats in Cisco CP 2.0*

Bug ID	Summary
CSCsy50471	Enable option should not be shown when the VDSL interface is up.
CSCsl65044	Array values displayed when the mouse is placed over list in the user screen.
CSCsq52996	Need to support SIP for self zone in Cisco CP.
CSCsy06399	Error #2032 is seen on the Router Status dialog box.
CSCtb14050	Cisco CP hangs when trying to upload files through SSL VPN.
CSCta95900	CSCta95900 - Outgoing dial plan configures invalid destination pattern.
CSCtb07893	Acknowledge error on importing Outgoing dial plan in the offline mode.
CSCta12755	Configuration failed when trying to deliver CLIs to the router.
CSCta65551	DID trunk configuration is failing in Online mode.
CSCta86408	Device needs to be discovered after moving to the online mode.
CSCta93218	Disabling CLI view in online mode causes CLIs to be sent directly.
CSCta95721	EM-4BRI-NT/TE ports under EVM-HD-8FXS/DID not getting discovered.
CSCtb03710	PRI Settings voice port values are not displayed correctly.

Table 13 *Resolved Caveats in Cisco CP 2.0 (continued)*

Bug ID	Summary
CSCtb05571	Forward PSTN access digit does not work.
CSCtb10599	Switching between devices in the offline mode shows incorrect data.
CSCtb14313	Cisco CP allows class removal with Firewall PT in GETVPN.
CSCtb24637	Post install fails for Pano device.
CSCtb25590	Deleting multiple extensions throws exception.

Open Caveats—Cisco CP 2.0

Table 14 lists caveats that are open in Cisco CP 2.0.

Table 14 *Open Caveats in Cisco CP 2.0*

Bug ID	Summary	Additional Information
CSCsm91019	Security screens overlap over menu bar options and tool bar information.	<p>Symptom: Some of the menu bar options, either Tools or Help, are hidden under security screens.</p> <p>Conditions: You are in Routing or Security features screen while selecting the menu options.</p> <p>Workaround: Move to any other feature other than Routing or Security, the issue will not be seen.</p>
CSCsm95507	Cisco CP icon is changed to Internet Explorer icon after a while in the titlebar.	<p>Symptom: The icon of Cisco CP application window changes to Internet Explorer icon.</p> <p>Conditions: After the successful launch of Cisco CP, minimize the Cisco CP screen and keep it minimized for a while.</p> <p>Workaround: There is no workaround.</p>
CSCsw23556	Security Applet is not responding error during discovery.	<p>Symptom: Discovery of a device failed with the error Security Applet not responding.</p> <p>Conditions: This issue happens intermittently.</p> <p>Workaround: Re-launch the application.</p>
CSCsw31280	CLI Preview dialog box moves to the background.	<p>Symptom: When configuring security features, you click the Add, Edit, or other command buttons in the user interface, the dialog boxes do not open.</p> <p>Conditions: CLI Preview dialog box is not closed and is present in the background.</p> <p>Workaround: Resize or move the main Cisco CP window and complete the CLI preview dialog options that are hidden in the background to continue.</p>

Table 14 **Open Caveats in Cisco CP 2.0 (continued)**

Bug ID	Summary	Additional Information
CSCsw39659	Enhancement in Cisco CP for CUE post initialization.	<p>Symptom: The data fields for CUE post initialization wizard are not retained on Cisco CP if you use the back button. It is time consuming to enter all the values again.</p> <p>Conditions: This issue occurs only when any field value is invalid in the CUE post initialization wizard.</p> <p>Workaround: To avoid this situation, make sure that you enter the correct values so that you do not have to use the back button.</p>
CSCsx05868	Unable to upload CME phone load tar file.	<p>Symptom: In Cisco Configuration Professional, while trying to upload phone load tar file from the Voice > Phone Firmware feature, phone load upload might fail after some upload progress.</p> <p>Conditions: On device if exec-timeout is not set under line vty configurations or if exec-timeout is set with a smaller timeout value, then phone load upload might fail.</p> <p>Workaround: On device, under all line vty configs, set exec-timeout config with proper timeout value. Example: <code>vtty line 0 4 exec-timeout 25 0 exit</code></p> <p>Further Problem Description: exec-timeout is used to set the interval that the EXEC command interpreter waits until user input is detected. If no input is detected during this interval, the EXEC facility returns the terminal to the idle state and disconnects the incoming session. A big size phone load tar file might take some time to get uploaded on the device's flash. So to avoid any error during upload, exec-timeout should be set with a value greater than the time taken by upload of big tar file. If exec-timeout is set as 0 0, then vtty lines may get blocked if session is not exited/closed properly.</p>
CSCsx57080	Cisco CP launching issue with Internet Explorer 8.	<p>Symptom: Unable to launch Cisco CP.</p> <p>Conditions: Using Internet Explorer 8 release candidate 1.</p> <p>Workaround: Downgrade to Internet Explorer 7.</p>
CSCsx72139	Cisco CP discover details should give warning in case of insufficient memory.	<p>Symptom: Voice menu folder is disabled in the Cisco CP GUI.</p> <p>Conditions: The router running IOS version 12.4(24)T or later has insufficient memory to enable telephony-service.</p> <p>Workaround: Upgrade the DRAM in the router.</p>

Table 14 **Open Caveats in Cisco CP 2.0 (continued)**

Bug ID	Summary	Additional Information
CSCsx75097	Unity express module discovery fails with SSH version >=2.0.	<p>Symptom: Cisco Unity Express module discovery fails with an error message stating that the device is configured with unsupported SSH version. The error messages are shown in the discovery details user interface. Due to this error message, none of the CUE features are available.</p> <p>Conditions: The device is configured with SSH version higher than or equal to 2.0.</p> <p>Workaround: Reconfigure the SSH version to lesser than 2.0, or use Telnet to communicate with the device.</p>
CSCsy49785	Service group not working for QoS, SSLVPN, NAC, and access-class.	<p>Symptom: OGACL with service group not working for QoS, SSLVPN, NAC, and access-class.</p> <p>Conditions: When associating an OGACL with service object group to QoS, SSL VPN, NAC, and access-class, the traffic does not match. This is due to an IOS issue.</p> <p>Workaround: There is no specific workaround. Use normal ACLs with these features. Once the IOS bug is fixed, this will be fixed in Cisco CP.</p>
CSCsy87964	CPU utilization at 100% when discovering devices.	<p>Symptom: After discovery of 5 devices in a community, some with secure mode, CPU shoots to 100% utilization and does not drop. CiscoCPEngine.exe CPU usage is in the range 83%-95%.</p> <p>Conditions: This problem occurs if one of the devices in the community, has high security configuration and bandwidth filters for the WAN interface. This problem does not occur in other PC environments.</p> <p>Workaround: There is no workaround.</p>

Table 14 **Open Caveats in Cisco CP 2.0 (continued)**

Bug ID	Summary	Additional Information
CSCsz13428	Configuration error on creating or editing outgoing dial-plan.	<p>Symptom: Dial-plan related configuration fails saying dial-peer tag is already in use. This issue occurs occasionally when voice hunt-group is configured on the router.</p> <p>Conditions: When hunt-group is configured with pilot CLI, and the pilot number is too huge to be the dial-peer tag.</p> <p>Further Problem Description: When hunt-group is configured with pilot CLI, the router creates a dial-peer with the pilot number as the dial-peer tag. This dial-peer is not displayed in show run, and Cisco CP does not read these dial-peers (only show run is used to read in dial-peer configurations). However, these dial-peers can be seen in show dial-peer voice summary.</p> <p>In normal circumstances, the pilot number and the dial-peer tag are large numbers. This is not an issue for Cisco CP as Cisco CP always chooses the smallest tag number available to configure dial-peers and there is never any overlap of tags. However, if the pilot number is too large to be a tag for dial-peer, the router chooses the next available smallest tag number to configure the dial-peer for that hunt group. In such a situation, Cisco CP configuration for dial-plan might cause a problem because the tag that Cisco CP chooses, can overlap with the already configured hunt group related dial-peer, which results in configuration failure.</p>
CSCsz13759	Deleting of extensions fails if configured as Monitor/Shared.	<p>Symptom: Error while deleting multiple extensions together.</p> <p>Conditions: Create 6 extensions. For example, 1000, 2000, 3000, 4000, 5000, 6000.</p> <p>Assign extensions 1000, 2000, 3000 on button 1 of user1; and extensions 4000, 5000, 6000 on button 2 of user1. Assign extension 1000, 2000, 3000, 4000, 5000, 6000 on button1 of user2. Assign extension 1000 on button1 of user3.</p> <p>Try to delete all the extensions together.</p> <p>Workaround: Delete the extensions one by one.</p>
CSCta31020	Whisper intercom does not throw error while editing an invalid entry.	<p>Symptom: No error message while editing invalid Whisper Intercom entry.</p> <p>Conditions: Whisper intercom dashboard should have invalid entry. Invalid entry should be created via the CLI.</p> <p>Workaround: There is no workaround.</p>

Table 14 **Open Caveats in Cisco CP 2.0 (continued)**

Bug ID	Summary	Additional Information
CSCta60741	Unable to add inspect rule to self zone when editing ZBF.	<p>Symptom: Inspect rule does not get configured correctly for the SSL VPN Passthrough.</p> <p>Conditions: Configure ZBF and then configure SSL VPN. The inspect rule does not get configured correctly. This is due to an IOS bug.</p> <p>Workaround: There is no workaround.</p>
CSCta77317	Analog Trunk window not closing on clicking the OK button.	<p>Symptom: Go to Configure > Voice > PSTN Trunks > Analog Trunks. The Edit screen does not close when the OK button is clicked without making any changes.</p> <p>Conditions: Go to Configure > Voice > PSTN Trunks > Analog Trunks screen. Select an entry, and then click Edit. Without making any changes, click OK. The dialog box does not close.</p> <p>Workaround: Click Cancel button.</p>
CSCta77454	Adhoc Conference update with SSH port blocked throws unwarranted error.	<p>Symptom: Although Discovery is successful with SSH port blocked, updates on Adhoc Conference fail as interactive commands use SSH protocol. The error message does not indicate that the SSH port is blocked.</p> <p>Conditions: Modification of Adhoc Conference parameters fail with SSH port blocked and the error message does not indicate the cause.</p> <p>Workaround: Unblock the SSH port for any transport/communication errors on Adhoc Conference.</p> <p>Further Problem Description: The Discovery process on Cisco CP is successful with SSH port blocked but features like Adhoc Conference use DSPs which interact using SSH ports. When the SSH port is blocked, all such interactions fail and hence updates on Adhoc Conference profile are not successful. The error message generated does not communicate the cause.</p>
CSCtb05983	Multiple delete fails in offline mode community dashboard.	<p>Symptom: Devices do not disappear from the community table immediately after deleting them.</p> <p>Conditions: Select multiple devices in the offline mode and press Delete.</p> <p>Workaround: Delete the devices one by one.</p> <p>Or</p> <p>Refresh the community table after all the devices are deleted.</p>

Table 14 **Open Caveats in Cisco CP 2.0 (continued)**

Bug ID	Summary	Additional Information
CSCtb81205	Location to download SDM IPS packages needs to be changed.	<p>Symptom: Latest SDM/CP packages for IPS cannot be auto downloaded using Cisco CP.</p> <p>Conditions: If the user clicks “Download” option from IPS, the latest SDM/CP package will not be downloaded. Only the IOS-CLI package will be downloaded.</p> <p>Workaround: Manually download the package from CCO and use it in Cisco CP for configuration or import options.</p>
CSCtb58966	Reload of router unsuccessful after deploying license.	<p>Symptom: Reload of device unsuccessful after deploying license or when using 'Reload router' button from License Management > Dashboard window.</p> <p>Conditions: This is seen with devices with an AP module that requires an input to the following interactive command.</p> <p>cisco881GW#reload</p> <p>Do you want to reload the internal AP? [yes/no]:</p> <p>Workaround: Manually reload the router for the license deployment to take effect and re-discover the router.</p>
CSCtb43408	Dialer persistent config conflicts with Do Not Configure Now in wizard.	<p>Symptom: No dialer persistent config delivered to the router.</p> <p>Conditions: Both dialer persistent and Do Not Configure Now specified.</p> <p>Workaround: There is no workaround.</p>
CSCtb33162	Only the last chat script is removed when multiple chat is configured.	<p>Symptom: Only the last chat script gets removed upon clicking the delete button for the specified interface.</p> <p>Conditions: Configure multiple chat script under Dialer tab in edit mode.</p> <p>Workaround: There is no workaround.</p>
CSCta71627	Dialer list configuration removed after GSM wizard configuration.	<p>Symptom: Previous configured dialer-list gets removed.</p> <p>Conditions: There are two GSM interfaces, one is pre configured with dialer-list 2. While using the wizard to configure the second interface, dialer-list 2 get removed.</p>

Table 14 Open Caveats in Cisco CP 2.0 (continued)

Bug ID	Summary	Additional Information
CSCsx05868	Unable to upload CME phone load tar file.	<p>Symptom: In Cisco Configuration Professional, while trying to upload phone load tar file from the Voice > Phone Firmware feature, the upload may fail after some upload progress.</p> <p>Conditions: On the device, if <code><CmdBold>exec-timeout</CmdBold></code> is not set under <code><CmdBold>line vty</CmdBold></code> configurations, or if <code><CmdBold>exec-timeout</CmdBold></code> is set with a smaller timeout value, then phone load upload may fail.</p> <p>Workaround: On the device, under all <code><CmdBold>line vty</CmdBold></code> configs, set <code><CmdBold>exec-timeout</CmdBold></code> config with proper timeout value. For example:</p> <pre> vty line 0 4 exec-timeout 25 0 exit </pre> <p>Further Problem Description: <code>exec-timeout</code> is used to set the interval that the EXEC command interpreter waits until user input is detected. If no input is detected during that interval, the EXEC facility returns the terminal to the idle state and disconnects the incoming session.</p> <p>A big size phone load tar file may take some time to get uploaded on the device's flash. So to avoid any error during upload, <code>exec-timeout</code> should be set with a value greater than the time taken to upload a big tar file.</p> <p>If <code>exec-timeout</code> is set as 0 0, then vty lines may get blocked if the session is not exited or closed properly.</p>
CSCtc30671	Issues with network object ACL groups	<p>Symptom: The ACL network object groups do not get listed under the summary screen after creation.</p> <p>The ACL object group created under one device gets listed under a different device.</p> <p>The network object group created under a device cannot be applied under the ACL rule.</p> <p>Conditions: The ACL network object groups do not get listed under the summary screen after creation. The ACL object group created under one device gets listed under a different device.</p> <p>This problem is seen when more than one device is discovered.</p> <p>Workaround: Rediscover the devices under Cisco CP.</p>

Related Documentation

Table 14 describes the related documentation available for Cisco Configuration Professional.

Table 15 *Cisco Configuration Professional Documentation*

Document Title	Available Formats
<i>Readme First for Cisco Configuration Professional</i>	This document is available in the following locations: <ul style="list-style-type: none"> On Cisco.com. On the product CD-ROM in the Documentation folder.
<i>Cisco Configuration Professional Quick Start Guide</i>	This guide is available in the following locations: <ul style="list-style-type: none"> On Cisco.com. On the product CD-ROM in the Documentation folder.
<i>Cisco Configuration Professional Getting Started Guide</i>	This guide is available in the following locations: <ul style="list-style-type: none"> On Cisco.com. On the product CD-ROM in the Documentation folder. During the installation process, just before you have finished installing the product, you are provided the option to read the Getting Started guide.
<i>Cisco Configuration Professional User Guide</i>	This guide is available in the following locations: <ul style="list-style-type: none"> On Cisco.com. Accessible from Online help.
<i>Cisco Configuration Professional Express User Guide</i>	This guide is available in the following locations: <ul style="list-style-type: none"> On Cisco.com. Accessible from Online help.
<i>Release Notes for Cisco Configuration Professional</i>	This document is available in the following location: <ul style="list-style-type: none"> On Cisco.com.
<i>Release Notes for Cisco Configuration Professional Express</i>	This document is available in the following location: <ul style="list-style-type: none"> On Cisco.com.



Note

For information on obtaining documentation and technical assistance, product security, and additional information, see [What's New](#), which also lists new and revised documents each month.

This document is to be used in conjunction with the documents listed in the “[Related Documentation](#)” section.

CCDE, CCENT, CCSI, Cisco Eos, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco Nurse Connect, Cisco Pulse, Cisco StackPower, Cisco StadiumVision, Cisco TelePresence, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flipshare (Design), Flip Ultra, Flip Video, Flip Video (Design), Instant Broadband, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Capital, Cisco Capital (Design), Cisco:Financed (Stylized), Cisco Store, and Flip Gift Card are service marks; and Access Registrar, Aironet, AllTouch, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Continuum, EtherFast, EtherSwitch, Event Center, Explorer, Fast Step, Follow Me Browsing, FormShare, GainMaker, GigaDrive, HomeLink, iLYNX, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, Laser Link, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerKEY, PowerPanels, PowerTV, PowerTV (Design), PowerVu, Prisma, ProConnect, ROSA, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0908R)

Copyright © 2009 Cisco Systems, Inc. All rights reserved.