



# Restrictions and Caveats in Cisco IOS XE 3.11 Releases

This chapter provides information about restrictions and caveats in Cisco IOS XE 3.11 releases.



## Note

We recommend that you view the field notices for the current release to determine whether your software or hardware platforms are affected. You can access field notices at [http://www.cisco.com/en/US/support/tsd\\_products\\_field\\_notice\\_summary.html](http://www.cisco.com/en/US/support/tsd_products_field_notice_summary.html).

## Caveats in Cisco IOS XE 3.11S Releases

Caveats describe unexpected behavior. Severity 1 caveats are the most serious caveats. Severity 2 caveats are less serious. Severity 3 caveats are moderate caveats and only select severity 3 caveats are included in this chapter.

This section describes caveats in Cisco IOS XE 3.11S releases. The following information is provided for each caveat:

- **Symptom**—A description of what is observed when the caveat occurs.
- **Conditions**—The conditions under which the caveat has been known to occur.
- **Workaround**—Solutions, if available, to counteract the caveat.



## Note

If you have an account on Cisco.com, you can also use the Bug Toolkit to find select caveats of any severity. To reach the Bug Toolkit, log in to Cisco.com and go to [http://www.cisco.com/cgi-bin/Support/Bugtool/launch\\_bugtool.pl](http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl). (If the defect that you have requested cannot be displayed, this may be due to one or more of the following reasons: the defect number does not exist, the defect does not have a customer-visible description yet, or the defect has been marked Cisco Confidential.)

The *Dictionary of Internetworking Terms and Acronyms* contains definitions of acronyms that are not defined in this document:

[http://docwiki.cisco.com/wiki/Category:Internetworking\\_Terms\\_and\\_Acronyms\\_\(ITA\)](http://docwiki.cisco.com/wiki/Category:Internetworking_Terms_and_Acronyms_(ITA))

The following sections describe the open and resolved caveats in 3.11S Releases:

- **Open Caveats**—Cisco IOS XE Release 3.11S, page 7-2
- **Resolved Caveats**—Cisco IOS XE Release 3.11S, page 7-2

## Open Caveats—Cisco IOS XE Release 3.11S

This section documents the unexpected behavior that might be seen with the Cisco ASR 903 router in Cisco IOS XE Release 3.11S.

- CSCuh86847

**Symptom:** When MR-APS CEM feature is configured on the router, the traffic stops flowing on deletion and recreation of CEM groups and xconnects.

**Conditions:** This issue occurs after deletion and recreation of CEM groups is performed and after a few iterations of performing an RSP SSO on a HA configured router..

**Workaround:** Perform an OIR of the OC-3 IM to resume the traffic.

- CSCuj60116

**Symptom:** WANPHY:SYNC-E does not gett synced in WAN mode.

**Conditions:** This issue occurs in WAN mode.

**Workaround:** There is no workaround.

- CSCul15030

**Symptom:** Traffic drops for few seconds then resumes for 2-3 minutes.

**Conditions:** This issue may be observed with a specific topology.

**Workaround:** There is no workaround.

- CSCul21349

**Symptom:** Crash is observed after seeing out of Tcam entries on the console.

**Conditions:** This issue occurs after seeing out of Tcam entries on the console.

**Workaround:** There is no workaround.

## Resolved Caveats—Cisco IOS XE Release 3.11S

This section documents the issues that have been resolved in Cisco IOS XE Release 3.11S.

- CSCuf35542

**Symptom:** Precise Frequency Monitor (PFM) fails for about 5 minutes after OIR is performed.

**Conditions:** This issue occurs after an OIR is trigger ed.

**Workaround:** Wait for 5-6 minutes after an OIR.

- CSCug05491

**Symptom:** The router drops traffic on VPLS circuits.

**Conditions:** This issue occurs when REP is configured with VLAN load balancing and VPLS VFI is configured on the VLANs. This issue occurs after stateful switchover (SSO) is performed.

**Workaround:** There is no workaround.

- CSCug39899

**Symptom:** Traffic stops flowing go through QinQ BDI interface after ARP times out and the ARP is removed by shutting the BDI interface.

**Conditions:** This issue occurs when static routing is configured and no routing protocol is configured on the interface.

- Workaround:** Manually resolve ARP by pinging the next hops BDI interface .
- CSCug44762

**Symptom:** POS interface stays down after a **shutdown** followed by a **no shutdown** on POS interface.

**Conditions:** This issue is seen when a **shutdown** followed by a **no shutdown** is performed on POS interface.

**Workaround:** Perform **shutdown** followed by a **no shutdown** on the controller.
  - CSCug50283

**Symptom:** Only 2-path are utilized for load sharing though 3-path is available.

**Conditions:** This issue occurs when ECMP is configured.

**Workaround:** There is no workaround.
  - CSCug61505

**Symptom:** The **platform enable** command is seen for ACR virtual controller when OC-3 IM is present in slot 0.

**Conditions:** This issue occurs after configuring aps group acr command on the OC-3 controller.

**Workaround:** Insert the IM in other bays instead of bay 0.
  - CSCug83434

**Symptom:** Lot of memory leak chunks are seen for FMANRP on the standby RSP.

**Conditions:** This issue occurs after memory leaks are verified on standby RSP.

**Workaround:** Perform a router reload.
  - CSCug84082

**Symptom:** ATM/IMA PVP links configured on either T1/E1 IM or OC-3IM exhibit traffic or ping failure.

**Conditions:** This issue occurs when ATM/IMA link flaps and is followed by SSO. Link flap can be IM OIR, etc.

**Workaround:** Performing an IM OIR may fix the issue, else perform a router reload.
  - CSCug84428

**Symptom:** Traffic drop are seen on the T1/E1 IM serial and MLPPP links.

**Conditions:** This issue occurs when traffic is sent via streams with jumbo packet sizes of 7000 bytes or larger. The interfaces toggle between the up/down state.

**Workaround:** Perform a IM OIR of the T1/E1 IM.
  - CSCug89348

**Symptom:** IOSXE\_RP\_SPA-3-IPCPORTFAIL tracebacks are seen on router with high availability configured.

**Conditions:** This issue occurs after SSO is performed.

**Workaround:** There is no workaround.
  - CSCug92536

**Symptom:** PLATFORM-3-NOMAC traceback is seen on standby console.

**Conditions:** This issue is seen when cem-acr is configured on a HA setup.

**Workaround:** There is no workaround.

- CSCug96958  
**Symptom:** IMA interfaces stay up when controller is shutdown.  
**Conditions:** This issue occurs after performing an admin shutdown on OC-3 controller.  
**Workaround:** Perform **no shutdown** on the controller.
- CSCug97639  
**Symptom:** IPv4 VRF ping fails when disabling IPv6 unicast-routing globally on the router.  
**Conditions:** This issue occurs when IPv6 unicast-routing is disabled.  
**Workaround:** Enable IPv6 unicast-routing
- CSCuh06123  
**Symptom:** Incorrect quality level (QL) mapping between the clock class and quality level on the PTP master.  
**Conditions:** This issue is seen when QL value is configured before configuring the PTP master.  
**Workaround:** Reconfigure the QL values or reload the router.
- CSCuh18073  
**Symptom:** In a domain with 2 BGP exit points acting in Active or Repair mode, the traffic exits the domain through Repair Path BGP PE instead of exiting through Active Path BGP PE.  
**Conditions:** This issue exists when the environment has 2 BGP exit points.  
**Workaround:** There is no workaround.
- CSCuh22045  
**Symptom:** Small MTU size is not fragmented on the OC-3 IM.  
**Conditions:** This issue occurs after a reload and SSO is performed.  
**Workaround:** Unconfigure and configure the IM.
- CSCuh46103  
**Symptom:** The BDI statistics do not get incremented on the router.  
**Conditions:** This issue occurs when the ingress and egress statistics are displayed using the show interface bdi or show interface bdi stats command.  
**Workaround:** Use **show platform hardware pp active interface statistics bdi** command.
- CSCuh81658  
**Symptom:** PTP packets are being treated as default packets even though QOS policy is configured  
**Conditions:** This issue occurs after CPU generated PTP packets do not reach egress QoS with high priority label (15 or 126) and hence does not hit the corresponding default port entries or even the EFP policy's control entries matching these labels.  
**Workaround:** There is no workaround.
- CSCuh93765  
**Symptom:** The interface goes down reporting loss of frame alarm.  
**Conditions:** This issue occurs on performing **shutdown** followed by a **no shutdown** on the PE and CE.  
**Workaround:** Perform an OIR on CE side.
- CSCui22637

**Symptom:** Crash observed on the router after unconfiguring 1000 psuedowires.

**Conditions:** This issue occurs after unconfiguring 1000 psuedowires at a stretch.

**Workaround:** There is no workaround.

- CSCui30240

**Symptom:** 'SPA is not initialized' messages are seen on bootup.

**Conditions:** This message is seen post bootup as well during **shutdown** command followed by a **no shutdown** command is issued on the controller. This issue occurs on remote PE reload.

**Workaround:** Disable console logging.

- CSCui34041

**Symptom:** Traffic is not flowing for one of the prefix.

**Conditions:** This issue occurs when the MAX MPLS label of that template is assigned to that prefix.

**Workaround:** Disable and enable that prefix.

- CSCui34989

**Symptom:** OC-3 IM IOMD crash is seen post SSO.

**Conditions:** This issue occurs after SSO is performed.

**Workaround:** There is no workaround.

- CSCui47776

**Symptom:** Virtual circuit receive counters do not increment after SSO is performed.

**Conditions:** This issue occurs when 1000 VCs are configured and SSO is performed.

**Workaround:** There is no workaround.

- CSCui52938

**Symptom:** Layer 3 interface adjacency is incomplete.

**Conditions:** This issue occurs after the RSP is removed from the router.

**Workaround:** There is no workaround.

- CSCui55567

**Symptom:** Traffic convergence for OC-3 IM with TDM features such as serial, MLPPP or POS is high after RSP SSO.

**Conditions:** This issue occurs after SSO is performed.

**Workaround:** There is no workaround.

- CSCui75901

**Symptom:** Sync packets are not sent at a regular interval by the router and inter-packet gap is not within the standard range.

**Conditions:** This issue occurs under normal conditions.

**Workaround:** There is no workaround.

- CSCui97872

**Symptom:** The controller remains in disabled state after enabling the license.

**Conditions:** This issue occurs on performing IM OIR or framing.

**Workaround:** Disable the license and enable it.

- CSCuj06140  
**Symptom:** SPAN captured packet has wrong destination MAC address.  
**Conditions:** This issue is seen when MPLS-TP BFD packet is captured.  
**Workaround:** There is no workaround.
- CSCuj07507  
**Symptom:** High convergence for downstream traffic observed on the router.  
**Conditions:** This issue occurs when VPLS VFI's controlled by g.8032 open ring with a large scale of about 500VC's and 10000 MAC address (40 per BD).  
**Workaround:** Use a lower MAC address scale.
- CSCuj46477  
**Symptom:** Layer 2 multicast traffic stops on VPLS VCs and starts flowing back on the ingress EFP.  
**Conditions:** This issue occurs when one of the VPLS VC goes down.  
**Workaround:** Traffic resumes after the VC comes up.
- CSCuj55599  
**Symptom:** ARP request for HSRP VRRP MAC (VMAC) is not punted to CPU.  
**Conditions:** This issue occurs when sending unicast ARP packets on the router.  
**Workaround:** There is no workaround.
- CSCuj76162  
**Symptom:** The input error counter constantly increases in **show platform infrastructure lsmapi** command.  
**Conditions:** This problem occurs when the synchronous mode is configured on the interface of router.  
**Workaround:** There is no workaround.
- CSCul14925  
**Symptom:** The following message displays on the console:  
%PMAN-3-PROCHOLDDOWN: SIP1: pman.sh: The process iomd has been helddown (rc 143)  
**Conditions:** When you perform a hard interface module (IM) online insertion and removal (OIR), IM pull out, or soft IM OIR and IOMD is gracefully terminated from the kernel.  
**Workaround:** There is no workaround. There is no service impact.