

Release Notes for 200 Series 8-Port Switches Software Version 1.0.6.2

February 2013

These Release Notes describe the recommended practices and known issues that apply to the Version 1.0.6.2 software for the following products:

Model	Description
SG200-08	8-Port 10/100/1000 Smart Switch
SG200-08P	8-Port 10/100/1000 PoE Smart Switch

These caveats apply to:

SW version: 1.0.6.2

Sx200 Boot version 1.0.0.12

Contents

[Limitations and Restrictions, page 2](#)

[Major Changes and Defects Corrected, page 4](#)

[Related Information, page 5](#)

Limitations and Restrictions

The following caveats are acknowledged in release 1.0.6.2:

Problem: LLDP-MED (applicable to PoE devices) is not fully operational. Connected devices only show the *Remote ID* and *Remote Port ID*.

Solution: Use CDP, however, LLDP-MED specific data will not be visible.

Problem: The configured time settings will not be preserved upon a reboot, regardless of the method used to set them.

Solution: Manually reset the time upon reboot.

Problem: It may take up to 5 minutes for Bonjour to detect the switch after a reboot.

Solution: There is no workaround.

The following limitations are carried over from Release 1.0.5.1

Problem: With a configuring PC attached to port g1, the MAC address binds to the port. After disconnecting from the switch, the PC can still connect to the switch and manage the DUT on other ports if using the same MAC address.

Solution: There is no workaround.

Problem: When using Internet Explorer version 6 the Filter label is displayed vertically.

Solution: Use Internet Explorer version 8 or a different browser.

Problem: Selected special characters such as: ",',%,!,?,x,÷ are not allowed in any GUI/CLI user-input fields (e.g. password, vlan name, snmp community fields, hostname, etc.). In addition, the whitespace/blank is not supported only in the Password field.

Solution: It is possible to utilize a subset : ",',%,!,? via CLI configurations, however, it is recommended that they should not be used due to possible compatibility issues. If a user had provisioned this subset of characters in previous load via CLI, such as the password, then the user can continue to access via GUI using these special characters.

Problem: When the SG200-08P is acting as a Powered Device (PD) without a connected power adapter, and is being served by an SG200-08P acting as a Power Sourcing Equipment (PSE), the total power given to the PD will be 15.4w. This power is used to run the PD thus yielding approximately half of that as available power to run other equipment such as a single Cisco PVC300 IP Camera at 7.2w. Any addition equipment being powered on by the other PoE port will cause the PD to reboot continuously.

Solution: It is highly recommended that the PD have its own power supply so that it acts as a PSE and not a PD.

Problem: When using Internet Explorer version 6 with the Japanese language, the Filter label is displayed vertically.

Solution: Use Internet Explorer version 8 or a different browser.

802.3af Considerations

The following information supersedes any that is found in the Administration Guide and on-line help:

- **802.3af 4point** - Resistive signature devices detected with the first algorithm that corresponds to the original IEEE 802.3af-2003 PoE standard that provides up to 15.4 W of DC power (minimum 44 V DC and 350 mA) to each device. This mode also supports failover by auto-detecting legacy powered devices. This detection type includes extra detection and resistance measurement of connected device in an attempt to eliminate unwanted noise. **This is the recommended setting.**
- **802.3af 2point** - Resistive signature devices detected with the first algorithm that correspond to the original IEEE 802.3af-2003 PoE standard that provides up to 15.4 W of DC power (minimum 44 V DC and 350 mA) to each device. This mode also supports failover by auto-detecting legacy powered devices. **This selection is not recommended unless the device you are using explicitly recommends this setting.**

Major Changes and Defects Corrected

The following issues were corrected between release 1.0.5.1 and 1.0.6.2:

- Fixed an issue with instability on the 8 and 24 port switches when installing a language pack.
- Fixed a Multicast Listener Discovery (MLD) snooping issue that was causing the switch to fail the forwarding of IPv6 multicast packets.
- Fixed an issue with the selected languages character set causing the inability to add VLAN Tagged to Port.

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Small Business Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco Small Business Smart Switches	www.cisco.com/go/200switches
Regulatory, Compliance, and Safety Information	www.cisco.com/en/US/docs/switches/lan/csb_switching_general/rcsi/Switch_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Copyright © 2013

OL-26026-01C0