



Cisco RF Gateway 1 Software Release 3.02.06 Release Note

Overview

Introduction

Software Release 3.02.06 fixes a bug that prevented scrambling on channels 25 through 48.

Purpose

The purpose of this document is to notify RF Gateway 1 users of the scrambling fixes, miscellaneous improvements, and special upgrade procedures needed for release 3.02.06.

Audience

This document is intended for system engineers and managers responsible for operating and/or maintaining this product.

Related Publications

Refer to the following documents for additional information regarding hardware and software.

- *Cisco RF Gateway 1 Configuration Guide*, part number 4025112
- *Cisco RF Gateway 1 System Guide*, part number 4024958

Safe Operation for Software Controlling Optical Transmission Equipment

If this document discusses software, the software described is used to monitor and/or control ours and other vendors' electrical and optical equipment designed to transmit video, voice, or data signals. Certain safety precautions should be observed when operating equipment of this nature.

For equipment specific safety requirements, refer to the appropriate section of the equipment documentation.

For safe operation of this software, refer to the following warnings.



WARNINGS:

- Ensure that all optical connections are complete or terminated before using this equipment to remotely control a laser device. An optical or laser device can pose a hazard to remotely located personnel when operated without their knowledge.
- Allow only personnel trained in laser safety to operate this software. Otherwise, injuries to personnel may occur.
- Restrict access of this software to authorized personnel only.
- Install this software in equipment that is located in a restricted access area.

In This Document

■ Tier Based Scrambling Fixes.....	3
■ Miscellaneous Improvements	4
■ Known Issues	5
■ Licensing	7
■ Upgrade Information	8
■ IP Port Configuration Changes.....	9
■ Upgrade Procedure for Customers Running 1.02.09.....	10
■ IP Port Configuration Parameter Settings.....	12
■ For Information.....	14

Tier Based Scrambling Fixes

The RF Gateway 1 fails to scramble sessions on the second 24 carriers (channels 25 - 48) when operating without an 8 channel per-port license. This issue is fixed in the 3.02.06 release.

Miscellaneous Improvements

The following miscellaneous improvements have been made in release 3.02.06.

- Added a lock icon to be displayed along with SessionID on the Monitor Output page indicating that the streams are scrambled.
- Fixed a bug that caused the SNMP GET to return an incorrect max QAM bandwidth when operating in either ITU-A or ITU-C mode.

Known Issues

The following list identifies known limitations planned to be resolved as part of an upcoming GA release.

- The RF Gateway 1 web interface is not fully tested with IE-8 and Firefox 3.5 or newer. The RF Gateway 1 web management interface is tested with IE-6 or Firefox 2.0.0.14 and above. Use of Java 1.6.x is recommended.
- The *Summary* page displays the unit rear panel with the conditional access (CA) port enabled/ disabled as green/ gray. This represents the on/off setting and not the actual link status.



- The database restore feature requires disabling trap settings (in the "restore from database file" prior to release 2.01.09) before starting the restore procedure. This can be done before starting a restore configuration in 3.02.06. This step is needed for compatibility with the enhanced SNMPv1 and 2 trap support in this release.
- SNMP community strings are provided to support SNMPv1 and 2 traps. Prior to release 2.01.09, a single community string was applicable for all five trap receivers configurable for the operator. In release 2.02.11 and later, SNMPv1 and 2 traps are supported and each of the five trap receivers has a separate configurable trap community string. This may cause a possible loss of SNMP trap community strings during an upgrade or downgrade procedure. An operator should carefully verify their trap community strings when upgrading to or downgrading from 3.02.06, if they are being used.
- An upgrade to 3.02.06 from pre-release 2.01.09 automatically enables insertion of the Network PID into the PAT. If this is an issue in the user's system, it may be disabled on the *System/System Configuration* page.
- The system uptime counter rolls over to zero after approximately 49 days of continuous use. This behavior manifests on the web management GUI and via SNMP. The rollover does not cause any operational problems or side effects on active services.
Note: A power cycle or reboot of the RF Gateway 1 resets the system uptime counter as part of normal operation.
- The *Monitor Input* page displays the UDP port as the program number for SPTS streams.

Known Issues

- When there is at least one log entry in the system with 101 characters in the log description, downloading the log file by clicking the "View All Logs" hyperlink may cause the unit to crash or freeze. The problem does not occur with 102 characters or more, or with 100 characters or less.
- The "Details" popup window on the *Monitor Input* page does not show correct values for MPTS streams that have the "Ignore UDP Port" parameter set to **TRUE**.
- Clicking the "Display PIDs in hex" check box in the "Replication Details" popup window on the *Monitor Input* page corrupts displayed data. Close and reopen the popup window to display the correct values.

Licensing

After an upgrade to 3.02.06, a system license is required for the following features. Refer to Licensing in the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

- Data streams requiring use of the DOCSIS® Timing Interface
- DVB Encryption

Most systems delivered with 1.02.20 or later using a data part number included a license file pre-installed at the factory. For these systems, an FTP transfer is not necessary.

All systems delivered prior to 1.02.20 and some systems delivered with 1.02.20 require a license file. This can be obtained from Cisco after an upgrade to 3.02.06. Contact your account representative for details on obtaining your license files.

Note: Performing an upgrade without a license file will generate an alarm, informing the user that a license file is not present. The unit continues to function until configuration changes are made. However, performing the upgrade may impact functionality of licensed features.

For systems requiring a license upgrade, a licensing capable RF Gateway 1 provides the operator with a new tree menu item, *License Management* located under the **System** tab. See the following screen. The menu provides an FTP mechanism to transfer license files to the device. It is recommended that the operator monitor the file transfer status using feedback from the FTP server.

The screenshot shows the Cisco RF Gateway 1 web interface. The top navigation bar includes tabs for Summary, Monitor, Alarms, QAMS, Maps, and System. The System tab is selected, and the time 15:41:28 is displayed. On the left, a tree menu shows System Configuration, About, ARP & Routes, Authentication, Backup Configuration, Clock, DTI Config, IP Network, License Management (highlighted), and Logs. The main content area displays the Device Host ID as 000000006316817. Below this is a table titled 'License Overview'.

Type	Installed	Count	Usage	Expiration Date	Remaining Time	Expired	Key
DATA	Yes	1	0	00-000-0000	0	No	
DVB_SCRAMBLING	Yes	1	1	00-000-0000	0	No	

Upgrade Information

An RF Gateway 1 unit running release 1.02.20 can be upgraded directly to 3.02.06. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112, for more information. The RF Gateway 1 reboots automatically at the end of the upgrade process. However, when upgrading to 3.02.06 from 1.02.09, an intermediate step of using the bridge release 1.02.19 to arrive at 1.02.20 and finally 3.02.06 must be followed. The bridge release designated as 1.02.19 has been created to provide a secure and robust upgrade path. Releases 1.02.19 (bridge) and 1.02.20 (final) have identical user features and functionality. See *Upgrade Procedure for Customers Running 1.02.09* (on page 10).



WARNING:

Upgrading to 1.02.20 or above directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to be non-operational.

Refer to Known Issues (on page 5) for SNMP related upgrade, downgrade and database restore considerations.

IP Port Configuration Changes

There is a bug in 1.02.09 that causes the following IP port configuration parameters to have inverted values saved in the configuration file.

- Negotiation Mode (On/Off) - one for each port (total 4)
- Redundancy Mode (Auto/Manual) - one for each port pair (total 2)
- Revert Mode (Enable/Disable) - one for each port pair (total 2)

For details on these parameters, see Chapter 3, *General Configuration and Monitoring* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

This bug has been corrected in the configuration file in 1.02.19. Upon upgrade to 1.02.19, these three parameters will appear to have changed values as seen in the *System/IP Network* page of the web GUI. As a result, the IP ports may not be configured properly for operation immediately after upgrade (after the subsequent reboot that follows activation.)

See *Upgrade Procedure for Customers Running 1.02.09* (on page 10).

Upgrade Procedure for Customers Running 1.02.09



WARNING:

Upgrading to 2.02.22 directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to become non-operational.

- 1 Before starting the upgrade, backup the system configuration. Refer to Chapter 3, *General Configuration and Monitoring (Configuration Backup)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. Name the file appropriately to identify it as a configuration that corresponds to 1.02.09. This file will be necessary later if the user decides to revert back to 1.02.09.
- 2 Record the IP port configuration parameters by saving a screen capture of the *System/IP Network* page. See **Recording IP Port Configuration Settings** (on page 13).
- 3 Download and activate 1.02.19. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. The RF Gateway 1 reboots automatically at the end of the upgrade process.
- 4 After reboot, display the *System/IP Network* page. See **Displaying IP Port Configuration Settings** (on page 12).
- 5 Verify the IP port configuration parameters by checking them against those recorded in step 2 (prior to the upgrade as done in step 3). The Negotiation Mode, Redundancy Mode, and Revert Mode parameter values are inverted. See **Displaying IP Port Configuration Settings** (on page 12). Change the differing parameter values to match those recorded before download and activation. Be sure to click **Apply** after making your changes.
- 6 Once step 5 is completed, save the configuration which includes the IP port configuration parameters. Going forward, these values will not change.
- 7 Validate/qualify/soak release 1.02.19 in its application to establish confidence the release is operating at the same level as 1.02.09. In the very unlikely event that service is impacted by 1.02.19, reverting back to 1.02.09 may be done to re-establish operations. If reverting back to 1.02.09 is necessary, the IP port configuration parameters must be swapped back and the configuration saved in step 2 restored.

- 8 After satisfactory completion of step 7, upgrade from 1.02.19 to 1.02.20. These two releases have identical performance and behavior. Release 1.02.20 includes a boot code upgrade that readily supports future roadmap features/releases without the need for subsequent two-step bridge upgrade processes.
- 9 Download and activate 2.01.09. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112. The RF Gateway 1 reboots automatically at the end of the upgrade process.

IP Port Configuration Parameter Settings

The RF Gateway 1 has four physical GbE input ports that receive video and data streams from the upstream network. These ports may be used independently (in software releases 2.02.22 or later) or configured to implement input redundancy. See Chapter 3, *General Configuration and Monitoring of the Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for specific details.

Displaying IP Port Configuration Settings

Follow these instructions to display the *System/IP Network* page.

- 1 Launch your web browser.
- 2 In the IP Address field, enter the RF Gateway 1 IP address.
- 3 Click **Enter**.
- 4 Click the *System/IP Network* tab and review the IP settings. Refer to the following screen.

The screenshot displays the Cisco RF Gateway 1 configuration interface, specifically the **System/IP Network** tab. The interface includes a navigation menu on the left with options like System Configuration, About, APP & Routes, Backup Configuration, Clock, OTN Config, IP Network (selected), Logs, Release Management, Restore Configuration, and SNMP & Traps. The main content area is divided into several sections:

- 10/100 Ports:** Contains a table for Port Control and Conditional Access settings.

Port Control	Management	Conditional Access
Address Selection Mode	Static	Static
MAC Address	00:50:4b:11:30:94	00:50:4b:11:30:95
IP Address	10.90.149.80	150.158.255.250
Subnet Mask	255.255.255.0	255.255.255.0
Default Gateway	10.90.149.1	150.158.255.254
- Port Pair Configuration:** Shows settings for Port Pair 1 and Port Pair 2.

Port Pair Configuration	Port Pair 1	Port Pair 2
Video/Data IP	10.1.1.140	10.1.1.141
Redundancy Mode	Auto	Manual
Primary Port	1	3
Current Active Port	1	3
Redundancy Configuration	Ethernet Link	Ethernet Link
Detection Mode	Ethernet Link	Ethernet Link
LOS Timeout (s)	1	1
Revert To Primary	Enabled	Enabled
Revert Check Time (s)	1	1
- GbE Input Ports:** Shows settings for four GbE input ports.

Port Configuration	Port 1	Port 2	Port 3	Port 4
MAC Address	00:50:4b:11:30:98	00:50:4b:11:30:97	00:50:4b:11:30:98	00:50:4b:11:30:99
IP Address	10.1.1.140	10.1.1.141	10.1.1.142	10.1.1.143
Subnet Mask	255.255.255.0	255.255.255.0	255.255.255.0	255.255.255.0
Negotiation Mode	On	On	On	On

Recording IP Port Configuration Settings

Follow these instructions to record the IP port configuration settings.

- 1 Navigate to the *System/IP Network* page.
- 2 Click the **Alt-PrtScrn** keys to copy the IP Network parameter settings to the clipboard.
- 3 Launch Microsoft Word (or WordPad if you don't have Microsoft Word) and paste the clipboard contents to page 1.
- 4 Save the Microsoft Word document as ipsettings.doc.

For Information

Support Telephone Numbers

This table lists the Technical Support and Customer Service numbers for your area.

Region	Centers	Telephone and Fax Numbers
North America	Cisco Services Atlanta, Georgia United States	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> ■ Toll-free: 1-800-722-2009 ■ Local: 678-277-1120 (Press 2 at the prompt) For <i>Customer Service</i> , call: <ul style="list-style-type: none"> ■ Toll-free: 1-800-722-2009 ■ Local: 678-277-1120 (Press 3 at the prompt) ■ Fax: 770-236-5477 ■ Email: customer-service@cisco.com
Europe, Middle East, Africa	Belgium	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> ■ Telephone: 32-56-445-197 or 32-56-445-155 ■ Fax: 32-56-445-061 For <i>Customer Service</i> , call: <ul style="list-style-type: none"> ■ Telephone: 32-56-445-444 ■ Fax: 32-56-445-051 ■ Email: service-elc@cisco.com
Japan	Japan	<ul style="list-style-type: none"> ■ Telephone: 81-3-5908-2153 or +81-3-5908-2154 ■ Fax: 81-3-5908-2155
Korea	Korea	<ul style="list-style-type: none"> ■ Telephone: 82-2-3429-8800 ■ Fax: 82-2-3452-9748 ■ Email: songk@cisco.com
China (mainland)	China	<ul style="list-style-type: none"> ■ Telephone: 86-21-2401-4433 ■ Fax: 86-21-2401-4455 ■ Email: xishan@cisco.com
All other Asia Pacific countries & Australia	Hong Kong	<ul style="list-style-type: none"> ■ Telephone: 852-2588-4746 ■ Fax: 852-2588-3139 ■ Email: saapac-support@cisco.com
Brazil	Brazil	<ul style="list-style-type: none"> ■ Telephone: 11-55-08-9999 ■ Fax: 11-55-08-9998 ■ Email: fattinl@cisco.com or ecavalhe@cisco.com
Mexico, Central America, Caribbean	Mexico	For <i>Technical Support</i> , call: <ul style="list-style-type: none"> ■ Telephone: 52-3515152599 ■ Fax: 52-3515152599 For <i>Customer Service</i> , call: <ul style="list-style-type: none"> ■ Telephone: 52-55-50-81-8425 ■ Fax: 52-55-52-61-0893 ■ Email: sa-latam-cs@cisco.com

Region	Centers	Telephone and Fax Numbers
All other Latin America countries	Argentina	<p>For <i>Technical Support</i>, call:</p> <ul style="list-style-type: none">■ Telephone: 54-23-20-403340 ext 109■ Fax: 54-23-20-403340 ext 103 <p>For <i>Customer Service</i>, call:</p> <ul style="list-style-type: none">■ Telephone: 770-236-5662■ Fax: 770-236-5888■ Email: keillov@cisco.com



Cisco Systems, Inc.
5030 Sugarloaf Parkway, Box 465447
Lawrenceville, GA 30042

678 277-1120
800 722-2009
www.cisco.com

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks.

DOCSIS is a registered trademark of Cable Television Laboratories, Inc.

DVB is a registered trademark of the DVB project.

Other third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2011 Cisco and/or its affiliates. All rights reserved.
February 2011

Printed in USA
Part Number 7018765 Rev A