· || · · ·| · · c · s c o ..

Cisco RF Gateway 1 Software Release Notes, Release 5.01.05

Overview

Introduction

The Cisco RF Gateway 1 software version 5.01.05 supports DVB® Scrambling control and PowerKEY® Encryption.

Purpose

The purpose of this document is to notify RF Gateway 1 users of the enhancements included in the current release, and to inform users of any special upgrade procedures needed for using Release 5.01.05.

Audience

This document is intended for system engineers or managers responsible for operating and/or maintaining this product.

Related Publications

Refer to the following documents for additional information regarding hardware and software.

- Cisco RF Gateway 1 Configuration Guide, part number 4025112
- Cisco RF Gateway 1 System Guide, part number 4024958

Safe Operation for Software Controlling Optical Transmission Equipment

If this document discusses software, the software described is used to monitor and/or control ours and other vendors' electrical and optical equipment designed to transmit video, voice, or data signals. Certain safety precautions should be observed when operating equipment of this nature.

For equipment specific safety requirements, refer to the appropriate section of the equipment documentation.

Overview

For safe operation of this software, refer to the following warnings.

WARNINGS:

- Ensure that all optical connections are complete or terminated before using this equipment to remotely control a laser device. An optical or laser device can pose a hazard to remotely located personnel when operated without their knowledge.
- Allow only personnel trained in laser safety to operate this software. Otherwise, injuries to personnel may occur.
- Restrict access of this software to authorized personnel only.
- Install this software in equipment that is located in a restricted access area.

In This Document

Simulcrypt/PowerKEY Support	3
Known Issues	
Licensing	5
Upgrade Information	
Software Release 5.01.05 Miscellaneous Enhancements	
IP Port Configuration Parameter Settings	.8
5	

Simulcrypt/PowerKEY Support

The RF Gateway 1 software version 5.01.05 supports DVB Scrambling control and PowerKEY Encryption. See chapter 3, *General Configuration and Monitoring* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112, for additional information.

The following list describes release 5.01.05 features.

- RF Gateway 1 Release 5.01.05 supports DVB Scrambling control
- PowerKEY Encryption is now supported
- Broadcast session operation (up to 48 QAM carriers)
- PowerKEY and DVB Scrambling licenses required
- DNCS 4.4.1 required for session setup
- EIS must be operating in an AC Reference Mode to configure scrambling

Known Issues

The following list identifies known limitations planned to be resolved as part of an upcoming GA release.

- The RF Gateway 1 Web interface is not fully tested with IE-8 and Firefox 3.5.x or newer. The RF Gateway 1 web management interface is tested with IE-6 or Firefox 2.0.0.14 and above. Use of Java 1.6.x is also recommended.
- When using /31 IP addressing, although the RF Gateway 1 allows setting IP addresses and masks that correspond to this point-to-point protocol, it will not respond to ICMP ping requests.

Licensing

After an upgrade to 5.01.05, users do not have access to 96 QAM channel support (8 channels per port). For information regarding RF Gateway 1 licensing requirements and procedures, see the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112.

The following features require a system license:

- Data streams requiring use of the DOCSIS[®] Timing Interface
- DVB Encryption
- PowerKEY Encryption

If licenses are not pre-installed at the factory, activation of the features listed above requires that a license file be obtained from Cisco after an upgrade to 5.01.05. Contact your account representative for details on obtaining your license files.

Note: Performing an upgrade without a license file will not affect the configuration of a chassis already operating in release 1.03.*X*, 2.02.*X*, or 1.02.*X*. The unit continues to function as configured earlier until any configuration or license changes are made. No alarms or warnings are currently present that indicate the absence of the 8 channel per port license.

For systems requiring a license upgrade, a licensing-capable RF Gateway 1 provides the operator with a new tree menu item, *License Management*, located under the **System** tab. See the following screen. The screen provides an FTP mechanism to transfer license files to the device.

	rfgw1)[L	ogin Reboot	Save	Refresh	Help	cisco	
Summary Monitor	Alarms	QAMS	Ĭ	Ma	aps Sy	stem		16:08	:05		
System Configuration About ARP & Routes Authentication Backup Configuration	Device Host ID 00000006311020]									
Clock		License Overview									
IP Network	Туре	Installed	Count	Usage	Expiration Date	Remaining Time	Expired		Ke	ey .	
License Management	DATA	Yes	1	0	00-000-0000	0	No	7E4164E82	9C42CD5A	FEF8EE0CC9	A1EA4
⊕ Logs Release Management	DVB_SCRAMBLING	Yes	1	1	00-000-0000	0	No	60EC99759	BF5FBF00	F43BAB4C7	B06F2F
-Restore Configuration	8_CHANNELS_PER_PORT	Yes	1	1	00-000-0000	0	No	652553940	0A24111E	FB92CA9F51	18D5E2
Scrambler								-1			
License File Information											
	License File Path	/SW_Rele	ease/Li	cense/				1			
	License File Name	6311020	AllThr	ee_Rav	i_license.dat						
	Download License	Cancel						_			

Upgrade Information

An RF Gateway 1 unit running release 1.02.20 or higher can be upgraded directly to 5.01.05. Refer to Chapter 3, *General Configuration and Monitoring (Release Management)* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112, for more information. The RF Gateway 1 reboots automatically at the end of the upgrade process. However, when upgrading to 5.01.05 from 1.02.09, an intermediate step of using the bridge release 1.02.19 to arrive at 1.02.20 and finally 5.01.05 must be followed. The bridge release designated as 1.02.19 has been created to provide a secure and robust upgrade path. Releases 1.02.19 (bridge) and 1.02.20 (final) have identical user features and functionality.



WARNING:

Upgrading to 1.02.20 or 5.01.05 directly from 1.02.09 must not be attempted. This may cause the RF Gateway 1 to be non-operational.

Software Release 5.01.05 Miscellaneous Enhancements

The following list identifies all 5.01.05 software enhancements. These items refer to incidents recorded in the Issue Management Utility.

Item	Enhancement
114309	Added debug functions to help detect pid errors.
114410	Added debug for V3 createsession failures.
114444	Corrected PAT playout CRC error for initial PAT.
114460	Corrected GUI error in Monitor page resulting from too much data information.
115762	Corrected PK private data increment for SCARD.
115776	Improved debug functions qpiderrors, qpiderrorshex, qpiderrorsall, and qpiderrorsallhex.

IP Port Configuration Parameter Settings

The RF Gateway 1 has four physical GbE input ports that receive video and data streams from the upstream network. These ports may be used independently (in software releases 02.02.11 or later) or configured to implement input redundancy. See Chapter 3, *General Configuration and Monitoring* of the *Cisco RF Gateway 1 Configuration Guide*, part number 4025112 for details.

Displaying IP Port Configuration Settings

ollow these instructions to display the System/IP Network page.

- 1 Launch your web browser.
- 2 In the IP Address field, enter the RF Gateway 1 IP address.
- 3 Click Enter.
- 4 Click the *System/IP Network* tab and review the IP settings. See the following screen.

	rfgw1		Login Reb	oot Save Refresh	Help cisco					
Summary Mon3	tor Alarma C	QUMS Maps	System	(17:	10:49					
ystem Configuration About	10/100 Ports									
-ARP & Routes		Management	Conditional Access							
Authentication	Port Control		011							
Backup Configuration Clock	Address Selection Mode	Static (#)	Static 💌							
IP Network	MAC Address	00:50:40:11:20:a0	00 50 40 11 20 30							
Ucense Management Logs	IP Address	10.90.149.87	150.158.235.250							
Release Nanagement	Subnet Mask	255.255.255.0	255.255.255.0							
Restore Configuration Scrambler	Default Gateway	10.90.149.1	150.158.235.254							
SNMP & Traps	-			'						
		GbE Input Ports								
	GbE Data Port Mode	Dual Port Pairs	141							
	Port Configuration	Port 1 Port 2		Port 3	Port 4					
	MAC Address	00.50.4b 11.2c ae	00.50.4b 11.2c at 00.50.4b 11.2c at 00.50		00.50.46 11 20.61					
	IP Address	76.59.89.129	150.158.232.252	76.59.91.195	150.155.234.250					
	Subnet Mask	255.255.255.248	255.255.255.252	255.255.255.248	255.255.255.252					
	Negotiation Mode	On 💌	On IV	On 💌	On Is					
	Port Pair Configuration	Port	Pair 1	Port Pair 2						
	Video/Data IP	76.59.89.130	1	76.59.91.194						
	Redundancy Mode	(Manua)		Manual						
	Primary Port	1	1	3						
	Current Active Port	1		3						
	Redundancy Configuration									
	Detection Mode	Ethernet Link	(*)	Ethernet Unic						
	LOS Timeout (s)	1		1						
	Revert To Primary	Enabled	×.	Feetled						
	Revert Check Time (s)	2	6	2	1					
			Apply Reset							

Recording IP Port Configuration Settings

Follow these instructions to record the IP port configuration settings.

- **1** Navigate to the *System/IP Network* page.
- 2 Click the **Alt-PrtScrn** keys to copy the IP Network parameter settings to the clipboard.
- **3** Launch Microsoft Word (or WordPad if you don't have Microsoft Word) and paste the clipboard contents to page 1.
- **4** Save the Microsoft Word document as ipsettings.doc.

Cisco Systems, Inc. 5030 Sugarloaf Parkway, Box 465447 Lawrenceville, GA 30042 678.277.1000 www.cisco.com

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at

www.cisco.com/go/trademarks.

DOCSIS is a registered trademark of Cable Television Laboratories, Inc.

DVB is a registered trademark of the DVB project.

Other third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1007R)

Product and service availability are subject to change without notice.

© 2010 Cisco and/or its affiliates. All rights reserved. Printed in September 2010 Part N

Printed in United States of America Part Number 7021722 Rev A