



Release Note – Cisco D9036 Modular Encoding Platform, Software Release Version 01.01.20

Overview

This document describes the features of software release version 01.01.20 for the Cisco® D9036 Modular Encoding Platform. This version supersedes v01.00.17, providing new features and resolution for several issues.

New Features

The following new features are included in software release version v01.01.20.

1. CEA-608 closed captions on line 21 for 60 Hz SD systems. Users can choose between VANC based CEA-608/708 caption input or Line 21. Closed Caption test patterns have also been added.
2. AFD and Bar data. Values can be statically configured for a given video, or AFD inputs can be acquired from the source video using SMPTE-2016 or VII. Default values can be set for the video stream that the encoder will revert to in the event that the incoming AFD signal is not present in the incoming video source. A selection is available for AFD to indicate if 4 bit or legacy 3 bit mode is to be used.
3. VBI-based Aspect Ratio (AR) switching. Aspect ratio can be set statically in the D9036, or it can be sourced from the incoming video on 50 Hz video systems using WSS or VII. Default values can be set for the video stream that the encoder will revert to in the event that the incoming AR setting is not present in the incoming video source.
4. New audio formats – AAC and Dolby® Digital Plus. AAC and Dolby Digital plus have been introduced as licensed features on the D9036. AAC audio supports a number of different modes including MPEG-2 and MPEG-2 AAC with ADTS transport syntax (ISO/IEC 13818-7), and MPEG-4 AAC with LATM transport syntax (ISO/IEC 14496-3), with optional explicit mode. It supports SBR, TNS and PS AAC advanced encoding tools.
5. Additional audio channels on the MMA module. When operating in MPEG-1 LII, AAC or Dolby Digital (AC-3) audio mode, the maximum total number of stereos has been increased from 16 to 32 through this software upgrade. Newly introduced Dolby Digital Plus audio supports a maximum of 10 audio channels.
6. Multi-Channel Audio and MetaData. This version of the D9036 includes the ability to encode multi-channel audio, commonly referred to as 3/2 or 5.1 surround. Multi-channel audio is supported for Dolby Digital, Dolby Digital Plus and AAC audio. Dolby audio formats also include support for up to six external metadata channels, supplied via serial connections on the MMA module.

New Features

7. Audio passthrough. The D9036 now supports passthrough of Dolby E audio streams in SMPTE-302 format.
8. VBI Capabilities. DVB (EN 301 775) is now supported, including support for transmission of WST, WSS, VPS and transparent lines. EBU (ETS 300 472) WST is also supported. Users can apply a timing offset to the normal video-synchronized operation in order to allow early transmission of the associated data.
9. HD Teletext with OP47. OP47 can be used to receive teletext data from an HD VANC signal, and the D9036 can transmit this data in a Teletext PID on the compressed output.
10. Virtual Service Encoder (VSE) Editing. VSEs can now be edited after they are created and enabled. Audio, video and VBI streams can be deleted or added to an existing VSE while in service.
11. IP Address setting. The IP address of the D9036 can now be changed through the web GUI.
12. Clock Setup. The D9036 clock can now be set through the web GUI, making it easier to adjust the encoder's internal clock and time zone settings.
13. VBR Transport Streams (TS). A TS can now be configured for VBR operation.
14. VBR Encoding. Video Elementary Streams can now be configured as VBR in addition to CBR.

Supported Hardware

The following hardware is supported with software release version v01.01.20.

1. MVI-4 – Modular Video Input module. Four-input SD/HD-SDI video input module, including video frame synchronization and audio de-embedding, as well as video input duplication and routing to multiple encoding engines. Only one MVI module per chassis is allowed. (D9036-MVI-4-MKI)
2. MVI-8 – Modular Video Input module. Eight-input SD/HD-SDI video input, double-height module, including video frame synchronization and audio de-embedding, as well as video input duplication and routing to multiple encoding engines. Only one MVI module per chassis is allowed. (D9036-MVI-8-MKI)
3. MVC – Modular Video Codec module. Up to 4 SD encodes, 2 HD encodes or 2 SD/1HD encodes per module. The module can encode both AVC and MPEG-2. The type of encoding is controlled by license and user configuration. Up to two modules per chassis are supported. (D9036-MVC-MKI)
4. MMA – Modular Multi-Audio Codec module. Up to 32 stereo encodes, 16 AES-3id inputs are provided on the module. Embedded audio can also be routed from the MVI module for encoding. Only one MMA module per chassis is allowed. (D9036-MMA-MKI)
5. MIO – Modular Input/Output module. Four Gigabit Ethernet connections (2+2 redundant configuration) with dual ASI and optional port mirroring. Up to 32 multicast or unicast stream outputs are permitted. One MIO per chassis is allowed. (D9036-MIO-MKI)
6. D9036 2AC 1RU Chassis – 6 module bays, dual redundant PSU bays, front to rear cooling with field serviceable fans and filters. (D9036-2AC-1RU)
7. D9036 PSUs – auto-switching 90-264 VAC, 47 to 63 Hz, 400 W rating. (D9036-PWR-400W-AC)

Resolved Issues

The following issues with v01.00.17 were resolved in version v01.01.20.

ID	Description
ID CSCti48832	Number of TS packets in an outgoing IP packet
Issue	Errors can be seen in outgoing transport streams that have less than 7 transport stream packets per IP packet.
ID CSCti48748	VBR transport stream support
Issue	Continuity Count (CC) errors have been observed when IP output transport streams are used in VBR mode.
ID CSCtj59669	Video abnormalities may occur over time
Issue	Video may be lost occasionally for several seconds.
ID CSCti25898	Deleting a VSE results in incomplete cleanup
Issue	Deleting a VSE from the main VSE view leads to incomplete cleanup.
ID CSCtj15644	Video input format – shared input
Issue	Video inputs that are shared across multiple VSEs do not have a common control.
ID CSCti81404	Audio-only services
Issue	Audio-only VSEs cannot be created and mapped to an output transport stream in one service.
ID CSCti50490	Missing alarms
Issue	Power Supply failure and Fan failure alarms are not yet implemented.
ID CSCtj21092	Audio channel auto-naming
Issue	VSE audio channel auto-naming scheme stops incrementing after 10 audios are added.
ID CSCtj21606	Duplicate VSE
Issue	Using the duplicate VSE function results in a VSE that cannot be edited.
ID CSCth97581	Gigabit Ethernet statistics
Issue	Gigabit Ethernet statistics on the MIO are not implemented.
Miscellaneous	Date and time setting
Issue	Date and time cannot be set in the D9036 web GUI.
CSCtk33123	Dolby® Digital pass-through requires a Dolby Digital license
Issue	The D9036 web GUI requires a Dolby License for each Dolby Digital passthrough channel, even though a license should not be required.

Resolved Issues

ID	Description
CSCtk60544	Video sources with unstable frequency or asynchronous frequency have issues when using the SDI input as a clock source
Issue	Video inputs which are used as both a video source and a clock source for an incoming video may have stability issues if the incoming video source has an unstable frequency or has asynchronous switching.
CSCtk07523	Some MIO and System alarms refer to the source as “DCM”
Issue	Some alarms are reported with the text for the source set to DCM rather than D9036.
CSCti85824	560 Hz test tone is actually 390 Hz
Issue	Frequency of 560 Hz test tone is lower than expected.
CSCti09417	GOP Length in encoded video may exceed configured GOP length
Issue	GOP length may not always be as long as specified in the web GUI.
CSCti59102	Issues with Closed Captions loops in 720p mode
Issue	20 loops included with 720p content instead of 10.
CSCtj67933	AFD out of sync by one frame with video
Issue	AFD transition times 1 frame earlier than expected by video content.
CSCtk81974	Audio is disabled during change of input source from GUI
Issue	Changing from one SDI input to another results in audio being disabled.
CSCtk32925	VSE cannot be deleted if VSE name contains “/” character
Issue	VSEs with “/” character in name cannot be deleted.
CSCtk31505	MIO GigE interface link state goes down momentarily when the D9036 is activated
Issue	MIO link is lost momentarily lost on activation when output is to “auto” instead of “enabled”.
CSCti21695	PCR not inserted at RAP
Issue	PCR not inserted at Random Access Point (RAP).
CSCtk16371	HD AVC 50 Hz encoding at 22 Mbps causes issues for some decoders
Issue	Decoders have shown issues processing compressed HD AVC video from the D9036 in both 720p50 and 1080i25 modes when running at 22 Mbps. Bit rates higher and lower than this rate do not exhibit this behavior.
CSCti98817	Numerous simultaneous parameter changes causes timeout
Issue	Timeouts can occur if a large number of changes are made before selecting Apply .

ID	Description
CSCti95355	Backup/restore during previous backup/restore causes issues
Issue	Initiating a backup/restore during a previously initiated backup/restore results in D9036 unit stoppage.
CSCti48409	Freeze-frame generated when video is unplugged
Issue	Freeze-frame was generated instead of a test pattern when video is unplugged.
CSCtk54290	Alarms tied to a VSE are not cleared if VSE deleted
Issue	Alarms that are active that are tied to a specific VSE's operation will remain active after VSE is deleted.
CSCti65330	Unicast does not work reliably from MIO
Issue	Unicast IP streams do not work reliably.
CSCtn14341	Incorrect MAC Address on MIO Ethernet Ports.
Issue	MIO Ethernet ports use an incorrect MAC Address, which can cause issues if connected to the same Ethernet switch as another D9036 using the same MAC address.

For Information

Cisco provides its customers who have purchased support agreements with telephone support from anywhere in the world. If you require technical telephone assistance or product training support, or if you have any questions concerning your Cisco product, you may contact the appropriate Customer Support Center from those listed below. Charges may apply for customers without a current and applicable product support agreement.

Customers	Location	Phone Number
Programmers and Broadcasters	USA and Canada	Toll-free: 1.888.949.4786 +1.770.236.4786 dmn_support@cisco.com
Telcos and Cable Service Providers	Cisco Services	Toll-free: 1.800.722.2009 Local: 678.277.1120 (Press 2 at the prompt) customer-service@cisco.com
All customers	Europe	+32.56.445.155 or +32.56.445.197 saemea-support@cisco.com
All customers	Asia	+852.2588.4746 saapac-support@cisco.com

Customers who call a Customer Support Center are asked specific questions in order to identify their needs. In this way, each call can be directed to the customer support representative most experienced with your Cisco product.



Cisco Systems, Inc.
5030 Sugarloaf Parkway, Box 465447
Lawrenceville, GA 30042

678 277-1120
800 722-2009
www.cisco.com

Cisco and the Cisco logo are trademarks of Cisco and/or its affiliates in the U.S. and certain other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks.

Dolby is a registered trademark of Dolby Laboratories.

Other third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2011 Cisco and/or its affiliates. All rights reserved.
February 2011

Printed in USA
Part Number 7022437 Rev A