

Cisco D9854 Advanced Program Receiver Software Version 3.96 Release Note

Overview

This document describes the improvements and resolved issues in software version 3.96 for the Cisco® D9854 Advanced Program Receiver. This version supersedes version 3.91, providing resolutions for several issues.

New Features

There are no new features in software version 3.96.

Improvements and Maintenance

The following improvements and fixes are included in software version 3.96:

- Fixed DPI messaging and PID descrambling issues related to SCTE-35
- Improved FTP ROSA EM connectivity
- Fixed Macro Blocking
- Response time improvement when CAM is inserted
- Fixed errors in Chinese and Korean subtitles
- LEC System Group performance enhanced

Resolved Issues

The following issues are resolved in version 3.96:

ID	Description
CSCtw87261	DPI: Cue trigger does not receive DPI messages.
Issue	The SCTE-35 DPI based Cue tones and Cue trigger do not function properly.
CSCua55540	Last decoded picture is not at the head of decode queue.
Issue	A continuous video freeze occurs. The following message is reported in the log: "STAPI: Producer: Picture is not the last in decoding FIFO ID".
CSCtu07119	FTP cannot connect to ROSA-EM.
Issue	The FTP client on the IRD cannot connect to some old FTP servers, in this case, the ROSA-EM server.
CSCtx32227	In D9854 version 3.91, not all PIDs are descrambled.
Issue	Some PIDs are not descrambled by the CAM.
CSCtx98161	DPI messages on shared PID authorization is inconsistent.
Issue	The DPI PIDs are shared between multiple User Addresses, but the DPI messages are not always authorized by the Uplink.
CSCtz51095	Previous SNMP Read-only Community Strings still valid and accessible.
Issue	When changing the read/write community string while existing read-only and read/write community strings are the same, the previous SNMP read-only community string may still be valid and accessible.
CSCtz64854	No video outputs when tuned to third party scrambled channel.
Issue	No video on analog outputs when IRD is tuned to a third party scrambled channel.
CSCtz67698	Intermittent short Imitext subtitles are corrupted.
Issue	Brief subtitles are corrupted at the bottom of a displayed subtitle region.
CSCua63302	PRT FVT: Reboots during Codenomicon SNMP tests with length anomalies.
Issue	The unit reboots due to a watchdog event.
CSCtz60826	SNMP parameters reset after dynamic disable/enable.
Issue	The SNMP parameters reset to its default values when the SNMP is dynamically enabled.

2 OL-27941-01

Resolved Issues

ID	Description
CSCua29581	Assert Log Messages are displayed while changing Program Entry CI Slot.
Issue	When changing the CI slot entries for PE 1, assert log messages are displayed.
CSCua63016	The D9854 reboots when bad Low Speed Data is received.
Issue	The D9854 receiver reboots when the Low Speed Data decoding is repeatedly turned on/off.

OL-27941-01 3

For Information

If You Have Questions

If you have technical questions, call Cisco Services for assistance. Follow the menu options to speak with a service engineer.



Cisco Systems, Inc. 5030 Sugarloaf Parkway, Box 465447 Lawrenceville, GA 30042 678 277-1120 800 722-2009 www.cisco.com

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL:

www.cisco.com/go/trademarks.

Manufactured under license from Dolby Laboratories. Dolby is a trademark of Dolby Laboratories.

Other third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Product and service availability are subject to change without notice.

© 2012 Cisco and/or its affiliates. All rights reserved.

September 2012 Part Number OL-27941-01