



# Release Notes for Cisco Wireless LAN Controllers and Lightweight Access Points for Release 4.2.209.0

---

**May, 2010**

These release notes describe open and resolved caveats for software release 4.2.209.0 for Cisco 2000, 2100, and 4400 Series Wireless LAN Controllers; Cisco Wireless Services Modules (WiSM); Cisco Wireless LAN Controller Network Modules; Catalyst 3750G Integrated Wireless LAN Controller Switches; Cisco 3201 Wireless Mobile Interface Cards (WMICs); and Cisco Aironet 1000, 1100, 1130, 1200, 1230AG, 1240, 1250, and 1300 Series Lightweight Access Points, which comprise part of the Cisco Unified Wireless Network (UWN) Solution.



**Note**

---

Unless otherwise noted, all of the Cisco wireless LAN controllers are hereafter referred to as *controllers*, and all of the Cisco lightweight access points are hereafter referred to as *access points*.

---

## Contents

These release notes contain the following sections.

- [Cisco Unified Wireless Network Solution Components, page 2](#)
- [Controller Requirements, page 3](#)
- [Software Release Information, page 3](#)
- [Installation Notes, page 8](#)
- [Important Notes, page 11](#)
- [Caveats, page 25](#)
- [Troubleshooting, page 29](#)
- [Documentation Updates, page 29](#)
- [Related Documentation, page 30](#)
- [Obtaining Documentation, Support, and Security Guidelines, page 30](#)



---

**Americas Headquarters:**

**Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA**

© 2010 Cisco Systems, Inc. All rights reserved.

# Cisco Unified Wireless Network Solution Components

The following components are part of the Cisco UWN Solution and are compatible in this release:

- Software release 4.2.209.0 for all Cisco controllers and lightweight access points
- Cisco autonomous to lightweight mode upgrade tool release 3.0
- Cisco Wireless Control System (WCS) software release 4.2.128.0, 5.2, or 6.0




---

**Note** Only Cisco WCS 4.2.128.0, 5.2, and 6.0 support controllers running software release 4.2.209.0.

---

- Cisco WCS Navigator 1.1.110.0
- Location appliance software release 3.1.43.0
- Cisco 2700 Series Location Appliances
- Cisco 2000 Series Wireless LAN Controllers
- Cisco 2100 Series Wireless LAN Controllers
- Cisco 4400 Series Wireless LAN Controllers
- Cisco Wireless Services Module (WiSM) for Cisco Catalyst 6500 Series Switches and Cisco 7600 Series Routers
- Cisco Wireless LAN Controller Network Module for Cisco Integrated Services Routers
- Catalyst 3750G Wireless LAN Controller Switches
- Cisco 3201 Wireless Mobile Interface Card (WMIC)
- Cisco Aironet 1000, 1100, 1130, 1200, 1230AG, 1240, 1250, and 1300 Series Lightweight Access Points




---

**Note** Only Cisco Aironet 1200 series access points that contain 802.11g (AIR-MP21G) or second-generation 802.11a radios (AIR-RM21A or AIR-RM22A) are supported for use with controller software releases. The AIR-RM20A radio, which was included in early 1200 series access point models, is not supported. To see the type of radio module installed in your access point, enter this command on the access point: **show controller dot11radio *n***, where *n* is the number of the radio (0 or 1).

---




---

**Note** The 1250 series access points have a hardware limitation where beacons can only be output at intervals that are multiples of 17 milliseconds. When these APs are configured for a 100-millisecond beacon interval, they transmit beacons every 102 milliseconds. Similarly, when the beacon interval is configured for 20 milliseconds, these APs transmit beacons every 17 milliseconds.

---

## Special Notice for Mesh Networks


**Note**

Do not upgrade to controller software release 4.2.209.0 if you have mesh access points in your network. If your network uses mesh access points, use only mesh-specific releases. These releases are labeled *MESH* in the Software Center.


**Note**

Cisco WCS software release 4.2.128.0 may be used to manage both mesh and non-mesh controllers (such as controllers running software release 4.2.209.0 and 4.2.207.54M). You do not need different instances of WCS to manage mesh and non-mesh controllers.

## Controller Requirements

The controller GUI requires the following operating system and web browser:

- Windows XP SP1 or higher or Windows 2000 SP4 or higher
- Internet Explorer 6.0 SP1 or higher


**Note**

Internet Explorer 6.0 SP1 or higher is the only browser supported for accessing the controller GUI and for using web authentication.

## Software Release Information

Software is factory installed on your controller and automatically downloaded to the access points after a release upgrade and whenever an access point joins a controller. As new releases become available for the controllers and their access points, consider upgrading.


**Note**

The Cisco WiSM requires software release SWISMK9-32 or later. The Supervisor 720 12.2(18)SXF2 supports the Cisco WiSM software release 3.2.78.4 or later, and the Supervisor 720 12.2(18)SXF5 (Cisco IOS Software Modularity) supports the Cisco WiSM software release 4.0.155.5 (with Cisco IOS Software Modularity).


**Note**

To use the Cisco WiSM in the Cisco 7609 and 7613 Series Routers, the routers must be running Cisco IOS Release 12.2(18)SXF5 or later.


**Note**

The Cisco Wireless LAN Controller Network Module is supported on Cisco 28/37/38xx Series Integrated Services Routers running Cisco IOS Release 12.4(11)T2, 12.4(11)T3, and 12.5.


**Note**

When you use the controller in the Catalyst 3750G Wireless LAN Controller Switch, the 3750 should not run Cisco IOS Releases 12.2(44)SE2 and 12.2(46)SE due to defect CSCsu02630.

## Finding the Software Release

To find the software release running on your controller, click **Monitor** and look at the Software Version field under Controller Summary on the controller GUI or enter **show sysinfo** on the controller CLI.

## Upgrading to a New Software Release

When you upgrade the controller's software, the software on the controller's associated access points is also automatically upgraded. When an access point is loading software, each of its LEDs blinks in succession. Up to 10 access points can be concurrently upgraded from the controller.



### Note

When you downgrade from 4.2.209.0 to 4.2.178.0 or an earlier release, the LWAPP mode may or may not change from Layer 3 to Layer 2, depending on whether the configuration was saved in the earlier image. If the LWAPP mode changes, access points may not join the controller, and you must manually reset the controller to Layer 3 to resolve this issue.



### Caution

Do not power down the controller or any access point during this process; otherwise, you might corrupt the software image. Upgrading a controller with a large number of access points can take as long as 30 minutes, depending on the size of your network. However, with the increased number of concurrent access point upgrades supported in software release 4.0.206.0 and later, the upgrade time should be significantly reduced. The access points must remain powered, and the controller must not be reset during this time.

## Special Rules for Upgrading to Controller Software Release 4.2.209.0



### Caution

Before upgrading your controller to software release 4.2.209.0, you must comply with the following rules.

- Make sure you have a TFTP server available for the software upgrade. Keep these guidelines in mind when setting up a TFTP server:
  - Controller software release 4.2.209.0 is larger than 32 MB; therefore, you must make sure that your TFTP server supports files that are larger than 32 MB. Some TFTP servers that support files of this size are tftpd and the TFTP server within the WCS. If you attempt to download the 4.2.209.0 controller software and your TFTP server does not support files of this size, the following error message appears: "TFTP failure while storing in flash."
  - If you are upgrading through the service port, the TFTP server must be on the same subnet as the service port because the service port is not routable, or you must create static routes on the controller.
  - If you are upgrading through the distribution system network port, the TFTP server can be on the same or a different subnet because the distribution system port is routable.
  - A third-party TFTP server cannot run on the same computer as the WCS because the WCS built-in TFTP server and the third-party TFTP server require the same communication port.

- If your controller is running software release 4.0.206.0 (or a later 4.0 release), 4.1.171.0 (or a later 4.1 release), or 4.2.61.0, 4.2.99.0, 4.2.112.0, or 4.2.130.0, you can upgrade your controller directly to software release 4.2.209.0. If your controller is running a 3.2 release or a 4.0 release prior to 4.0.206.0, you must upgrade your controller to an intermediate release prior to upgrading to 4.2.209.0. [Table 1](#) shows the upgrade path that you must follow before downloading software release 4.2.209.0.

**Table 1** Upgrade Path to Controller Software Release 4.2.209.0

Current Software Release	Upgrade Path to 4.2.209.0 Software
3.2.78.0 or later 3.2 release	Upgrade to 4.0.206.0 (or a later 4.0 release) before upgrading to 4.2.209.0.
4.0.155.5	Upgrade to 4.0.206.0 (or a later 4.0 release) before upgrading to 4.2.209.0.
4.0.179.11	
4.0.206.0 or later 4.0 release	You can upgrade directly to 4.2.209.0.
4.1.171.0 or later 4.1 release	You can upgrade directly to 4.2.209.0.
4.2.61.0 or later 4.2 release	You can upgrade directly to 4.2.209.0.



**Note** When you upgrade the controller to an intermediate software release, wait until all of the access points joined to the controller are upgraded to the intermediate release before you install the 4.2.209.0 software. In large networks, it can take some time to download the software on each access point.

- Cisco requires you to install the Cisco Unified Wireless Network Controller Boot Software 4.2.205.0 ER.aes file on the following controllers: 4400 series, Cisco WiSM, and Catalyst 3750G Wireless LAN Controller Switch. It is optional on other controller platforms. This file resolves CSCso00774 and is necessary to ensure proper operation of the controller. If you do not install the ER.aes file, your controller does not obtain the fix for this defect, and “Error” appears in the Bootloader Version field in the output of the **show sysinfo** command.



**Note** When you install the ER.aes file, a new bootloader file is also loaded. This is true for all controllers except the 2106 controller, for which the bootloader is not upgradable.



**Note** The ER .aes files are independent from the controller software files. You can run any controller software file with any ER.aes file. However, installing the latest boot software file (4.2.205.0 ER.aes) ensures that the boot software modifications in all of the previous and current boot software ER.aes files are installed.

**Caution**

If you require a downgrade from one release to another, you may lose the configuration from your current release. The workaround is to reload the previous controller configuration files saved on the backup server or to reconfigure the controller.

**Note**

Do not install the 4.2.209.0 controller software file and the 4.2.205.0 ER.aes boot software file at the same time. Install one file and reboot the controller; then install the other file and reboot the controller.

Follow these steps to upgrade the controller software using the controller GUI.

**Step 1** Upload your controller configuration files to a server to back them up.



**Note** Cisco highly recommends that you back up your controller's configuration files prior to upgrading the controller software. Otherwise, you must manually reconfigure the controller.

**Step 2** Follow these steps to obtain the 4.2.209.0 controller software and the Cisco Unified Wireless Network Controller Boot Software 4.2.205.0 ER.aes file from the Software Center on Cisco.com:

- a. Click this URL to go to the Software Center:  
<http://www.cisco.com/cisco/software/navigator.html>
- b. Click **Wireless Software**.
- c. Click **Wireless LAN Controllers**.
- d. Click **Standalone Controllers** or **Integrated Controllers and Controller Modules**.
- e. Click a controller series.
- f. If necessary, click a controller model.
- g. If you chose Standalone Controllers in Step d., click **Wireless LAN Controller Software**.
- h. If you chose Cisco Catalyst 6500 Series/7600 Series Wireless Services Module (WiSM) in Step e., click **Wireless Services Modules (WiSM) Software**.
- i. Click a controller software release. The software releases are labeled as follows to help you determine which release to download:
  - **Early Deployment (ED)**—These software releases provide new features and new hardware platform support as well as bug fixes.
  - **Maintenance Deployment (MD)**—These software releases provide bug fixes and ongoing software maintenance.
  - **Deferred (DF)**—These software releases have been deferred. Cisco recommends that you migrate to an upgraded release.
- j. Click a software release number.
- k. Click the filename (*filename.aes*).
- l. Click **Download**.
- m. Read Cisco's End User Software License Agreement and then click **Agree**.
- n. Save the file to your hard drive.
- o. Repeat Steps a. to n. to download the remaining file (either the 4.2.209.0 controller software or the Cisco Unified Wireless Network Controller Boot Software 4.2.205.0 ER.aes file).

**Step 3** Copy the controller software file (*filename.aes*) and the Cisco Unified Wireless Network Controller Boot Software 4.2.205.0 ER.aes file to the default directory on your TFTP server.

**Step 4** Click **Commands > Download File** to open the Download File to Controller page.

**Step 5** From the File Type drop-down box, choose **Code**.

**Step 6** In the IP Address field, enter the IP address of the TFTP server.

- Step 7** The default values of 10 retries and 6 seconds for the Maximum Retries and Timeout fields should work fine without any adjustment. However, you can change these values if desired. To do so, enter the maximum number of times that the TFTP server attempts to download the software in the Maximum Retries field and the amount of time (in seconds) that the TFTP server attempts to download the software in the Timeout field.
- Step 8** In the File Path field, enter the directory path of the software.
- Step 9** In the File Name field, enter the name of the software file (*filename.aes*).
- Step 10** Click **Download** to download the software to the controller. A message appears indicating the status of the download.
- Step 11** Repeat [Step 4](#) to [Step 10](#) to install the remaining file (either the 4.2.209.0 controller software or the Cisco Unified Wireless Network Controller Boot Software 4.2.205.0 ER.aes file).
- Step 12** After the download is complete, click **Reboot**.
- Step 13** If prompted to save your changes, click **Save and Reboot**.
- Step 14** Click **OK** to confirm your decision to reboot the controller.
- Step 15** If desired, reload your latest configuration file to the controller.
- Step 16** To verify that the 4.2.209.0 controller software is installed on your controller, click **Monitor** on the controller GUI and look at the Software Version field under Controller Summary.
- Step 17** To verify that the Cisco Unified Wireless Network Controller Boot Software 4.2.205.0 ER.aes file is installed on your controller, enter the **show sysinfo** command on the controller CLI and look at the Bootloader Version field. “N/A” appears if the ER.aes file is installed successfully. “Error” appears if the ER.aes file is not installed.

**Note**

You can use this command to verify the boot software version on all controllers except the 2106 because the bootloader is not upgradable on the 2106 controller.

## Installation Notes

This section contains important information to keep in mind when installing controllers and access points.

## Warnings

**Warning**

**This warning means danger. You are in a situation that could cause bodily injury. Before you work on any equipment, be aware of the hazards involved with electrical circuitry and be familiar with standard practices for preventing accidents.**

**Warning**

**Only trained and qualified personnel should be allowed to install, replace, or service this equipment.**



**Warning**

**Do not locate any antenna near overhead power lines or other electric light or power circuits, or where it can come into contact with such circuits. When installing antennas, take extreme care not to come in contact with such circuits, as they may cause serious injury or death. For proper installation and grounding of the antenna, refer to national and local codes (e.g. U.S.: NFPA70, National Electrical Code, Article 810, in Canada: Canadian Electrical Code, Section 54).**

**Warning**

**This product relies on the building's installation for short-circuit (overcurrent) protection. Ensure that the protective device is rated not greater than: 120 VAC, 15A U.S. (240vac, 10A International)**

**Warning**

**This equipment must be grounded. Never defeat the ground conductor or operate the equipment in the absence of a suitably installed ground connector. Contact the appropriate electrical inspection authority or an electrician if you are uncertain that suitable grounding is available.**

**Warning**

**Read the installation instructions before you connect the system to its power source.**

**Warning**

**Do not work on the system or connect or disconnect cables during periods of lightning activity.**

**Warning**

**Do not operate your wireless network near unshielded blasting caps or in an explosive environment unless the device has been modified to be especially qualified for such use.**

**Warning**

**In order to comply with radio frequency (RF) exposure limits, the antennas for this product should be positioned no less than 6.56 ft. (2 m) from your body or nearby persons.**

**Warning**

**This unit is intended for installation in restricted areas. A restricted access area can be accessed only through the use of a special tool, lock and key, or other means of security.**

## Safety Information

Follow the guidelines in this section to ensure proper operation and safe use of the controllers and access points.

## FCC Safety Compliance Statement

FCC Compliance with its action in ET Docket 96-8, has adopted a safety standard for human exposure to RF electromagnetic energy emitted by FCC-certified equipment. When used with approved Cisco Aironet antennas, Cisco Aironet products meet the uncontrolled environmental limits found in OET-65 and ANSI C95.1, 1991. Proper operation of this radio device according to the instructions in this publication results in user exposure substantially below the FCC recommended limits.

## Safety Precautions

Each year hundreds of people are killed or injured when attempting to install an antenna. In many of these cases, the victim was aware of the danger of electrocution but did not take adequate steps to avoid the hazard.

For your safety, and to help you achieve a good installation, read and follow these safety precautions.

**They may save your life!**

1. If you are installing an antenna for the first time, for your own safety as well as others, seek professional assistance. Your Cisco sales representative can explain which mounting method to use for the size and type of antenna you are about to install.
2. Select your installation site with safety as well as performance in mind. Electric power lines and phone lines look alike. For your safety, assume that any overhead line can kill you.
3. Call your electric power company. Tell them your plans and ask them to come look at your proposed installation. This is a small inconvenience considering your life is at stake.
4. Plan your installation carefully and completely before you begin. Successfully raising a mast or tower is largely a matter of coordination. Each person should be assigned to a specific task and should know what to do and when to do it. One person should be in charge of the operation to issue instructions and watch for signs of trouble.
5. When installing an antenna, remember:
  - a. **Do not** use a metal ladder.
  - b. **Do not** work on a wet or windy day.
  - c. **Do** dress properly—shoes with rubber soles and heels, rubber gloves, long-sleeved shirt or jacket.
6. If the assembly starts to drop, get away from it and let it fall. Remember that the antenna, mast, cable, and metal guy wires are all excellent conductors of electrical current. Even the slightest touch of any of these parts to a power line completes an electrical path through the antenna and the installer: **you!**
7. If any part of an antenna system should come in contact with a power line, **do not touch it or try to remove it yourself. Call your local power company.** They will remove it safely.
8. If an accident should occur with the power lines, call for qualified emergency help immediately.

## Installation Instructions

Refer to the appropriate quick start guide or hardware installation guide for instructions on installing controllers and access points.



### Note

---

To meet regulatory restrictions, all external antenna configurations must be professionally installed.

---

Personnel installing the controllers and access points must understand wireless techniques and grounding methods. Access points with internal antennas can be installed by an experienced IT professional.

The controller must be installed by a network administrator or qualified IT professional, and the proper country code must be selected. Following installation, access to the controller should be password protected by the installer to maintain compliance with regulatory requirements and ensure proper unit functionality.

## Important Notes

This section describes important information about the controllers and access points.

### ARP Requests Sometimes Fail for Access Points Connected Directly to 2006 and 2100 Series Controllers

Cisco 2006 and 2100 series controllers do not support ARP requests from access points connected directly to a port on the controller unless there is an interface configured on that controller port. ARP requests from the access point cannot reach the gateway on the interface VLAN and the access point might lose its connection to the controller.

To work around this limitation, configure the access point's default gateway to match the controller's management IP address, or connect the access point to a switch port between the access point and the controller.

### One-Time Password (OTP) Support

One Time Passwords (OTP) are supported on the Wireless Lan Controller (WLC) using TACACS and RADIUS. In this configuration, the controller acts as a transparent pass-thru device. The controller forwards all client requests to the TACACS/RADIUS server without inspecting the client behavior. When using OTP the client must only establish a single connection to the controller to function properly. The controller currently does not have any intelligence or checks to correct a client that is trying to establish multiple connections.

### QoS Interaction with RRM

Controller software release 4.2.205.0 or later affects the way that QoS interacts with the RRM scan defer feature:

- When you configure a WLAN with a Bronze (Background Priority) QoS policy level, traffic with Scan Defer Priority 0 (UP=0) should be downgraded to UP=1 (UP 1,2 are the lowest priority; 0,3 are the next higher priority). Traffic to and from clients on this WLAN will compete with clients sending UP=0 traffic in Silver/Gold/Platinum policies.
- The QoS policy for the WLAN configuration overrides the traffic sent. In other words, if you have patient monitors, phones, or other client devices in a WLAN with a Silver QoS policy, the traffic is downgraded to a priority no higher than UP=3. If you attempt to defer off-channel scanning by configuring the WLAN for UP=5, the QoS policy overrides that configuration and off-channel scanning is not deferred.
- Traffic sent with UP=7 on a WLAN with a Platinum policy will be downgraded to UP=6; if you configure off-channel scanning for UP=7 only, scanning will not be deferred. You might not want to defer scanning for UP=7 traffic but you might for UP=6 traffic; in this case, the traffic sent with UP=7 will be downgraded and cause a deferral. Similarly, if you want to defer scanning for UP=7 traffic, you must set the scanning priority to UP=6 because the traffic will be downgraded.

If you completely disable off-channel scanning on your network, you should consider alternative ways to implement off-channel scanning: adding monitor-mode access points or creating AP groups where some access points in the area do not carry the configured WLANs for those devices.

## Crash Files for 1250 Series Access Points

The 1250 series access points may contain a bootloader older than version 12.4(10b)JA. Units with old bootloaders do not generate a crash log when a crash occurs. The crash log is disabled so that a crash does not corrupt the flash file system. Units with bootloader versions 12.4(10b)JA or later generate a crash log if the access point is associated to a controller software release 4.2.112.0 or later.

New 1250 series access points shipped from the factory contain new bootloader images, which fixes the flash file system after it is corrupted during a crash (without losing files). This new bootloader automatically sets a new CRASH\_LOG environment variable to “yes,” which enables a crash log to be generated following a crash but only on controllers running software release 4.2.112.0 or later. Therefore, no user configuration is needed to enable a crash log on new 1250 series access points shipped from the factory.

These examples show the output from the CLI commands (in bold) that you use to check the bootloader version on LWAPP and autonomous 1250 series access points:

LWAPP (commands entered on the controller CLI):

```
(wlc) >debug ap enable AP001b.d513.1754
(wlc) >debug ap command "show version | include BOOTLDR" AP001b.d513.1754
(wlc) >Thu Apr 23 09:31:38 2009: AP001b.d513.1754: BOOTLDR: C1250 Boot Loader
(C1250-BOOT-M) Version 12.4(10b)JA, RELEASE SOFTWARE (fc1)
```

Autonomous (command entered on the access point CLI):

```
ap# show version | include BOOTLDR
BOOTLDR: C1250 Boot Loader (C1250-BOOT-M) Version 12.4(10b)JA, RELEASE SOFTWARE (fc1)
```

## Port Mirroring Not Supported on Some Controller Platforms

The controller port mirroring feature is not supported on 2100 series controllers, 4400 series controllers, Cisco WiSM controllers, and controller network modules.

## Internal DHCP Server

When clients use the controller’s internal DHCP server, IP addresses are not preserved across reboots. As a result, multiple clients can be assigned the same IP address. To resolve any IP address conflicts, clients must release their existing IP address and request a new one.

## RLDP Limitations

Rogue Location Discovery Protocol (RLDP) is a controller feature that detects the presence of rogue access points that are connected to your wired network. RLDP operates with these limitations:

- RLDP detects rogue access points that are configured for open authentication.
- RLDP detects rogue AP which use a broadcast BSSID--that is, the access point broadcasts its SSID in beacons.
- RLDP detects only rogue AP that are on the same the network. In other words, if an access list in the network prevents the sending of RLDP traffic from the rogue AP to the controller, RLDP will not work.
- RLDP does not work on 5-GHz DFS channels.

- RLDLP is a best-effort protocol. For each rogue, the controller initiates RLDLP only once. If the controller does not detect a rogue (due to a noisy RF environment, for example), the controller does not retry. However, you can initiate RLDLP manually on a rogue at any time.

## Configuration File Stored in XML Format

In controller software 4.2, the controller's bootup configuration file is stored in an Extensible Markup Language (XML) format rather than in binary format. Therefore, you cannot download a binary configuration file onto a controller running software release 4.2. However, when you upgrade a controller from a previous software release to 4.2, the configuration file is migrated and converted to XML.

## Web Authentication Redirects

The controller supports web authentication redirects only to HTTP (HTTP over TCP) servers. It does not support web authentication redirects to HTTPS (HTTP over SSL) servers.

## Disabling Radio Bands

The controller disables the radio bands that are not permitted by the configured country of operation (CSCsi48220).

## 40-MHz Channels in the 2.4-GHz Band

Cisco recommends that you do not configure 40-MHz channels in the 2.4-GHz radio band because severe co-channel interference is likely to occur.

## Impact of External Antenna Gain on Transmit Power

In controller software release 4.2 or later, external antenna gain is factored into the maximum transmit power of the access point. Therefore, when you upgrade from an earlier software release to 4.2 or later, you might see a decrease in transmit power output.

## Supporting Oversized Access Point Images

Controller software release 4.2 or later allows you to upgrade to an oversized access point image by deleting the recovery image to create sufficient space. This feature affects only access points with 8 MB of flash (the 1100, 1200, and 1310 series access points). All newer access points have a larger flash size than 8 MB.



### Note

As of August 2007, there are no oversized access point images, but as new features are added, the access point image size will continue to grow.

The recovery image provides a backup image that can be used if an access point power-cycles during an image upgrade. The best way to avoid the need for access point recovery is to prevent an access point from power-cycling during a system upgrade. If a power-cycle occurs during an upgrade to an oversized access point image, you can recover the access point using the TFTP recovery procedure.

Follow these steps to perform the TFTP recovery procedure.

- 
- Step 1** Download the required recovery image from Cisco.com (c1100-rcvk9w8-mx, c1200-rcvk9w8-mx, or c1310-rcvk9w8-mx) and install it in the root directory of your TFTP server.
  - Step 2** Connect the TFTP server to the same subnet as the target access point and power-cycle the access point. The access point boots from the TFTP image and then joins the controller to download the oversized access point image and complete the upgrade procedure.
  - Step 3** After the access point has been recovered, you may remove the TFTP server.
- 

## Cisco 1250 Series Access Points and Cisco 7920 IP Phones

Cisco 1250 series access points are not supported for use with the Cisco 7920 IP phone. They can, however, be used with the Cisco 7921 and 7925 IP phones.

## Multicast Limitations

Multicast is not supported on access points that are connected directly to the local port of a 2000 or 2100 series controller.

## MAC Filtering for WGB Wired Clients

Controller software release 4.1.178.0 or later enables you to configure a MAC-filtering IP address for a workgroup bridge (WGB) wired client to allow passive WGB wired clients, such as terminal servers or printers with static IP addresses, to be added and remain in the controller's client table while the WGB is associated to a controller in the mobility group. This feature, activated by the **config macfilter ipaddress MAC\_address IP\_address** CLI command, can be used with any passive device that does not initiate any traffic but waits for another device to start communication.

This feature allows the controller to learn the IP address of a passive WGB wired client when the WGB sends an IAPP message to the controller that contains only the WGB wired client's MAC address. Upon receiving this message from the WGB, the controller checks the local MAC filter list (or the anchor controller's MAC filter list if the WGB has roamed) for the client's MAC address. If an entry is found and it contains an IP address for the client, the controller adds the client to the controller's client table.



### Note

Unlike the existing MAC filtering feature for wireless clients, you are not required to enable MAC filtering on the WLAN for WGB wired clients.



### Note

WGB wired clients using MAC filtering do not need to obtain an IP address through DHCP to be added to the controller's client table.

## CKIP Not Supported with Dynamic WEP

In controller software release 4.1.185.0 or later, CKIP is supported for use only with static WEP. It is not supported for use with dynamic WEP. Therefore, a wireless client that is configured to use CKIP with dynamic WEP is unable to associate to a wireless LAN that is configured for CKIP. Cisco recommends that you use either dynamic WEP without CKIP (which is less secure) or WPA/WPA2 with TKIP or AES (which are more secure).

## Synchronizing the Controller and Location Appliance

For controller software release 4.2 or later, if a location appliance (release 3.1 or later) is installed on your network, the time zone must be set on the controller to ensure proper synchronization between the two systems. Also, Cisco highly recommends that the time be set for networks that do not have location appliances. Refer to Chapter 4 of the *Cisco Wireless LAN Controller Configuration Guide, Release 4.2* for instructions for setting the time and date on the controller.



**Note**

The time zone can be different for the controller and the location appliance, but the time zone delta must be configured accordingly, based on Greenwich Mean Time (GMT).



**Note**

Daylight Savings Time (DST) is not supported in controller software release 4.2.

## UNII-2 Channels Disabled on New 1000 Series Access Points for United States, Canada, and Philippines

New Cisco 1000 series lightweight access points for the United States, Canada, and the Philippines do not support the UNII-2 band (5.25 to 5.35 GHz). These models are labeled AP10x0-B, where “B” represents a new regulatory domain that replaces the previous “A” domain.

## FCC DFS Support on 1130 Series Access Points

Federal Communications Commission (FCC) dynamic frequency selection (DFS) is supported only on 1130 series access points in the United States, Canada, and the Philippines that have a new FCC ID. Access points use DFS to detect radar signals such as military and weather sources and then switch channels to avoid interfering with them. 1130 series access points with FCC DFS support have an FCC ID *LDK102054E* sticker. 1130 series access points without FCC DFS support have an *LDK102054* (no *E* suffix) sticker. 1130 series access points that are operating in the United States, Canada, or the Philippines; have an FCC ID *E* sticker; and are running the 4.1.171.0 software release or later can use channels 100 through 140 in the UNII-2 band.

## Inaccurate Transmit Power Display

After you change the position of the 802.11a radio antenna for a lightweight 1200 or 1230 series access point, the power setting is not updated in the controller GUI and CLI. Regardless of the user display, the internal data is updated, and the transmit power output is changed accordingly. To see the correct transmit power display values, reboot the access point after changing the antenna's position. (CSCsf02280)

## Setting the Retransmit Timeout Value for TACACS+ Servers

Cisco recommends that the retransmit timeout value for TACACS+ authentication, authorization, and accounting servers be increased if you experience repeated reauthentication attempts or the controller falls back to the backup server when the primary server is active and reachable. The default retransmit timeout value is 2 seconds and can be increased to a maximum of 30 seconds.

## Configuring an Access Point's Prestandard Power Setting

An access point can be powered by a Cisco prestandard 15-watt switch with Power over Ethernet (PoE) by entering this command:

**config ap power pre-standard {enable | disable} {all | Cisco\_AP}**

A Cisco prestandard 15-watt switch does not support intelligent power management (IPM) but does have sufficient power for a standard access point. The following Cisco prestandard 15-watt switches are available:

- AIR-WLC2106-K9
- WS-C3550, WS-C3560, WS-C3750
- C1880
- 2600, 2610, 2611, 2621, 2650, 2651
- 2610XM, 2611XM, 2621XM, 2650XM, 2651XM, 2691
- 2811, 2821, 2851
- 3631-telco, 3620, 3640, 3660
- 3725, 3745
- 3825, 3845

The **enable** version of this command is required for full functionality when the access point is powered by a Cisco prestandard 15-watt switch. It is safe to use if the access point is powered by either an IPM switch or a power injector or if the access point is not using one of the 15-watt switches listed above.

You might need this command if your radio operational status is “Down” when you expect it to be “Up.” Enter the **show msglog** command to look for this error message, which indicates a PoE problem:

```
Apr 13 09:08:24.986 spam_lrad.c:2262 LWAPP-3-MSGTAG041: AP 00:14:f1:af:f3:40 is unable to
verify sufficient in-line power. Radio slot 0 disabled.
```



## 1000 Series Access Points and Radar Detection

The 1000 series access points perform radar detection on channels that do not require it (such as channel 36). If the access points detect radar on these channels, the controller captures it in log messages.

## Controller Functions that Require a Reboot

After you perform these functions on the controller, you must reboot the controller in order for them to take effect:

- Switch between Layer 2 and Layer 3 LWAPP mode
- Enable or disable link aggregation (LAG)
- Enable a feature that is dependent on certificates (such as HTTPS and web authentication)
- Add new or modify existing SNMP v3 users
- Enable or disable the mobility protocol port using this CLI command:

**config mobility secure-mode {enable | disable}**

## Multicast Queue Depth

The multicast queue depth is 512 packets on all controller platforms. However, the following message might appear on 2006 and 2106 controllers: “Rx Multicast Queue is full on Controller.” This message does not appear on 4400 series controllers because the 4400 NPU filters ARP packets, and all forwarding (multicast or otherwise) and multicast replication are done in the software on the 2006 and 2106.

This message appears when too many multicast messages are sent to the CPU. In controller software releases prior to 5.1, multicast, CDP, and ARP packets share the same queue. However, in software releases 5.1 and later, these packets are separated into different queues. There are currently no controller commands that can be entered to determine if the multicast receive queue is full. When the queue is full, some packets are randomly discarded.

## 2106 Controller LEDs

The 2106 controller’s Status LED and AP LED do not flash amber when software is being uploaded to the controller or downloaded to an access point, respectively.



### Note

Some versions of the *Cisco 2106 Wireless LAN Controller Quick Start Guide* might incorrectly state that these LEDs flash amber during a software upload or download.

## Resetting the Configuration on 2006 Controllers

If you wish to reset the configuration to factory defaults on a 2006 controller, perform one of the following:

- From the controller GUI, click **Commands > Reset to Factory Default > Reset**.
- From the controller CLI (after system bootup and login), enter **clear config**. Then after the configuration has been cleared, enter **reset system** without saving the current configuration.

- From the controller console (after system bootup), enter **Recover-Config** from the User Name prompt.

**Caution**

Do not attempt to reset the controller's configuration by choosing Option 5, Clear Config, from the boot menu.

## Rate-Limiting on the Controller

Rate-limiting is applicable to all traffic destined to the CPU from either direction (wireless or wired). Cisco recommends that you always run the controller with the default **config advanced rate enable** command in effect in order to rate-limit traffic to the controller and protect against denial-of-service (DoS) attacks. You can use the **config advanced rate disable** command to stop rate-limiting of Internet Control Message Protocol (ICMP) echo responses for testing purposes. However, Cisco recommends that you reapply the **config advanced rate enable** command after testing is complete.

## Pings Supported to the Management Interface of the Controller

Controller software release 4.1.185.0 or later is designed to support ICMP pings to the management interface either from a wireless client or a wired host. ICMP pings to other interfaces configured on the controller are not supported.

## Pinging from a Network Device to a Controller Dynamic Interface

Pinging from a network device to a controller dynamic interface may not work in some configurations. When pinging does operate successfully, the controller places Internet Control Message Protocol (ICMP) traffic in a low-priority queue, and the reply to ping is on best effort. Pinging does not pose a security threat to the network. The controller rate limits any traffic to the CPU, and flooding the controller is prevented. Clients on the WLAN associated with the interface pass traffic normally.

## GLBP Not Supported

Controller software release 4.2 or later is not compatible with the Gateway Load Balancing Protocol (GLBP). Make sure to configure the controller's default gateway to a fixed address and not to the GLBP virtual address.

## IPSec Not Supported

Software release 4.2 does not allow you to choose IPSec as a Layer 3 security option. None and VPN Passthrough are the only available options. If you upgrade to this release from a previous release that supported IPSec as a Layer 3 security option, any WLANs that are configured for this feature become disabled. If you want to configure IPSec, you must use a version of controller software prior to 4.0.

## 4400 Series Controllers Do Not Forward Subnet Broadcasts through Guest Tunnel

As designed, 4400 series controllers do not forward IP subnet broadcasts from the wired network to wireless clients across the EoIP guest tunnel.

## Connecting 1100 and 1300 Series Access Points

You must install software release 4.0.179.8 or later on the controller before connecting 1100 and 1300 series access points to the controller.

## Preventing Clients from Accessing the Management Network on a Controller

To prevent or block a wired or wireless client from accessing the management network on a controller (from the wireless client dynamic interface or VLAN), the network administrator should ensure that there is no route through which to reach the controller from the dynamic interface or use a firewall between the client dynamic interface and the management network.

## Voice Wireless LAN Configuration

Cisco recommends that aggressive load balancing always be turned off either through the controller GUI or CLI in any wireless network that is supporting voice, regardless of vendor. When aggressive load balancing is turned on, voice clients can hear an audible artifact when roaming, and the handset is refused at its first reassociation attempt.

## Changing the IOS LWAPP Access Point Password

Cisco IOS Lightweight Access Point Protocol (LWAPP) access points have a default password of *Cisco*, and the pre-stage configuration for LWAPP access points is disabled by default. To enable it, you must configure the access point with a new username and password when it joins the controller. Enter this command using the controller CLI to push a new username and password to the access point:

```
config ap username user_id password password {Cisco_AP | all}
```

- The *Cisco\_AP* parameter configures the username and password on the specified access point.
- The **all** parameter configures the username and password on all the access points registered to the controller.

The password pushed from the controller is configured as “enable password” on the access point.

There are some cases where the pre-stage configuration for LWAPP access points is disabled and the access point displays the following error message when the CLI commands are applied:

“ERROR!!! Command is disabled.”

For more information, refer to *Upgrading Autonomous Cisco Aironet Access Points to Lightweight Mode* at this URL:

[http://www.cisco.com/en/US/docs/wireless/access\\_point/conversion/lwapp/upgrade/guide/lwapnote.html](http://www.cisco.com/en/US/docs/wireless/access_point/conversion/lwapp/upgrade/guide/lwapnote.html)

## Exclusion List (Blacklist) Client Feature

If a client is not able to connect to an access point, and the security policy for the WLAN and client are correct, the client has probably been disabled. In the controller GUI, you can view the client's status on the Monitor > Summary page under Client Summary. If the client is disabled, click **Remove** to clear the disabled state for that client. The client automatically comes back and, if necessary, reattempts authentication.

Automatic disabling happens as a result of too many failed authentications. Clients disabled due to failed authorization do not appear on the permanent disable display. This display is only for those MACs that are set as permanently disabled by the administrator.

## RADIUS Servers and the Management VLAN

If a RADIUS server is on a directly connected subnet (with respect to the controller), then that subnet must be the management VLAN subnet.

## Cisco 1000 Series Access Points and WMM

Cisco 1000 series access points in REAP mode do not support the Wi-Fi Multi-Media (WMM) protocol.

## Cisco Aironet 1030 Remote Edge Lightweight Access Points and WPA2-PSK

Cisco Aironet 1030 Remote Edge Lightweight Access Points do not support WPA2-PSK in REAP standalone mode.

## Lightweight Access Point Connection Limitations

Cisco Aironet lightweight access points do not connect to the 4400 series controller if the date and time are not set properly. Set the current date and time on the controller before allowing the access points to connect to it.

## RADIUS Servers

This product has been tested with CiscoSecure ACS 3.2 and later and works with any RFC-compliant RADIUS server.

## Management Usernames and Local Netuser Names

Management usernames and local netuser names must be unique because they are stored in the same database. That is, you cannot assign the same name to a management user and a local netuser.

## 802.1X and Microsoft Wireless Configuration Manager

Clients using the Microsoft Wireless Configuration Manager and 802.1X must use WLANs configured for 40- or 104-bit key length. Configuring for 128-bit key length results in clients that can associate but not authenticate.

## Using the Backup Image

The controller bootloader stores a copy of the active primary image and the backup image. If the primary image becomes corrupted, you can use the bootloader to boot with the backup image.

With the backup image stored before rebooting, be sure to choose **Option 2: Run Backup Image** from the boot menu to boot from the backup image. Then upgrade with a known working image and reboot the controller.

## Home Page Retains Web Authentication Login with IE 5.x

Because of a caching problem in the Internet Explorer 5.x browser, the home page retains the web authentication login. To correct this problem, clear the history or upgrade your workstation to Internet Explorer 6.x.

## Rogue Location Discovery Protocol (RLDP)

Enabling RLDP may cause access points connected to the controller to lose connectivity with their clients for up to 30 seconds.

## Ad-Hoc Rogue Containment

Client card implementations may mitigate the effectiveness of ad-hoc containment.

## Changing the Default Values of SNMP Community Strings

The controller has commonly known default values of “public” and “private” for the read-only and read-write SNMP community strings. Using these standard values presents a security risk. Therefore, Cisco strongly advises that you change these values. Refer to the *Cisco Wireless LAN Controller Configuration Guide, Release 4.2* for configuration instructions.

## Changing the Default Values for SNMP v3 Users

The controller uses a default value of “default” for the username, authentication password, and privacy password for SNMP v3 users. Using these standard values presents a security risk. Therefore, Cisco strongly advises that you change these values. Refer to the *Cisco Wireless LAN Controller Configuration Guide, Release 4.2* for configuration instructions.



**Note**

SNMP v3 is time sensitive. Make sure that you have configured the correct time and time zone on your controller.

## Features Not Supported on 2000 and 2100 Series Controllers

These hardware features are not supported on 2000 and 2100 series controllers:

- Power over Ethernet (PoE) for 2000 series controllers only



**Note**

Ports 7 and 8 on 2100 series controllers are PoE ports.

- Service port (separate out-of-band management 10/100-Mbps Ethernet interface)

These software features are not supported on 2000 and 2100 series controllers:

- VPN termination (such as IPSec and L2TP)
- Termination of guest controller tunnels (origination of guest controller tunnels is supported)
- External web authentication web server list
- Layer 2 LWAPP
- Spanning tree
- Port mirroring



**Note**

Port mirroring is also not supported on 4400 series controllers.

- Cranite
- Fortress
- AppleTalk
- QoS per-user bandwidth contracts
- IPv6 pass-through
- Link aggregation (LAG)
- Multicast-unicast mode

## Some Clients See Only 64 Access Point MAC Addresses (BSSIDs) at a Time

In a crowded RF environment, clients may not be able to detect the desired SSID because of internal table limitations. Sometimes disabling and then enabling the client interface forces a rescan. Your RF environment needs to be controlled. Cisco UWN rogue access point detection and containment can help you to enforce RF policies in your buildings and campuses.

## 2006 Image Not Supported for 3504 Controllers

The 2006 controller image is supported for use with only 2000 series controllers. Do not install the 2006 image on a 3504 controller. Otherwise, errors may occur. Install only the 3504 image on a 3504 controller.

## Running a 3504 Image on a 2000 Series Controller

It is possible to run a 3504 controller image on a 2000 series controller, but Cisco Aironet 1130, 1200, and 1240 series access points will not be able to connect to the controller.

## Upgrading External Web Authentication

When upgrading a controller from operating system release 2.0 or 2.2.127.4 to release 3.2.116.21 or later, update the external web authentication configuration as follows:

1. Instead of using a preauthentication ACL, the network manager must configure the external web server IP address using this command:

**config custom-web ext-webserver add *index IP-address***



**Note** *IP-address* is the address of any web server that performs external web authentication.

2. The network manager must use the new login\_template shown here:



**Note** Make sure to format the script to avoid any extra characters or spaces before using the web authentication template.

```
<html>
<head>
<meta http-equiv="Pragma" content="no-cache"> <meta HTTP-EQUIV="Content-Type"
CONTENT="text/html; charset=iso-8859-1"> <title>Web Authentication</title> <script>

function submitAction(){
    var link = document.location.href;
    var searchString = "redirect=";
    var equalIndex = link.indexOf(searchString);
    var redirectUrl = "";
    var urlStr = "";
    if(equalIndex > 0) {
        equalIndex += searchString.length;
        urlStr = link.substring(equalIndex);
        if(urlStr.length > 0){
            redirectUrl += urlStr;
            if(redirectUrl.length > 255)
                redirectUrl = redirectUrl.substring(0,255);
            document.forms[0].redirect_url.value = redirectUrl;
        }
    }

    document.forms[0].buttonClicked.value = 4;
    document.forms[0].submit();
}
```

```

function loadAction(){
    var url = window.location.href;
    var args = new Object();
    var query = location.search.substring(1);
    var pairs = query.split("&");
    for(var i=0;i<pairs.length;i++){
        var pos = pairs[i].indexOf('=');
        if(pos == -1) continue;
        var argname = pairs[i].substring(0,pos);
        var value = pairs[i].substring(pos+1);
        args[argname] = unescape(value);
    }
    //alert( "AP MAC Address is " + args.ap_mac);
    //alert( "The Switch URL is " + args.switch_url);
    document.forms[0].action = args.switch_url;

    // This is the status code returned from webauth login action
    // Any value of status code from 1 to 5 is error condition and user
    // should be shown error as below or modify the message as it suits
    // the customer
    if(args.statusCode == 1){
        alert("You are already logged in. No further action is required on your
part.");
    }
    else if(args.statusCode == 2){
        alert("You are not configured to authenticate against web portal. No further
action is required on your part.");
    }
    else if(args.statusCode == 3){
        alert("The username specified cannot be used at this time. Perhaps the user is
already logged into the system?");
    }
    else if(args.statusCode == 4){
        alert("Wrong username and password. Please try again.");
    }
    else if(args.statusCode == 5){
        alert("The User Name and Password combination you have entered is invalid.
Please try again.");
    }
}

</script>
</head>
<body topmargin="50" marginheight="50" onload="loadAction();" > <form method="post">
<input TYPE="hidden" NAME="buttonClicked" SIZE="16" MAXLENGTH="15" value="0"> <input
TYPE="hidden" NAME="redirect_url" SIZE="255" MAXLENGTH="255" VALUE=""> <input
TYPE="hidden" NAME="err_flag" SIZE="16" MAXLENGTH="15" value="0">

<div align="center">
<table border="0" cellspacing="0" cellpadding="0"> <tr> <td>&nbsp;</td></tr>

<tr align="center"> <td colspan="2"><font size="10" color="#336699">Web
Authentication</font></td></tr>

<tr align="center">

<td colspan="2"> User Name &nbsp;&nbsp;&nbsp;&nbsp;&nbsp;<input type="TEXT" name="username"
SIZE="25" MAXLENGTH="63" VALUE=""> </td> </tr> <tr align="center" > <td colspan="2">
Password &nbsp;&nbsp;&nbsp;&nbsp;&nbsp;&nbsp;&nbsp;&nbsp;<input type="Password" name="password"
SIZE="25" MAXLENGTH="24"> </td> </tr>

<tr align="center">

```



```
<td colspan="2"><input type="button" name="Submit" value="Submit" class="button"
onclick="submitAction();" > </td> </tr> </table> </div>

</form>
</body>
</html>
```

## Caveats

The following sections lists [Open Caveats](#) and [Resolved Caveats](#) in release 4.2.209.0. For your convenience in locating caveats in Cisco's Bug Toolkit, the caveat titles listed in this section are drawn directly from the Bug Toolkit database. These caveat titles are not intended to be read as complete sentences because the title field length is limited. In the caveat titles, some truncation of wording or punctuation might be necessary to provide the most complete and concise description. The only modifications made to these titles are as follows:

- Commands are in **boldface** type.
- Product names and acronyms may be standardized.
- Spelling errors and typos may be corrected.



### Note

If you are a registered cisco.com user, view Bug Toolkit on cisco.com at the following website:

<http://tools.cisco.com/Support/BugToolKit/>

To become a registered cisco.com user, go to the following website:

<http://tools.cisco.com/RPF/register/register.do>

## Open Caveats

These caveats are open in controller software release 4.2.209.0.

**Table 2**      **Open Caveats**

ID Number	Caveat Title
CSCsg73965	2106 unable to ping switch if two ports connected to the switch
CSCsi18500	System message documentation for USMDB
CSCsj62507	AP in Sniffer mode does not synchronize time
CSCsj79606	rap without bgn will show no mesh neighbor at mesh link tab
CSCsj87925	In GUI netmask for ACL accept arbitrary values
CSCsk17001	Wired WLAN template without wired interface - need proper validation
CSCsk64154	MESH Battery parameter missing/unknown flip from Con->D3
CSCsl03097	h-reap ap in standalone mode does not move ch during radar event
CSCsl18618	Client status shows disassociated on export anchor
CSCsl41764	Neighbor List should be sent by an AP as soon as it accepts Association

**Table 2**      **Open Caveats (Continued)**

ID Number	Caveat Title
CSCso31640	downgr to D3MR1, HREAP group got wiped out
CSCso40821	Apple Laptops Fail to Roam
CSCso60597	1250 fails to configure 40mhz wide channel for Sniffer Mode
CSCso94935	AP tftp downgrade does not give any error for invalid tftp address
CSCsq26051	controller hung after reboot
CSCsq29243	802.11h configuration allows invalid mode values to be configured
CSCsq30821	Able to bypass webauth after inter-cntr roam
CSCsq32038	CLI needs to indicate maximum length of interface name
CSCsq34262	Traceback on WLC console when loaded with 4.2.125.0 image
CSCsq35590	Trace back observed in AP console in 4.2.125.0
CSCsq38075	Trace back observed in AP console when configured Spain Country
CSCsq74144	Channel selected by AP in Sniffer Mode not displayed in WLC
CSCsq85579	Non-symmetric eoip ping reply from 440x Anchor is broken
CSCsr02316	WLC needs to return error instead of truncating SNMP string
CSCsr12961	Unknown parameters for configuring 802.11h
CSCsr72091	RRM: Various Issues with RRM on 4.2.130.0
CSCsu44722	Invalid Error Message while Enabling IPv6 for Mobility Anchor WLAN - GUI
CSCsv27173	Anchor Ct2106 passing unicast traffic in webauth reqd state
CSCsv54436	SSH to wlc is sometimes denied "Sorry, telnet is not allowed on.."
CSCsv76513	BSSIDs on A radio are the same as for B/G on 2106 running 4.2.130.0
CSCsw93671	Packets sourced from the service port sent from wlc when not connected
CSCsx28806	changing channel on C1510-E (RAP backhaul) all RAP & MAP gets cra
CSCsx75442	WLC 2106 giving Unnecessary message while upgrading.
CSCsy31995	AP1010 mapping wrong 802.11e value on downlink traffic
CSCsy60739	R-regulatory domain shows invalid power levels in AP1010
CSCsy82585	WLC2106 does not handle RLDP DHCP offer
CSCsy91860	Lock Assert (ccxRmTask)
CSCsy97877	1510 reboot, reason: unable to allocate buffer
CSCsz08837	2106 misbehaving after downgrading to Dmr4 from H
CSCsz19970	Hot Standby, controller has issue with data rates for voice clients
CSCsz39384	Radio Core Dump fails on TFTP Upload
CSCta54283	Invalid channel getting assigned to AP
CSCta56507	Silent reboot on foxhound on the script run
CSCta75471	LWAPP AP not joining Boxer WLC with a particular configuration
CSCtb10500	HREAP AP Crashed while in CONFIG state on a noisy wan link
CSCtb81465	In WebUI Ap detail page, ap group name is shown as '--' .

**Table 2**      **Open Caveats (Continued)**

ID Number	Caveat Title
CSCtc77130	Mobility fail when IRCM with 6.0.183.x and above
CSCtc97999	AP1500 fails on cryptonicon IPv4 test
CSCtf66329	Cannot stop debug packet logging when # of packets is specified
CSCtf78029	SNMP traps for 1231 AP also sent for Interface:1(unknown type)
CSCtf84298	AP1030 keep on detecting Deauth attack. (MFP)
CSCtf95220	Cannot add IDS throug GUI
CSCtf96302	ping fails to dyn i/f
CSCtg03267	WLC2106 reboots without crash info
CSCtg06563	PerUserBandwidth not honoured when user switch btw vendor -> regular
CSCtg09207	1510 possibly out of buffers, breaks MAP join and large frame forwarding
CSCtg11797	Issue while upgrading from DCubedMR5 to DcubedMR6.
CSCtg27187	Able to access the Foreign Controller during Web_auth Req State
CSCtg28826	Lock Assert

## Resolved Caveats

These caveats are resolved in controller software release 4.2.209.0.

**Table 3**      **Resolved Caveats**

ID Number	Caveat Title
CSCtb31111	Memory Leak in EAP framework task
CSCsl22707	AP1250 Resets During Boot Using POE from 3550 Switch
CSCsm84048	AP1250 does not get 20 W power if switch is configure for trunk port
CSCso50723	WLC2106 EAP-FAST PAC provision failed due to slow DiffieHellman
CSCsq09933	Converted AP w/ static IP ignores DNS after downloading full image
CSCsv77658	AP reset from watchdog timer expired
CSCsw31160	Lobby Admin username can be used for webauthentication
CSCsx07150	Voice gap when phone roams, if CAC is not configured on APs
CSCsx50408	LWAP DOS Attack trap message does not record the source MAC address
CSCsx69535	AP on different subnet lost connetion with WLC
CSCsx70889	Crash due to stack corruption caused by recursive tunnels
CSCsx71175	WLC broadcast dhcp does not comply with RFC 1542
CSCsy06464	H-REAP AP obtains IP via DHCP on wrong interface
CSCsy06689	Memory leak on 3.2.210.0
CSCsy30722	Next hop address stored in capwap doesn't get updated on rcvng GRAT ARP
CSCsy97077	WLC Controller 'show run-config' is truncated, not complete, incomplete

**Table 3**      **Resolved Caveats (Continued)**

ID Number	Caveat Title
CSCsz03148	Talwar crashes @ EAP Framework
CSCsz14243	Unable to enable the WLAN while the APs are joining
CSCsz26858	WLC crash Task Name: dot11b (usmDbSnmpRrmProfileFailureTrapSend)
CSCsz32424	Rogue not detected on wire using the arp
CSCsz38828	AMAC radio core dumps: transmitter seems to have stopped
CSCsz48244	4.2 Mobility Control path flapping up/down
CSCsz48460	AP crashing on dot11_tx
CSCsz49863	WLC Local EAP auth periodically fails with 792x phone using EAP-FAST
CSCsz58995	Reaper reset crash on WLC with 1 monitor AP
CSCsz64049	WLC crash - nf_iterate causes kernel panic/exception
CSCsz72416	Unexpected vlan is assigned due to failed to aaa override
CSCsz76796	PMK cache isn't updated
CSCsz82548	Clients can communicate even though clients auth status is "No"
CSCsz88241	Per user bandwidth contracts stop functioning
CSCsz89606	AP unable to perform DNS based on given DHCP DNS options
CSCta09996	Sometimes LAP can't join to WLC via alternative port in port redundancy
CSCta13941	AP rejecting association request with status code 13
CSCta19001	AP1000 reboots continuously when applying fix for CSCs190630
CSCta29484	Radio stops beaconing for 10-second period
CSCta40160	Dropping primary discovery request from an AP already joined to the WLC
CSCta45156	Upgrade to 6.0.182.0 Webauth login page text views as one long sentence
CSCta93380	WLC on 4.2.205.0 drops bootp packet
CSCtb12031	1142 / 1252 inconsistently ACKs Vocera (gen1) badge
CSCtb29243	ARP storm on inter-controller NAC scenario for quarantined client
CSCtb34971	WLC WISM loading 3rd party cert for web-auth disables HTTPS port 443
CSCtb36010	Lightweight AP responds on port 22 when SSH is disabled
CSCtb52563	WLC 4.2.205.0 crashes at spam_CCM_decrypt+124
CSCtb58091	WLC CPU Spike with emWeb - Controller Not Responding - No crash
CSCtb64994	Intermittent Webadmin and Webauth access on WiSM running 5.2.193
CSCtb74239	WISM crashed on task sshpmMainTask System Crash
CSCtc03575	Controller fails to redirect web authentication to external server
CSCtc15346	AP1252 fails to retransmit missing AMPDU packet in response to block ack
CSCtc45090	Controller sends wrong mac in ARP response, can cause mobility flapping
CSCtc91431	ReadOnly local management user can change H-REAP VLAN mapping
CSCtc97595	Only one of many Gratuitous ARP packets are forwarded to client
CSCtd01611	Important TLS/SSL security update

**Table 3**      **Resolved Caveats (Continued)**

ID Number	Caveat Title
CSCtd16938	WLC crash after passing invalid arguments to emweb
CSCtd26408	WCS 4.2.110.0 cannot modify external web auth redirection URL for WLANs
CSCte40517	WLC2106 reboots at pemReceiveTask
CSCte55458	Web-Auth: Web page takes a long time to display under heavy load
CSCte89891	Radio may stop transmitting beacons periodically
CSCtf63030	Radio may get stuck in RESET or DOWN state

## If You Need More Information

If you need information about a specific caveat that does not appear in these release notes, you can use the Cisco Bug Toolkit to find caveats of any severity. Click this URL to browse to the Bug Toolkit:

<http://tools.cisco.com/Support/BugToolKit/>

(If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.)

## Troubleshooting

For the most up-to-date, detailed troubleshooting information, refer to the Cisco TAC website at

<http://www.cisco.com/en/US/support/index.html>

Click **Product Support** > **Wireless**. Then choose your product and **Troubleshooting** to find information on the problem you are experiencing.

## Documentation Updates

This section lists updates to user documentation that has not yet been added to either printed or online documents.

## Omissions

The Package Contents section in the *Quick Start Guide: Cisco 4400 Series Wireless LAN Controllers* should be updated to include this item, which is included with the 4400 series controller:

- DB-9-to-DB-9 null modem cable

## Related Documentation

For additional information on the Cisco controllers and lightweight access points, refer to these documents:

- The quick start guide for your particular controller or access point
- *Cisco Wireless LAN Controller Configuration Guide*
- *Cisco Wireless LAN Controller Command Reference*
- *Cisco Wireless Control System Configuration Guide*

Click this link to browse to the Cisco Support and Documentation page:

<http://www.cisco.com/cisco/web/support/index.html>

## Obtaining Documentation, Support, and Security Guidelines

For information on obtaining documentation, obtaining support, providing documentation feedback, security guidelines, and also recommended aliases and general Cisco documents, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

CCDE, CCENT, CCSI, Cisco Eos, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Nurse Connect, Cisco Pulse, Cisco SensorBase, Cisco StackPower, Cisco StadiumVision, Cisco TelePresence, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flipshare (Design), Flip Ultra, Flip Video, Flip Video (Design), Instant Broadband, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Capital, Cisco Capital (Design), Cisco:Financed (Stylized), Cisco Store, Flip Gift Card, and One Million Acts of Green are service marks; and Access Registrar, Aironet, AllTouch, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Lumin, Cisco Nexus, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Continuum, EtherFast, EtherSwitch, Event Center, Explorer, Follow Me Browsing, GainMaker, iLNX, IOS, iPhone, IronPort, the IronPort logo, Laser Link, LightStream, Linksys, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, PCNow, PIX, PowerKEY, PowerPanels, PowerTV, PowerTV (Design), PowerVu, Prisma, ProConnect, ROSA, SenderBase, SMARTnet, Spectrum Expert, StackWise, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0910R)

© 2010 Cisco Systems, Inc. All rights reserved.