



Release Notes for Cisco Wireless Control System 5.0.56.2 for Windows or Linux

April 2008

These release notes describe open and resolved caveats for the Cisco Wireless Control System 5.0.56.2 for Windows or Linux, which comprises part of the Cisco Unified Wireless Network Solution (Cisco UWN). This software release does not introduce new features; it is an update to release 5.0.56.0 that resolves these defects:

- CSCsm78993—The WCS installer no longer fails to restore the database at the end of a software upgrade.
- CSCsm93369—After you assign a location server to the network design and click Synchronize, WCS no longer returns to the synchronize servers page still showing the design as unassigned. WCS now synchronizes the network design correctly and the design shows as assigned.
- CSCso39180—The standalone SE demo License now enables the SE feature.



Note

This release of Cisco WCS does not support controllers running software releases 4.2.99.0 and 4.2.112.0. A future release of Cisco WCS will support controllers running these software releases.



Note

Cisco WCS Navigator release 1.2.56.0 is compatible with this release of Cisco WCS. No upgrade from WCS Navigator release 1.2.56.0 is required when you install this release of Cisco WCS.



Americas Headquarters:

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved.

Contents

These release notes contain the following sections.

- [Cisco Unified Wireless Network Solution Components, page 2](#)
- [Requirements for Cisco WCS, page 3](#)
- [Important Notes, page 5](#)
- [New and Changed Information, page 8](#)
- [Caveats, page 8](#)
- [Troubleshooting, page 17](#)
- [Related Documentation, page 18](#)
- [Obtaining Documentation, Obtaining Support, and Security Guidelines, page 18](#)

Cisco Unified Wireless Network Solution Components

The following components are part of the Cisco UWN Solution and are compatible in this release:

- Operating system (Wireless LAN Controller and Cisco Aironet Lightweight Access Point)
- Cisco Wireless Control System (Cisco WCS) software release 5.0.56.2
- Location appliance software release 4.0.33.0
- Cisco WCS Navigator release 1.2.56.0
- Cisco 2700 Series Location Appliance
- Cisco 2000 Series Wireless LAN Controllers
- Cisco 2100 Series Wireless LAN Controllers
- Cisco 4400 Series Wireless LAN Controllers
- Catalyst 3750G Wireless LAN Controller Switches
- Cisco Wireless Services Modules (WiSMs) for Cisco Catalyst 6500 Series Switches
- Cisco WLAN Controller Network Modules for Cisco Integrated Services Routers
- Cisco Aironet 1000, 1100, 1130, 1200, 1230, 1240, 1250, 1310, and 1500 Series Lightweight Access Points
- Cisco Aironet 1310 and 1410 Bridges
- Cisco Aironet Access Points running LWAPP

Requirements for Cisco WCS

The following server hardware and software is required to support Cisco WCS for Windows or Linux.

Hardware Requirements for Server

Cisco WCS can be run on a workstation or server, and access points can be distributed unevenly across controllers.


Note

AMD processors that are equivalent to the Intel processors listed below are also supported.

- High End Server—Supports up to 3,000 Cisco Aironet lightweight access points, 1,250 standalone access points, and 750 Cisco wireless LAN controllers.
 - 3.16-GHz Intel Xeon Quad processor with 8-GB RAM.
 - 80-GB minimum free disk space is needed on your hard drive.
- Standard Server—Supports up to 2,000 Cisco Aironet lightweight access points, 1,000 standalone access points, and 150 Cisco wireless LAN controllers.
 - 3.2-GHz Intel Dual Core processor with 4-GB RAM.
 - 40 GB minimum free disk space is needed on your hard drive.
- Low End Server—Supports up to 500 Cisco Aironet lightweight access points, 200 standalone access points, and 125 Cisco wireless LAN controllers.
 - 3.06-GHz Intel processor with 2-GB RAM.
 - 30 GB minimum free disk space is needed on your hard drive.


Note

The free disk space listed is a minimum requirement but may be different for your system, depending on the number of backups.


Note

Cisco WCS can simultaneously manage multiple Cisco wireless LAN controllers running different software versions. The new features supported in wireless LAN controller version 5.0.148.0 will be supported by Cisco WCS 5.0.56.2 and WLC running release 4.1.191.24M to support Cisco Aironet mesh access points.

Operating Systems Requirements

The following operating systems are supported:

- Windows 2003/SP2 or later 32-bit installations with all critical and security Windows updates installed.


Note

Windows 2003/SP2 64-bit installations are not supported.

**Note**

Windows 2003 32-bit installations provide support for up to 64 GB of RAM provided Physical Address Extension (PAE) is enabled. Refer to Windows documentation for instructions on enabling this mode.

- Red Hat Linux Enterprise Server 5.0 32-bit operating system installations.

**Note**

Red Hat Linux Enterprise Server 5.0 64-bit operating system installations and Red Hat Linux Enterprise Server 5.1 are not supported.

- Windows 2003 and Redhat Linux version support on VmWare ESX 3.0.1 version and above.

**Note**

VmWare must be installed on a system with these minimum requirements: Quad CPU running at 3.16 GHz, 8 GBs RAM, and 200-GB hard drive.

**Note**

Individual operating systems running WCS in VmWare must follow the specifications for the size of WCS you intend to use.

Supported Browsers

The Cisco WCS user interface requires Internet Explorer 6.0/SP1 or 7.0, with the Flash plugin. The Cisco WCS user interface has been tested and verified using a Windows workstation.

Browsing on Windows 2003 Cisco WCS servers is not recommended because recommended Windows 2003 security settings cause browsing problems.

WCS on WLSE Appliance

Cisco WCS on a WLSE appliance supports up to 1500 Cisco Aironet lightweight access points and 100/375 Cisco wireless LAN controllers. The required processors is a 3-GHz Intel Pentium with 3 GB of RAM and 38 GB of free hard drive space.

**Note**

AMD processors that are equivalent to the Intel processors are also supported.

**Note**

Windows operating system is not supported with the WCS on the WLSE appliance.

Cisco WCS User Interface

The Cisco WCS user interface requires Internet Explorer 6.0/SP1 or later, with the Flash plug-in. The Cisco WCS user interface has been tested and verified using Internet Explorer 6.0 on a Windows workstation.

**Note**

The screen resolution should be set to 1024 x 768 pixels for both WCS and Navigator.

Client Requirements

In order for clients to access WCS, they must have a minimum of 1 GB RAM and a 2-GHz processor. The client device should not be running any CPU or memory-intensive applications.

Finding the Software Release

To find the software release Cisco WCS is running, refer to the *Cisco Wireless Control System Configuration Guide*. If WCS is already installed and connected, verify the software release version by choosing **Help > About the Software**.

Upgrading to a New Software Release

The Cisco WCS release must be the same or more recent than the controller software release. Upgrade the Cisco WCS first to prevent any unexpected problems. Cisco WCS supports database upgrades only from the following official Cisco WCS releases:

- 4.1.83.0
- 4.1.91.0
- 4.2.62.0
- 4.2.62.11
- 5.0.56.0

Important Notes

This section describes important information about Cisco WCS.

Compatibility

**Note**

This release of Cisco WCS does not support controllers running software releases 4.2.99.0 and 4.2.112.0. A future release of Cisco WCS will support controllers running these software releases.

This release of Cisco WCS for Windows or Linux is compatible with wireless LAN controller and Cisco Aironet lightweight access point release 5.0.148.0 or later. Previous releases of Cisco WCS should not be used with the 5.0.148.0 controller software release.

For compatibility issues with the location server, refer to the *Release Notes for Cisco 2700 and 2710 Location Appliances for Software Release 4.0.32.0* at this location:

http://www.cisco.com/en/US/products/ps6386/prod_release_notes_list.html

You may experience compatibility issues if you add a controller with a newer release than the WCS release. For example, 5.0 controller software releases should not be added to WCS 4.2.

Regulatory Updates

- Japan update—The Japanese government is formally permitting wireless LAN use of the frequencies in the W56 band for 802.11a radios. [Table 1](#) shows the channels, frequencies, and power levels in unit of measure of the W56 band.

Table 1 Channels, Frequencies, and Power Levels for W56 in Japan

Channel	Frequency (MHz)	Maximum Power for AIR-LAP1132AG-Q-K9	Maximum Power for AIR-LAP1242AG-Q-K9
100	5500	17	15
104	5520	17	15
108	5540	17	15
112	5560	17	15
116	5580	17	15
120	5600	17	15
124	5620	17	15
128	5640	17	15
132	5660	17	15
136	5680	17	15
140	5700	17	15

All of the channels in the W56 band require dynamic frequency selection (DFS). In Japan, the W56 band is subject to Japan's DFS regulations. Currently, only the new 1130 and 1240 series access point SKUs support this requirement: AIR-LAP1132AG-Q-K9 and AIR-LAP1242AG-Q-K9.

- Additional country support—Country codes have been added for these additional countries supported by the controller: Bahrain (BH), Costa Rica (CR), Dominican Republic (DO), Ecuador (EC), Kazakhstan (KZ), Kuwait (KW), Oman (OM), Pakistan (PK), Paraguay (PY), Puerto Rico (PR), Vietnam (VN).

Notes about Google Earth

When you launch Google Earth, this message appears:

```
Google Earth could not write to the current cache or myplaces file location. The values
will be set as follows:
My Places Path:"C:\Document and Settings\userid\Application Data\Google\GoogleEarth"
Cache Path: "C:\Documents and Settings\userid\Local Settings\Application
Data\Google\GoogleEarth"
```

This is expected behavior.

Also, if you visit AP details a second time, you get an “invalid path / googleArthLradDetails was requested” HTTP status message. This Google Earth problem can be resolved by deleting the first access point details occurrence.

Refresh Controller Values

If configuration differences are found as a result of the audit, you can either restore WCS values on the controller or refresh controller values to synchronize WCS with the controller. Choose **Restore WCS Values** or **Refresh Controller Values**.



Note

If you choose to refresh the controller values, you receive a Refresh Config window with two options for “Configuration if present on WCS but not on device, do you wish to:”

Retain—The WCS refreshes the configuration from the controller but will not delete any devices or configurations that no longer exist in the controller configuration. For example, if the WCS database shows an AP1 but that access point is no longer present in the controller configuration, WCS will not delete AP1 from its database.

Delete—WCS deletes the configuration of the controller from its database and retrieves a new configuration from the controller. Delete is the recommended option so WCS matches the most recent configuration you are refreshing from WLCs.



Note

When WCS does a Refresh Config, only the configuration objects for this controller in the WCS database are updated. Upon refresh, the WCS templates are not updated.

Windows XP Cannot Load CAD Files

Internet Explorer 7 running on Windows XP cannot load CAD files because of missing DLLs (C:\Windows\system\DWMAPI.DLL). These DLLs are only present on Windows Vista.

One of the following actions can be taken:

- Uninstall IE7 and install IE6.
- Leave IE7 and install the missing DLLs.

Security Reports Are Not Getting Upgraded

If you are using Windows 2K and upgrading to software release 4.2, the Security report is not getting upgraded. All of the other reports (Audit, Client, Inventory, Mesh, and Performance) are upgrading correctly.

User Assistant Cannot Configure Controller

User assistants cannot configure or monitor controllers. They can only configure LocalNet Users in the controller, but they must access the **Configure > Controller** path to configure these local net features. If you create a user assistant user under the group category, login as that user, and go to **Monitor > Controller**, you receive a permission denied message as expected behavior.

Deletion of TFTP Server Is Not Updated in the Configuration Backup

To add a TFTP server you click **Configure > Controller Templates**, choose **TFTP server** from the left sidebar menu, and choose **Add TFTP Server** from the drop-down menu. To add the TFTP server, you give details of the name and IP address and click **Save**. If you later delete this TFTP server and perform a configuration backup (**Administration > Background Task > Configuration Backup**), the IP address of the TFTP server still shows in the TFTP Server window when only the default server should be shown.

Conflicting Ports Interrupt WCS Start

WCS fails to start if there is a conflicting port in use. You receive a “Failed to start WCS server” message, but you do not receive a list of conflicting ports. Go to **WCS/webnms/logs/wcs-0-0.log** and view the conflicting ports. In Windows XP and Windows Server 2003, enter **NETSTAT -0** to get a list of the process ID associated with each connection. In the Task Manager, you see the respective PID and can stop the process using the port that WCS requires.

New and Changed Information

New Features

This release does not include new features.

Changed Information

There is no deployment restriction on the number of hybrid-REAP access points per location. However, the minimum bandwidth restrictions remains at 128 kb/s with the roundtrip latency no greater than 100 ms and the maximum transmission unit (MTU) no smaller than 500 bytes.

Caveats

This section lists resolved and open caveats in Cisco WCS 5.0.56.2 for Windows and Linux.

Resolved Caveats

These caveats are resolved in software release 5.0.56.2:

- CSCsm78993—The WCS installer no longer fails to restore the database at the end of a software upgrade.
- CSCsm93369—After you assign a location server to the network design and click Synchronize, WCS no longer returns to the synchronize servers page still showing the design as unassigned. WCS now synchronizes the network design correctly and the design shows as assigned.
- CSCso39180—The standalone SE demo License now enables the SE feature.

Open Caveats

These caveats are open in Cisco WCS 5.0.56.2:

- CSCsg74466—If you choose **Monitor > Devices > Access Points** and select **Noise/Interference/Coverage (RSSI/SNR)** to generate a report, the legend of the report overlays the actual chart display area.
Workaround: You can instead view the report on the WLC.
- CSCsh44930—In the Clients Summary page (Monitor > Clients), typing the MAC address for a mobile client in the Client field and clicking the **Troubleshoot** button does not open up the Client Troubleshooting window.
Workaround: Search for the client by its MAC address using the Quick Search field and click the link for the returned client to go the Client Details page. On the Client Details page, choose **Troubleshoot** from the Command drop-down list and click **GO**.
- CSCsh81856—While installing, the password field is only partially encrypted.
Workaround: Only one or two of the letters show up during installation. After the password is created and the user clicks **Enter**, the screen proceeds to the next session.
- CSCsh82165—Upon install or uninstall, the following error message sometimes displays: “Command.run(): process completed before monitors could start.”
Workaround: This message is irrelevant. No workaround is necessary.
- CSCsi26963—The Client Association report does not include any records older than 7 days.
Workaround: None at this time.
- CSCsi46344—There are certificate download errors on the WCS.
Workaround: Certificates can be downloaded directly to the controller rather than via the WCS.
- CSCsj16153—You cannot simultaneously troubleshoot two different clients from the same WCS.
Workaround: None at this time.
- CSCsj18398—When setting up a WLAN from WCS, a WPA or WPA2 choice does not forward to the 4.1 version controller.
Workaround: You must choose WPA/WPA2 (instead of individual WPA or WPA2) for controller version 4.1 and greater.
- CSCsj36002—The logs that get generated while troubleshooting a client cannot be truncated into 2 MB files.
Workaround: None at this time. However, this has no adverse effect on functionality.
- CSCsj61673—The event log for the client gets duplicated after some time has passed.
Workaround: Click **Stop** to terminate the event log capture after the log has been retrieved.

- CSCsj72272—You cannot enable the Accept Signed Certificate option on the Configure > Controller Template > AP Authorization page.
Workaround: You can perform this operation on the Configure > Controller > Security > AP Authorization page with the Edit AP Policies option from the Select a command drop-down menu.
- CSCsj77046—If you add controllers (with comma separation) which are combinations of WiSMs (2000s and 4400s), the status messages makes it appear as if only the WiSMs were added.
Workaround: On the Configure > Controllers page, you can see a complete list of controllers that were added successfully.
- CSCsj96574—When adding guest user accounts using a CSV file, you may receive an unknown exception error from the import operation.
Workaround: Make sure you format the file correctly and retry the operation. The correct sequence of fields per row is username, password, lifetime, description, and then disclaimer.
- CSCsk01665—If you add any template with a negative test case and try to apply the template to the device, the object is not created in the device, even though the Apply To field is incremented.
Workaround: Confirm if the object is added by logging onto the device and using an audit to check the configuration.
- CSCsk02071—The following error message occurs when loading a CAD file in maps:
Error in getting data from server. Make sure you have connectivity and server is UP.
Workaround: Add the .dll files in the following locations and restart the WCS server:
c:\windows\system32\msvcp71.dll
c:\windows\system\dwmapi.dll
- CSCsk12424—An invalid CSV file results in an unknown exception on the migration template.
Workaround: Create a CSV with a valid format.
- CSCsk17031—The history page loads slow when trying to view the location history of a tag or client.
Workaround: Make sure the history interval for client, tags, rogue clients, and access points is not significantly high on the Location Server > Administration > History Parameters page. You can also frequently purge the data.
- CSCsk17038—If more than 1000 elements (clients and tags) are tracked by the location server on a single floor, the performance for maps on that floor is affected.
Workaround: Turn off the client and tags layer on the map so you can see the access points and other information on the map. Viewing over a thousand items on a single map is not practical. You should use the search option on the Monitor > Clients or Monitor > Tags page to look at the clients.
- CSCsk18826—Cisco WCS might experience slower refresh and rendering times (in Location > Synchronization) when managing large controller networks (200 or more) because of increased page synchronization requirements. Additionally, the CPU use for the web browser increases substantially and the browser might be unresponsive for a short period of time.
Workaround: Wait for the page to load completely.
- CSCsk25417—All clients are displayed if you click any header to resort WGB clients.
Workaround: Choose **Monitor >WGB** to reset the list of WGB clients.
- CSCsk28639—The restore configuration system command is not working.
Workaround: Restore the templates individually or access the controller to make the changes there.

- CSCsk28942—While omnidirectional antennas’ radiation pattern may have some asymmetry, they generally radiate in all directions. This causes confusion trying to set antenna orientation and position access points in WCS. When Cisco omnidirectional antenna products are chosen, the setting for omni products should be disabled since the specifications of the antenna are known. The following Cisco products should have omnidirectional patterns considered: AIR-ANT5959, AIR-ANT4941, AIR-ANT2422DW-R, AIR-ANT1728, AIR-ANT2506, AIR-ANT3213, AIR-ANT24120, integrated AP1120 antenna, integrated RM21A antenna, AIR-ANT5135D-R, AIR-ANT5135DW-R, AIR-ANT5145V-R, AIR-ANT5160V-R, AIR-ANT58G9VOA-N, AIR-ANT5175V-N, AIR-ANT2455V-N, and integrated AP1130AG antennas.

Workaround: Set the antenna orientation value to 0.

- CSCsk31842—WLC fails to join WCS if a NAT/PAT is in place.

Workaround: Downgrade to 3.2.195.13.

- CSCsk39485—If you make modifications to an existing HREAP AP group template and save them, the changes are not reflected.

Workaround: None at this time.

- CSCsk41869—If you apply a template and then reapply the same template, the sort process returns an exception.

Workaround: None at this time.

- CSCsk45060—Within access point templates, the WLAN profiles in the WLAN override list are retained even when profiles are no longer used on any controllers.

Workaround: None at this time.

- CSCsk45607—An error should appear when a snmpv3 user enters less than 12 characters for an AES cipher authentication password.

Workaround: None at this time.

- CSCsk48985—If you change template parameters of an existing template and then apply it to a different number of controllers, the window shows the template as applied to the original number of controllers.

Workaround: If you need to change parameters in a template, create a new template.

- CSCsk51302—When you click on Client Troubleshooting in Monitor > Clients, an “object *switch* does not exist” error displays.

Workaround: None at this time.

- CSCsk55160—If you switch between perimeter and rectangle in the planning mode tool, the total coverage area does not change, and the message above the radio buttons does not update.

Workaround: Adjust the size of the rectangle to approximately cover the perimeter area. Generate the report in either perimeter or rectangle mode.

- CSCsk72193—When you perform a refresh config from the controller, you are given the option to retain or delete if the configuration is present in WCS but not on the device. The differences between the options is unclear to the user.

Workaround: None at this time.

- CSCsk78181—The Automatic Client Troubleshooting Logs or CCXv5 Test Analysis generates a frame log .cap file, but the file does not contain any frames data.

Workaround: None at this time.

- CSCsk79095—On the client detail page for WGB clients (Monitor > WGB), the drop-down menu contains options which are not relevant to the WGB clients. If you choose radio measurements, V5 statistics, operation parameters, and so on, a misleading message appears.
Workaround: None at this time. Commands related to the radio do not apply to WGB clients.
- CSCsk81958—Clients that are connected to autonomous access points are showing as rogue clients.
Workaround: None at this time.
- CSCsk87607—When a location accuracy test is tracking a large number of elements and it is left in the enabled state for a number of days, large log files might fill the logs directory. A subsequent download of a given log file might timeout given the size of the file.
Workaround: Log into the location server via SSH and move or remove log files of the following format: *rf-MAC-address.log* (rf-00-0c-5c-07-18.log) from the */opt/locserver/logs* directory.
- CSCsk88821—When creating maps, the floor information for a building is not retained, and WCS displays an error.
Workaround: None at this time.
- CSCsk91931—Even if rogue entries are made into the WCS template with uppercase MAC addresses, the WLC and WCS always show them as lowercase. This results in an audit error.
Workaround: Use only lowercase for known rogues.
- CSCsl08696—If you establish an RF calibration model under WCS > Monitor > Maps > RF Calibration Model, you cannot change the name. This occurs in WCSs running version 4.1.91.0 and 4.2.62.0.
Workaround: None at this time.
- CSCsl11236—If you try to change the 802.11b/g configuration by checking or unchecking parameters, you may see a servlet exception error.
Workaround: None at this time.
- CSCsl12804—When you test the link between the controller and the client using Link Test, the ping results or RSSIs fail for some authenticated clients and voice clients. An error message that appears says the connection requires an associated client when in actuality it requires authenticated clients.
Workaround: None at this time.
- CSCsl38408—When you press the Exit or Save button, the map editor does not exit.
Workaround: You can close the window by pressing X on the right-hand side of the browser.
- CSCsl38717—After a guest user template is created and applied, some of the attributes are represented incorrectly when the template is revisited. For example, the status of the user account may show as expired rather than active.
Workaround: Delete the existing template and create and apply a new one.
- CSCsl40179—The CSV file contains a typo. It should read *csv-telnetpassword.jpeg* instead of *csv-tenetpassword.jpeg*.
Workaround: None at this time.
- CSCsl41999—An exception failure occurs when applying an SNMP template.
Workaround: None at this time.
- CSCsl42250—When running concurrent user sessions on WCS, some access pages take a very long time to display.
Workaround: None at this time.

- CSCsl42358—In a quick search, the substring matching function returns more data than the matched strings.
Workaround: None at this time
- CSCsl44156—When using Cisco WCS, attempts to login to Monitor Lite are denied after upgrading from release 4.0 to 5.0. A window displays stating that you do not have privileges for the requested operation.
Workaround: None at this time.
- CSCsl47529—When WCS is upgraded from 4.1.83.0, the lobby ambassador cannot view the password of guest users created in this version.
Workaround: None at this time.
- CSCsl48403—When you import an access point configuration, you get an unwanted WCS prefix before the access point names in the status message.
Workaround: None at this time.
- CSCsl48483—The access point name gets updated in the access point link but not in the Config > Access Point page where all the access points are listed.
Workaround: None at this time.
- CSCsl51188—WCS does not update the friendly internal state for a rogue access point when the same MAC is present on two WLCs.
Workaround: None at this time.
- CSCsl53127—The operation status in Config > AP does not show the correct information. The admin status of the radios differ from the operational status, and they should be the same.
Workaround: None at this time.
- CSCsl53478—The access point goes into pending state while searching for access points using Monitor > AP and does not retrieve the results.
Workaround: Search for access points from a different page, such as the Monitor page.
- CSCsl53595—When the controller information on the access point is imported through the Import AP Config feature, the access point gets updated but the error message returns that it was not updated.
Workaround: None at this time.
- CSCsl53612—The first and last information which appears for rogue access points on maps does not appear.
Workaround: None at this time.
- CSCsl53877—The access point cannot be searched by floor area on an access point template page. Without this, an admin may not be able to apply an access point template to a particular access point.
Workaround: Use the Search for AP based on Controller(s) option instead of floor areas and then apply the templates on the access point.
- CSCsl53950—The icon for single radios appears incorrectly on the floor map. For example, if you choose 802.11a/n, the 802.11b/g radio shows as green when it should be gray. When the map is initially launched, the status shows correct, but when you change the protocol, the status is wrong until the map is launched again.
Workaround: None at this time.

- CSCsl54522—The port number that displays in the pop-up when you mouse over a client icon map might differ from the port number that displays in the client general properties panel when you click on the client icon on the map. These port values should be the same.

Workaround: Use the port value that displays on the client general properties panel.

- CSCsl57064—When an administrator tries to create a wired guest user within WCS, an error message appears.

Workaround: The wired guest user interface can be created on the controller instead of WCS. The created wired guest user interface can then be pushed to WCS through the refresh config from a controller command.

- CSCsl57546—When WCS is displaying a rogue device, it sometimes shows the detecting access point's MAC address instead of its name depending on the detection method used. If WCS discovers the rogue through a poll, it uses the MAC address of the access point for a name. If WCS discovers the rogue by a trap from a WLC, it uses the name.

Workaround: None at this time.

- CSCsl63991—The status message does not display tertiary controller information after you do a Config > AP > Import.

Workaround: None at this time.

- CSCsl64048—If you try to update more than two access point host names, the update does not occur.

Workaround: None at this time.

- CSCsl64243—The status of the tertiary controller does not show up in the log.

Workaround: None at this time.

- CSCsl68504—When you create a guest user whose limited life spans the end of the month, WCS incorrectly throws an “end data cannot be older than start date” error.

Workaround: Create the guest user from the start date until the end of the month and then create a second user from the first of the month until the desired end date.

- CSCsl73139—The channel utilization for mesh access point for backhaul interface does not match that of regular maps and Google Earth maps.

Workaround: None at this time.

- CSCsl73205—When a rogue is detected as friendly on one controller, the rogue state is not always updated from malicious to alert to friendly.

Workaround: If you execute the rogue access point background task multiple times, the rogue state on the controller is updated.

- CSCsl75176—In some cases the access point heatmap is displayed in the upper left-hand corner instead of where the access point is placed.

Workaround: None at this time.

- CSCsl75617—The interference alarm is detected by the spectrum expert but shows no location information on the Location Server when the alarm is generated.

Workaround: Synchronize your location server.

- CSCsl76192—If you use the Apply button when in planning mode, a servletException error appears.

Workaround: None at this time.

- CSCsl77797—The Location Accuracy Tool (Tools > Location Accuracy Tool) does not generate a spatial image when the map is not imported as a GIF file.

Workaround: Import maps as JPEG files.

- CSCsl79802—When importing a file, the primary and secondary controller entries cannot be blank.
Workaround: None at this time.
- CSCsl80359—Although the task scheduler may show guest users as expired, the Guest User template shows them as scheduled.
Workaround: None at this time.
- CSCsl82286—A WCS TFTP upload may fail when running software version 4.2.62.x. This occurs if the TFTP directory for WCS is on a drive other than the one in which WCS is installed.
Workaround: Configure WCS to have the TFTP server on the same partition of the hard disk as the WCS installation.
- CSCsl82677—The Config > AP > Import Config page needs to have a column for the access point name (or MAC address if the access point name is not known). Without a host name, nothing is displayed in the import status messages.
Workaround: None at this time.
- CSCsl83378—If you use the Firefox browser to open up the Monitor > Clients page, the graphs and white space around it are not proportioned.
Workaround: None at this time.
- CSCsl84309—If a lobby ambassador creates a guest user using a CSV file, the end time and account expiration does not appear correctly.
Workaround: You can create a guest user account without using CSV files.
- CSCsl85843—The Cisco Compatible Extensions version 5 client statistics task takes many hours to complete and blocks the other scheduled tasks from running.
Workaround: None at this time.
- CSCsl87541—If you choose Monitor > AP and click **Edit View**, the search results show multiple listings of the client count.
Workaround: None at this time.
- CSCsl89809—If you audit a WLC and then choose **Restore WCS Values**, you get the following error:

```
Udi <ipaddress>/<number>COMMON-1: Some unexpected internal error has occurred. If the problem persists, please report to the Tech Support.
```


Workaround: None at this time.
- CSCsl95415—In some cases, the Network Configuration Audit Report (Reports > Audit Report) might display blank lines in the results table.
Workaround: None at this time.
- CSCsl98668—The New Rogue AP Count report (Reports > Security Reports) might graph a bar that covers the entire chart when the selected reporting period is *the last 6 hours* and only one record is collected and graphed for that time period. However, the number that displays on the Y axis of the chart represents the accurate number of New Rogue APs records.
Workaround: None at this time.
- CSCsm00991—It takes awhile for client troubleshooting to appear.
Workaround: None at this time.
- CSCsm03250—The location appliance logs contained within the downloaded WCS logs are outdated.

Workaround: Download the logs manually from the location appliance.

- CSCsm04809—The radio utilization report shows accurate information, but the rest of the reports are skewed. The 802.11 counters and Tx power reports show information for Tx but none for Rx.

Workaround: None at this time.

- CSCsm09162—In the Monitor > Event page, if you generate a pre-coverage hole by phones in the calling state, the pre-coverage hole report shows data clients rather than voice clients.

Workaround: None at this time.

- CSCsm13536—The supported channel bandwidths are different depending on whether 20-MHz or 40-MHz range is used. The controller lists them differently for an 802.11n access point, but WCS lists them the same in both ranges.

Workaround: None at this time.

- CSCsm14363—When you create a config group and then perform an audit, the Attribute Differences page does not have a Close button.

Workaround: None at this time.

- CSCsm17395—WCS location access point rogue information is inaccurate. When looking at the rogue clients through WCS, the “APs that detected this rogue client” value is blank.

Workaround: Change the Search In value to *WCS Controllers* on the Monitor > Security > Rogue Clients page. You can also search for rogue clients directly on the controller. From those clients that result, you see detecting access points as well as the location if the rogue client was detected by a location server.

- CSCsm20294—When the primary and secondary controllers are not configured in the access point, an import fails. The following error message appears: “AP4 primaryMwar and secondaryMwar entries 10.20.10.5 Maz40 are not configured in WCS.”

Workaround: None at this time.

- CSCsm30661—If you choose all templates from a controller and then add them to the config group with Apply, the number of templates in the report does not add up to the total number of templates in the config group.

Workaround: Choose each applicable template individually to add to the config group.

- CSCsm33619—In WCS 4.2.62.0 under Monitor > Clients, the client search does not show the location server information for the client when doing a quick or new search. If you go to the maps where the client’s access point is located, the client shows on the map as *located* by the location server.

Workaround: Go to the map where the client’s access point is located.

- CSCsm35824—The restore operation fails after two consecutive restores.

Workaround: Restart the server. The restore operation is not successful for the second attempt. If you restore it again, it is successful.

- CSCsm48775—Some copy and paste errors occurred in the upgrade from 4.2 to 5.0 for the LradXxxStats table. Sometimes the wrong sequence is dropped, but the wrong sequence may also be used in migration, and the table is not getting populated.

Workaround: None at this time.

- CSCsm50334—If the template application or any other such templates for the guest users fails, the message shows up as limited. The error may occur because of a lack of DB space, but the error message needs to explain the cause.

Workaround: None at this time.

- CSCsm53129—The 1310 access point with a 2506 antenna shows an incorrect heatmap on the large outdoor map. The map may show approximately 700 feet, and the customer site survey information indicates that -50dBm extends 300 feet from the access point, but the heatmap does not reflect that.
Workaround: None at this time.
- CSCsm56708—Even if you set the Last Detected Within setting to a minimal amount (such as 15 minutes), all clients detected even many months prior appear in the Monitor > Security > Rogue Clients menu. Also, the rogue access point MAC addresses are all zeroes.
Workaround: None at this time.
- CSCsm57470—When you are adding an outdoor area to a map and change the zoom level, the newly added outdoor areas do not scale to the selected zoom level. The zoom level stays at 100%.
Workaround: After changing the zoom value, click **Place** after it scales the new area.
- CSCsm60523—The PoE status for the 1250 access point shows as *not applicable* on the Monitor > Access Points window.
Workaround: None at this time.
- CSCsm60843—The copyright information shown when logging onto WCS should show 2008.
Workaround: None at this time.
- CSCsm61279—The client throughput on the Client tab of the WCS Home page should display the traffic values in Mbps rather than Kbps.
Workaround: None at this time.
- CSCsm74066—WCS 5.0 should provide a proper error message and prevent installation when a user tries to install WCS or Navigator on a server running Red Hat Linux Enterprise Server 5.1.

If You Need More Information

If you need information about a specific caveat that does not appear in these release notes, you can use the Cisco Bug Toolkit to find caveats of any severity. Click this URL to browse to the Bug Toolkit:

<http://tools.cisco.com/Support/BugToolKit/>

(If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.)

Troubleshooting

For the most up-to-date, detailed troubleshooting information, refer to the Cisco TAC website at the following location:

<http://www.cisco.com/tac>

Click **Technology Support**, select **Wireless** from the menu on the left, and click **Wireless LAN**.

Related Documentation

For information on the Cisco Unified Wireless Network Solution and for instructions on how to configure and use the Cisco UWN, refer to the *Cisco Wireless Control System Configuration Guide* and the *Cisco Wireless LAN Controller Configuration Guide*.

Obtaining Documentation, Obtaining Support, and Security Guidelines

For information on obtaining documentation, obtaining support, providing documentation feedback, security guidelines, and also recommended aliases and general Cisco documents, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco StadiumVision, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn is a service mark; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0804R)