



## FIELD NOTICE

# ETHERNET SWITCH NETWORK MODULE RESTRICTIONS FOR DLSW+ AND DLSW+ ETHERNET REDUNDANCY

This Field Notice explains restrictions and configuration requirements for the NM-16ESW, NM-36ESW, and WIC-4ESW Ethernet Switch Modules, when both data-link switching plus (DLSw+) and IP routing are required.

## PROBLEM DESCRIPTION

The NM-16ESW, NM-36ESW, and WIC-4ESW 10/100 Fast Ethernet Switch Network Modules impose restrictions for DLSw+ and IP addressing on the same interface. They also do not support the simultaneous use of the Ethernet Redundancy feature of DLSw+ and IP addressing on the same interface.

## BACKGROUND

The NM-16ESW, NM-36ESW, and WIC-4ESW added support for bridging for Switched Virtual Interface (SVI) in Cisco IOS® Software Releases 12.2(15)ZJ and 12.3(4)T. This support requires the use of Integrated Routing and Bridging (IRB) to simultaneously bridge Logical Link Control (LLC) traffic and route IP traffic to SVI. This also precludes the simultaneous use of the Ethernet Redundancy feature of DLSw+ and IP addressing on the same interface. DLSw+ and the Ethernet Redundancy feature will operate normally, whether an IP address is configured or not, but the IP address routing will fail, when both are configured on a SVI.

## PROBLEM SYMPTOMS

The symptom is that IP communication between the router and any end systems connected to the affected VLAN will not work.

## WORKAROUND/SOLUTION

DLSw+ and IP routing can be configured to work together by using IRB. The following example shows how this might be configured.

```
Bridge irb
Dlsw local-peer peer-id 10.10.10.1
Dlsw remote-peer 0 tcp 10.20.20.1
Dlsw bridge-group 10
Dlsw bridge-group 20
Interface fastethernet 1
Switchport access-vlan 10
Interface fastethernet 2
Switchport access-vlan 20
Interface vlan 10
Bridge-group 10
Interface vlan 20
```

```

Bridge-group 20

Interface BVI 10

Ip address 10.10.10.1 255.255.255.0

Interface BVI 20

Ip address 20.20.20.1 255.255.255.0

Bridge 10 protocol ieee

Bridge 10 route ip

Bridge 20 protocol ieee

Bridge 20 route ip

```

**Note:** This notice affects the following products:

Product	Remarks
<b>NM-16ESW</b>	16-Port 10/100 Fast Ethernet Switch Module for Cisco 2600 and 3600 Series Multiservice Platforms and Cisco 3700 Multiservice Access Router
<b>NM-36ESW</b>	16-Port 10/100 Fast Ethernet Switch Module for Cisco 2600 and 3600 Series Multiservice Platforms and Cisco 3700 Series Multiservice Access Router
<b>WIC-4ESW</b>	4-Port 10/100 Fast Ethernet Switch Module for Cisco 1700 Series Modular Access Router



**Corporate Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**  
Cisco Systems International  
BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**  
Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R)

204044\_ETMG\_AE\_08.04

Printed in the USA

