




Cisco IOS Early Deployment Release 12.2(8)MC2

Introduction

This Product Bulletin describes the content and delivery information concerning Cisco IOS™ software release 12.2(8)MC2. It should be used in conjunction with Product Bulletin titles, Cisco IOS Software Release 12.2(8)T. 12.2(8)MC2 is a short-lived Early Deployment (ED) release parented to 12.2(8)T and supporting the MGX-RPM-1FE-CP back card and the MWR 1900 Mobile Wireless Router.

Migration Guide

The diagram below displays Cisco 12.2(8)MC2 release functionality relative to the 12.2T release. This diagram also identifies the recommended migration path.



New Features in 12.2(8)MC2

12.2(8)MC2 is a maintenance release for the introduction of the MWR 1900 Wireless Edge Router. The new features in this release enable T1/E1 protection switching between two MWR 1900s in a 1:1 redundant configuration; in such deployments, one MWR 1900 is the active router and the other is the standby router. The new features are:

Redundancy Logic: HSRP to determine the active/standby router and control the T1/E1 terminations on the VWIC-2MFT-T1-DIRs and VWIC-2MFT-E1-DIRs.

Failover Logic: To force a switchover under hardware failures or over temperature conditions on the active MWR 1900 router so that the active router becomes the standby router, and the standby router becomes the active router.



Relay Control: To appropriately open and close the T1/E1 interfaces on the VWIC-2MFT-T1-DIRs (or VWIC-2MFT-E1-DIRs) in the active/standby routers so that only one interface is closed at any one time (so that the T1/E1s are not double-terminated).

Diagnostic Functions: To monitor the “health” of the standby MWR 1900 router.

For more detailed information about the platforms and features being delivered in 12.2(8)MC2, please reference the following documents:

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122relnt/1fecp/122mcrn/122mc2rn/index.htm>

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122relnt/mwr1900/122mcrn/122mc2rn/index.htm>

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122newft/122limit/122mc/1228mc2/index.htm>

Support

Cisco IOS software release 12.2(8)MC2 follows the standard Cisco support policy as indicated in the following link:

<http://www.cisco.com/warp/public/437/27.html>

Product Numbers

Cisco IOS Release 12.2(8)MC2 Feature Sets, Images, and Memory Recommendations

Platform	Software Feature Set	Product Code	Image	Flash	DRAM
MGX-RPM-1FE-CP	MGX back card support	S1FEBS-12208MC2	rpm-js-mz	N/A	N/A
MWR-1900	Mobile Wireless Edge Router	SM19ER-12208MC2	mwr1900-i-mz	32MB	128MB

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11 Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco *Powered* Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0203R)