

Release Notes for Cisco CVR100W Wireless-N VPN Router Firmware Version 1.0.1.20

October 2013

These Release Notes describe the known issues in Cisco CVR100W Wireless-N VPN Router firmware version 1.0.1.20.

Known Issues

The following table lists the known issues in firmware version 1.0.1.20:

Ref Number	Description
CSCuj15809	HTTP throughput is lower than the other TCP throughput. Workaround None.
CSCtx72346	Unable to block preinstalled ActiveX applications when Block ActiveX is enabled on the unit. Workaround Manually clean up the browser cache.
CSCtx72378	The wireless guest clients that are connected to the WDS slave devices cannot access the Internet. Workaround None.
CSCue86796	IGMP Snooping cannot work when the multicast source is located at the WLAN side. Workaround None.
CSCue86814	The wireless guest clients can join the multicast group without web authentication. Workaround None.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Product Documentation	
CVR100W	www.cisco.com/go/cvr100w
Cisco Small Business	
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2013 Cisco Systems, Inc. All rights reserved. PN: OL-30579-01