



Cisco LCI Software Version 2.4.11

Release Note

Overview

Introduction

This release note supports Local Craft Interface (LCI) Release 2.4.11. This release updates the executable program as well as the devtype collection.

Purpose

This release note is being provided for user support related to the installation and operation of LCI Release 2.4.11.

Audience

This document is intended for qualified and skilled personnel who configure the system. These personnel should understand basic optics, RF, and network monitoring operations.

Qualified Personnel

Only appropriately qualified and skilled service personnel should attempt to install, operate, maintain, and service this product.



WARNING:

Allow only qualified and skilled personnel to install, operate, maintain, and service this product. Otherwise, personal injury or equipment damage may occur.

Related Publications

You may find the following publications useful as you implement the procedures in this document:

- *Cisco Prisma II Platform Installation & Configuration Guide - System Release 2.05.31*, part number OL-27999-02
- *Cisco Prisma II Platform Configuration Guide - System Release 2.05.31*, part number OL-27998-02

Document Version

This is the first version of this release note.

In This Document

■ System Requirements	3
■ Limitations, Restrictions, and Caveats.....	4
■ New Features and Important Notes.....	5
■ Bug Toolkit	6
■ Installation Instructions	7

System Requirements

LCI Release 2.4.11 has the following minimum system requirements:

- Windows PC running Windows 95, Windows XP, or Windows 7
- At least 15 megabytes free disk space
- RS-232 port

Limitations, Restrictions, and Caveats

If possible, use a true RS-232 PC port with LCI. When using a USB to RS-232 converter cable or box, be aware that some of these devices work better than others. If you experience trouble when using such a converter, try using a different brand device.

New Features and Important Notes

This section lists the new or revised devtype files included in LCI Release 2.4.11.

Note: For information about resolved and known issues with this release, see *Bug Toolkit* (on page 6).

New or Revised Devtype Files

Default Description	Filename	Type #	Version
EDR 2:1 Dual Receiver with GS7000 Node Monitoring	p2-mbdr-rx1.txt	2025	1.12
EDR 2:1 Dual Receiver with Compact Node Monitoring	p2-mbdr-rx2.txt	2026	1.16
EDR 2:1 Dual Receiver	p2-mbdr-rx3.txt	2027	1.12

Bug Toolkit

If you need information about a specific caveat that does not appear in this release note, you can use the Cisco Bug Toolkit to find caveats of any severity. Use the following URL to access the Bug Toolkit:

<http://tools.cisco.com/Support/BugToolKit/>

If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.

Installation Instructions

To Install the LCI Software

LCI is distributed as a zipped executable file (.zip) that can be downloaded from www.cisco.com.

Complete the following steps to install the LCI software:

- 1 Download the LCI installation file from www.cisco.com.
- 2 Unzip the installation file to your Windows desktop.
- 3 Double-click the unzipped (.exe) file to open the installer application.
- 4 Follow the steps of the installer to complete the installation.

Note: We recommend that you check the Cisco website periodically for updates to the LCI program as well as for new or revised devtype files.

For Information

For Information

If You Have Questions

If you have technical questions, contact Cisco Services at the following URL:

<http://www.cisco.com/web/services/>



Cisco Systems, Inc.
5030 Sugarloaf Parkway, Box 465447
Lawrenceville, GA 30042

678 277-1120
800 553-6387
www.cisco.com

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, to go this URL:

www.cisco.com/go/trademarks.

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company.

Product and service availability are subject to change without notice.

© 2013 Cisco and/or its affiliates. All rights reserved.
October 2013

Printed in United States of America
Part Number OL-30086-01