



# QAM Modulator Software Version 2.5.8 Release Note

## Overview

### Introduction

This document describes the change requests (CRs) implemented by upgrading a Model D9477 Quadrature Amplitude Modulation (QAM) Modulator to QAM software version 2.5.8.

### Audience

This document is intended for system operators or field service engineers who are responsible for installing the QAM software onto the QAM.

### Scope

This release note provides an executive overview of QAM software version 2.5.8. If you have questions about this software release or require more detailed information, call Cisco® Services at 1-866-787-3866.

### Document Version

This is the third formal release of this document. This document has been revised to provide only release note information. Instructions for installing QAM software version 2.5.8 on a QAM Modulator can now be found in *QAM Software Installation Instructions* (part number 4026030).

## Introducing QAM Software Version 2.5.8

QAM software version 2.5.8 is designed to be installed on a QAM. After the software is installed and the modulator is active, it provides additional support for sites that deploy video-on-demand (VOD), *anything*-on-demand (xOD), and other interactive broadcast services.

**Note:** For a complete description of a QAM, refer to *QAM Modulator Model D9476 Installation and Operation Guide* (part number 568251).

### System Release Compatibility and Prerequisites

QAM software version 2.5.8 can be installed on a Digital Broadband Delivery System (DBDS) that is running System Release (SR) 4.3.2 and later releases.

For a complete configuration listing, or to upgrade your system, contact Cisco Services at 1-866-787-3866.

### Applications Included in this Release

QAM software version 2.5.8 includes the following software applications:

- QAM Host Application code 2.5.8
- QAM Host Boot code 2.1.2

The *QAM Software Installation Instructions* (part number 4026030) provides instructions to obtain the code for this release from an FTP server. Follow the instructions in the section *Obtaining the QAM Software File* to download the following file: **QAM258.tar.gz**.

### Hardware Supported

QAM software version 2.5.8 supports the Model D9476 QAM.

## What's Fixed?

This section provides a description of the Change Requests (CRs) implemented in QAM software version 2.5.8. These have been implemented since QAM software version 2.5.7 was released.

### **ID CSCzp03578: QAM Platforms Produce Black Screen or Frozen Video**

**ID CSCzp03578** corrects an issue wherein customers experienced black screens or frozen video that required the user to channel away, then back to recover.

## Known Issues

# Known Issues

At the time of this release, there are no known issues.

## For Information

### **If You Have Questions**

If you have technical questions, call Cisco Services for assistance. Follow the menu options to speak with a service engineer.



Cisco Systems, Inc.  
5030 Sugarloaf Parkway, Box 465447  
Lawrenceville, GA 30042

678 277-1120  
800 722-2009  
[www.cisco.com](http://www.cisco.com)

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at **[www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks)**.

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2008, 2009, 2011 Cisco and/or its affiliates. All rights reserved.

October 2011 Printed in USA

Part Number 4025081 Rev C