



Cisco D9828 Multiple Decryption Receiver Software Version 2.62 Release Note

Overview

This document describes the resolved issues in software version 2.62 for the Cisco® D9828 Multiple Decryption Receiver (MDR). This version supersedes version 2.61, providing resolutions for several issues.

New Features

There are no new features in the Cisco D9828 Multiple Decryption Receiver software version 2.62.

Resolved Issues

The following issues are resolved in version 2.62:

ID	Description
CSCtx57523	DPI messages that require authorization are dropped.
Issue	Ad Tier messages associated with DPI events are not transmitted.
CSCty17425	LEC prioritized above Disaster Recovery when both are signaled.
Issue	When both LEC and Disaster Recovery are signaled in a system, LEC is prioritized above Disaster Recovery by the D9828 receiver.

For Information

If You Have Questions

If you have technical questions, call Cisco Services for assistance. Follow the menu options to speak with a service engineer.



Cisco Systems, Inc.
5030 Sugarloaf Parkway, Box 465447
Lawrenceville, GA 30042

678 277-1120
800 722-2009
www.cisco.com

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks.

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2011-2012 Cisco and/or its affiliates. All rights reserved.

May 2012 Printed in USA

Part Number 4041509 Rev B