

Cisco Inband Control Computer (IBCC) Software Version 2.41 Release Note

Overview

This document describes the changes included in software release version 2.41(R02.41) for the Cisco® Inband Control Computer (IBCC), since the previous version (R02.40).

Updates

The following updates are included in this release.

- 1 The IBCC validates user settings for bitrates in the Edit PSI/SI Settings dialog and permits saving changes only if bitrates result in less than 90% utilization.
- A pop-up warning was added to alert the IBCC user to possible ASI output problems detected by the IBCC application. The pop-up enables the customer to choose between the following actions:
 - restart the ASI output drivers (recommended)
 - ignore the condition and continue without interruption

Note: This update is a workaround for the "Group Change Problem."

For Information

Cisco provides its customers who have purchased support agreements with telephone support from anywhere in the world. If you require technical telephone assistance or product training support, or if you have any questions concerning the Cisco product, you may contact the appropriate Customer Support Center from those listed below. Charges may apply for customers without a current and applicable product support agreement.

Customers	Location	Phone Number
Programmers and Broadcasters	USA and Canada	Toll-Free: 1.888.949.4786 +1.770.236.4786 dmn_support@cisco.com
Telcos and Cable Service Providers	Cisco Services	Toll-Free: 1.800.722.2009 Local: 770.236.6900 (press 2 at the prompt) customer-service@cisco.com
All Customers	Europe	+32.56.445.155 or +32.56.445.197 saemea-support@cisco.com
All Customers	Asia	+852.2588.4746 saapac-support@cisco.com

Customers who call a Customer Support Center are asked specific questions in order to identify their needs. In this way, each call can be directed to the customer support representative most experienced with their Cisco product.



Cisco Systems, Inc. 5030 Sugarloaf Parkway, Box 465447 Lawrenceville, GA 30042 678 277-1120 800 722-2009 www.cisco.com

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at **www.cisco.com/go/trademarks**.

Third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2011 Cisco and/or its affiliates. All rights reserved.

August 2011

Part Number

7023099 Rev A