

End-of-Sale and End-of-Life Announcement for the Cisco 1-Port ADSL-over-POTS and ADSL-over-ISDN WAN Interface Cards with Dying Gasp

EOL6184

Cisco[®] announces the end-of-sale and end-of life dates for the Cisco 1-Port ADSL-over-POTS and ADSL-over-ISDN WAN Interface Cards with Dying Gasp. The last day to order the affected product(s) is May 30, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco 1-Port ADSL-over-POTS and ADSL-over-ISDN WAN Interface Cards with Dying Gasp

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 30, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 30, 2008
Last Ship Date: HW, OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 28, 2008
End of SW Maintenance Releases Date: OS SW		
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	May 30, 2009
End of New Service Attachment Date: HW, OS SW		
End of Service Contract Renewal Date: HW, OS SW		August 25, 2012
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 29, 2013

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
WIC-1ADSL-DG	1-port ADSLoPOTS WIC with Dying Gasp	HWIC-1ADSL	1-port ADSLoPOTS HWIC
WIC-1ADSL-DG=	1-port ADSLoPOTS WIC w/Dying Gasp	HWIC-1ADSL=	1-port ADSLoPOTS HWIC

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
WIC-1ADSL-I-DG	1-port ADSLoISDN Wan Interface Card	HWIC-1ADSLI	1-port ADSLoISDN HWIC
WIC-1ADSL-I-DG=	1-port ADSLoISDN Wan Interface Card	HWIC-1ADSLI=	1-port ADSLoISDN HWIC
CISCO1841-ADSL-DG	1841 ADSLoPOTS w/dying gasp Bdle,IP Broadband,32FL/128DR	CISCO1841-ADSL2	1841 bundle, HWIC-1ADSL, IP BB, 32F/128D
CISCO1841-ADSLI	1841 ADSLoISDN Bdle,IP Broadband, 32FL/128DR	CISCO1841-ADSL2-I	1841 ADSLoISDN bdle, HWIC- 1ADSLI, IP Base, 64F/192D

Product Migration Options

Customers are encouraged to migrate to the Cisco ADSL2 and ADSL2+ High-Speed WAN Interface cards. Information about this product can be found at http://www.cisco.com/en/US/products/ps5853/products data sheet0900aecd80394b7e.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to http://www.cisco.com/go/tradein/. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to http://cisco.com/go/remarketing.

For More Information

For more information about the Cisco ADSL2 and ADSL2+ High-Speed WAN Interface cards, visit http://www.cisco.com/en/US/products/ps5853/products data sheet0900aecd80394b7e.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod end of life.html.

To subscribe to receive end-of-life/end-of-sale information, go to http://www.cisco.com/cgibin/Support/FieldNoticeTool/field-notice.



Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 527-0883 Asia Pacific Headquarters Cisco Systems, Inc. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

@2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.: Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.: and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitt, Chapter, Feat Steep, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, Cisco Verseard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0708R)

Printed in USA C51-438814-00 10/07