

Smoked Dome for the Cisco Video Surveillance 2421 May Affect Camera's Focus

In certain conditions, the refractive index and curvature of the smoked dome for the Cisco[®] Video Surveillance 2421 IP Dome Cameras may slightly change the focus of the lens when installed over the lens.

Products Affected

Part Number	Description
CIVS-IPC-2421	Indoor Dome, Smoked, Lens 2.8–10 mm

Problem Description

Camera focus without the dome present is sharp and clear. When the smoked dome is fitted over the camera to obfuscate the lens position, the image loses some sharpness and becomes noticeably softer. This problem is not seen when the smoked dome is removed.

Workaround/Solution

Adjustments for both focus and focal length of the lens should be done with the smoked dome positioned in front of the lens. Remove the smoked dome and hold it in front of the lens while making adjustments. If the tether on the attached smoked dome is too short and prevents it from being positioned in front of the lens, a spare smoked dome should be used instead.

Part Number	Description
CIVS-IPCA-1002=	Dome, Smoked, 2400 Series

The following table provides a bug ID link that you can follow to see detailed bug information. To see the information, you must be a <u>registered</u> user and you must be logged in.

DDTS	Description
	CIVS-IPC-2421—Flush mount with smoked bubble dome—hard to focus

For More Information

If you require further assistance, or if you have any questions regarding this field notice, please contact the <u>Cisco</u> <u>Technical Assistance Center (TAC)</u> by one of the following methods:

- Open a service request on Cisco.com
- By email
- By telephone



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, CCSI, Cisco Eos, Cisco Explorer, Cisco HealthPresence, Cisco IronPort, the Cisco logo, Cisco Nurse Connect, Cisco Pulse, Cisco SensorBase, Cisco StackPower, Cisco Stadum/Vision, Cisco TelePresence, Cisco TrustSec, Cisco Unified Computing System, Cisco WebEx, DCE, Flip Channels, Flip for Good, Flip Mino, Flipshare (Design), Flip Ultra, Flip Video, Flip Video (Design), Instant Broadband, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn, Cisco Capital, Cisco Capital (Design), Cisco-Financed (Stylized), Cisco Store, Flip Gift Card, and One Million Acts of Green are service marks; and Access Registrar, Aironet, AllTouch, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIP, CCIP, CCNP, CCPP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Lumin, Cisco Nexus, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Continuum, EtherFast, EtherSwitch, Event Center, Explorer, Follow Me Browsing, GainMaker, ILYNX, IOS, IPhone, IronPort, the IronPort logo, Laser Link, LightStream, Linksys, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, PCNow, PIX, PowerKEY, PowerPanels, PowerTV, PowerTV (Design), PowerVu, Prisma, ProConnect, ROSA, SenderBase, SMARTnet, Spectrum Expert, StackWise, WebEx, and the WebEx logo are registered trademarks of Cisco and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1002R)

Printed in USA

C25-600771-00 04/10