



End-of-Sale and End-of-Life Announcement for the Tandberg Classic 6000 32

EOL7856

Cisco announces the end-of-sale and end-of-life dates for the Tandberg Classic 6000 32. The last day to order the affected product(s) is January 1, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Tandberg Classic 6000 32

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 3, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 1, 2006
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 1, 2006
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 1, 2007
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 1, 2007
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 29, 2010
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2010

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-6000-CTN-K9=	113650N TANDBERG 6000 MXP NTSC	There is currently no replacement product available for this product.		
CTS-6000-CTP-K9=	113650P TANDBERG 6000 MXP PAL	There is currently no replacement product available for this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-CAB-112848=	112848 Composite video cable Video o	There is currently no replacement product available for this product.		
CTS-PLUG-113437=	113437 DVI-I to DVI-I, male/female 1m	There is currently no replacement product available for this product.		
CTS-T6-11365011N	B11365011N T6000 MXP - Single 32, NTSC	CTS-P52MXP-K9	Profile 52 w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B11365012N	B11365012N T6000 MXP - Single 34 XGA, NTSC	CTS-P52MXP-K9	Profile 52 w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B11365012P	B11365012P T6000 MXP - Single 34 XGA, PAL	CTS-P52MXP-K9	Profile 52 w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B11365021N	B11365021N T6000 MXP - Dual 32, NTSC	CTS-P52DMXP-K9	Profile 52 Dual w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B11365021P	B11365021P T6000 MXP - Dual 32, PAL	CTS-P52DMXP-K9	Profile 52 Dual w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B11365022N	B11365022N T6000 MXP - Dual 34 XGA, NTSC	CTS-P52DMXP-K9	Profile 52 Dual w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B11365022P	B11365022P T6000 MXP - Dual 34 XGA, PAL	CTS-P52DMXP-K9	Profile 52 Dual w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-T6-B113650PT6P	B113650PT6P T6000 MXP - Dual 34 XGA	CTS-P52DMXP-K9	Profile 52 Dual w 6000 MXP - PHD cam 7x, Rmt Cntrl, 3 Mics	-
CTS-TAAM-112744=	112744 Tandberg 33 inch Monitor PAL	There is currently no replacement product available for this product.		
CTS-TAAM-112745=	112745 34 inch XGA Monitor P/N	There is currently no replacement product available for this product.		
CTS-TAAM-112748=	112748 TANDBERG 29 inch XGA Monitor	There is currently no replacement product available for this product.		
CTS-TAAM-114396=	114396 34 inch XGA CRT Monitor	There is currently no replacement product available for this product.		

Product Migration Options

Customers are encouraged to migrate to the Cisco TelePresence System Profile 52-inch MXP or 52-inch MXP Dual. Information about these products can be found at:

<http://www.cisco.com/en/US/products/ps11420/index.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Tandberg Classic 6000 32 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco TelePresence System Profile 52-inch MXP or 52-inch MXP Dual, visit <http://www.cisco.com/en/US/products/ps11420/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)