cisco.

Software Activation and Return Merchandise Authorization for the Cisco Catalyst 3750-E and 3560-E Series Switches

Cisco[®] Catalyst[®] 3750-E Series Switches and Cisco Catalyst 3560-E Series Switches are enabled with Cisco IOS[®] Software activation. This means there is an electronic license that confers certain entitlement to the product owner and enables select Cisco IOS Software functionality within the switch. If one of these switches is returned to Cisco for replacement using the return merchandise authorization (RMA) process, some electronic license types require a process to transfer them from the returned switch to the new replacement switch.

Three license types are available for use in software activation with these switches: IP Base, IP Services, and Advanced IP Services. Depending on the type (product ID) of the returned switch, replacement from Cisco will come with the same type of feature license (either IP Base or IP Services). For switches upgraded to IP Services or Advanced IP Services in the field, the license must be transferred from the returned switch to the replacement switch. In other scenarios, license transfer is not necessary because the replacement switch comes with required feature licenses.

The transfer is performed by obtaining an RMA replacement license from Cisco and installing it on the replacement switch. Note that this replacement license can be generated for any available spare switch so long as it has the same product ID; it is not required to be generated and installed on the replacement switch sent from Cisco in the RMA transaction.

Obtaining a Replacement RMA License

An RMA replacement license can be obtained using the Cisco license portal on Cisco.com (<u>http://www.cisco.com/go/license</u>).Select the "Register for an RMA License" hyperlink to access the RMA license transfer tool (Figure 1).



Figure 1. Cisco License Portal

Four pieces of information must be gathered before initiating the license transfer: the product identifier (PID) of the returned switch, the serial number of the returned switch, the PID of the replacement switch, and the serial number of the replacement switch. The required information is entered into the Web tool (Figures 2 and 3). For switches returned under the 90-day hardware warranty and not covered by a Cisco service contract, contact the Cisco Technical Assistance Center (TAC) for assistance.

The PID and serial number are printed on a label on the back side of every switch. In addition, this information can be accessed electronically through Simple Network Management Protocol (SNMP) and the Cisco IOS Software command line (using show license UDI command). Cisco recommends recording this information when the switch is first received and storing it in a safe location. If the required information (PID, serial number, or contract number) is not available, contact the TAC for assistance.

Figure 2. Information for Returned Switch

License Administration Po		ernet Explorer p	rovided by Ci	sco Systems, Inc.		Ŀ		
	ools <u>H</u> elp		-				1	
🌀 Back 🔹 🐑 🐇 👔	💈 🏠 🔎 Search	Ravorites	🕝 🖉 🎙	🎍 🗷 • 🔜 🏭 🦓				
Address 🕘 https://tools.cisco.com	/SWIFT/Licensing/Licens	eAdminServlet/rmaL	censeTransfer			💌 🋃 Go	R	
Y! · @·		Search Web 🔹	Ø 📑• 🖷•	🛛 📮 My Web 🔹 🔯 Answer	s 🔹 🖂 Mail 🔹 🍿 Movies 🔹	🐚 News 🔹 🚳 My Yahoo! 🔹 Si	ign in 👻	
License Administration Portal	+ Add Tab						×	
Google G-IEEE 802.1af	🔽 Go 🐗 🍏 🗧	🏅 🕶 RS 🕶 🧐 🔹	- 🏠 Bookmar	ks 👻 🔯 29 blocked 🛛 🦑 Chee	k 👻 🔨 AutoLink 👻 🔚 Auto	Fili 👍 Send to 🗸 🌛 🌺 🥥 S	5ettings v	
Solutions Produ	cts & Services	Ordering	Support	Training & Events	Partner Central		^	
HOME Product License Registration		License R	egistratio	on			_	
	RMA License Transfer	2 Validate Feature	s) [©] Li	esignate censee 3ubmit	and	Toolkit: Roll over tools below Feedback Help		
	Use this page to tra (RMA) process.	ansfer a license fron	n a faulty device to	a replacement device during th	e Return Material Authorization	Related Tools		
	A * denotes a requ	iired field				Dynamic Configuration Tool TAC Service Request Tool		
	Return Material	Authorization Num	ber:			TAC Service Request Tour		
	Faulty Device UDI Product ID: *							
	Faulty Device UD	l Serial Number: *						
			r	leter	Refresh			
				urity purposes, please enter the ple viewing the word, click on Re				
							~	
Done						S Local intranet		

Figure 3. Information for New Replacement Switch and License Recipient(s)

aluto							Worldwide [change]	Logged In Profile About Cisco	
CISCO							Search	Go	
Solutions	Product	s & Services	Ordering	Support	Training & E	vents	Partner Central		
HOME Product License Registration	Support Product License Registration								
		RMA License Transfer	O Validate Features	3 Desi		Review and Submit	>	Toolkit: Roll overtool s below	
		A " * " denotes a required field Your sent 1					RMA License Key Your MMA License Key will be sent via email within 24hours to he enail address.	Esedback Help Related Tools Dynamic Confranction Tool TAC Service Request Tool	
		Enter the UDI (Unique D UDE* End Veer Agreement	PID:	SN	2	dilter Licente	Agreement		
		Registrant Informatio		, , , , ,					
		Enter one value at a time	e including dashe	es and capitalization					
		Job Title:		- Last -					
		Company Name:*							
		Company Addreaa:*	Street.*						

After the required information has been entered, one or more e-mail addresses can be specified to receive an electronic copy of the license. In addition, upon successful completion of this process, the license can be directly downloaded without waiting for the e-mail to arrive (Figure 4). The license must then be installed using either the switch's command-line interface or the Cisco License Manager.



Figure 4. Success Screen with Link to Download New License File

In summary, license transfer needs to be performed for returned switches if they were upgraded to IP Services or Advanced IP Services in the field. A replacement license can be obtained from the Cisco license portal and installed on the replacement switch.



Americas Headquarters Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 527-0883 Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. 168 Robinson Road #28-01 Capital Tower Singapore 068912 www.cisco.com Tel: +65 6317 7777 Fax: +65 6317 7779 Europe Headquarters Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: +31 0 800 020 0791 Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.: Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.: and Access Registrar. Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Capital, the Cisco Systems, Inc.: and Access Registrar. Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Capital, the Cisco Systems, Cisco Systems, Cisco Systems, Inc.: and Access Registrar. Aironet, BPX, Catalyst, CDA, CCNP, CCIE, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems, Cisco Systems, Cisco Systems, Inc.: and Access Registrar. Aironet, BPX, Catalyst, CDA, CCNP, CCIE, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco Internet, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, IQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0710R)

Printed in USA

C11-399809-01 10/07