Software advisory notice

Dear Cisco Customer,

Cisco engineering has identified a software issue with the release you have selected. This issue may affect your use of this software. Please review the advisory notice below to determine if the issue applies to your environment. Customers are urged to upgrade to the recommended solution image or most current software version.

For more comprehensive information about what is included in this software, please refer to the *Cisco TelePresence TC Software Release Notes (TC6)*.

Affected software and replacement solution

Software type	Software affected	Software solution	
	Version	Version	Availability (dd/mm/yyyy)
TC	6.1.0	6.1.1	07/05/2013

Reason for Advisory:

CDETS No: CSCug56483 affecting Cisco TelePresence MX series

Headline:

Camera pre-sets do not work in TC6.1.0 for MX series

Description:

Camera pre-sets are not returning to the saved location on MX series. Instead, the camera moves to the privacy position. Other TelePresence endpoints do not have this issue and can be safely used with TC6.1.0. This bug has been fixed in TC6.1.1, which was released on Cisco. com May 7th 2013.