SLM2024/SLM2048   Firmware Release Note

Software version 1.0.1 07/09/2007
Boot version 1.0.4   01/04/2007

Known Issues
==============================
1. Setup --> Network Settings
(a) The Management VLAN must be set to 1 (the default VLAN) if the system IP
address is set to the default IP address(192.168.1.254.) Otherwise, one will not
be able to access the system.
(b) The Default Gateway cannot be configured if the system IP address is set to
the default IP address,192.168.1.254.
Recommended Workaround: Before configuring management VLAN and default gateway,
One should change the system IP address and not use the default IP address.

2. Admin --> Save Configuration
Dowloading a large configuration file (greater than 16Kbyte) will fail when
using HTTP download.
Recommended Workaround: Use TFTP to download a large configuration file.

3. Web browser availability
The web management interface is best viewed using Internet Explorer 5.5 and up,
with a resolution of 1024 x 768. In the current software version, certain pages
cannot be viewed well using other browsers. It is recommended to apply the
following workarounds.
Note: Internet Explorer web browser must be installed prior to running the
following procedures.

-Using Mozilla Firefox Web Browser:
(a) Install Firefox "IE Tab" add-ons. The latest version is available at
https://addons.mozilla.org/firefox/1419/
(b) Select Tools --> IE Tab. Add in the IP address of switches to Sites Filters
    (e.g. "http://172.18.1.27"   accepts wildcard http://172.18.1.*).
(c) Ensure that cookies are enabled, by clicking "enable" for "All sites to set
cookies" under Tools -> Options -> Privacy -> Cookies.

-Using Netscape Web Browser: Click the icon in the left corner, and select "IE
Display"