Field Notice:
for M-CARD PKM 800/1/2/3

Purpose

This document notifies all MSOs that Multi-Stream CableCARD^{TM} and PKM PowerKEY model 800/1/2/3 will be shipped from the factory with OS 1.5.2.3001 code and not OS 1.5.2.1401 code.

Affected CableCARD Hosts

The contents of this Field Notice applies to the following CableCARD hosts:
- 82XX HDC
- 42XX HDC
- 85XX HDC
- 86XX HDC
- 46XX HDC
- 16XX HDC
- 87XX HDC
- 47XX HDC
- 8300 HDC
- RNG200N
- RNG150N
- RNG100

Audience

This document is intended for all MSO system operators and system administrators.

Document Version

This is the first formal release of this document.

For More Information

If you have additional technical questions, call Cisco Services at 770 236-2200 or 866 787-3866 for assistance. Follow the menu options to speak with a service engineer.

Open Source GNU GPL Statement

Cisco set-top boxes contain(s), in part, certain free/open source software ("Free Software") under licenses which generally made the source code available for free copy, modification, and redistribution. Examples of such licenses include all the licenses sponsored by the Free Software Foundation (e.g. GNU General Public License (GPL), GNU Lesser General Public License (LGPL), Berkeley Software Distribution (BSD), the MIT licenses and different versions of the Mozilla and Apache licenses). To find additional information regarding the Free Software, including a copy of the applicable license and related information, please go to: for North America **http://www.cisco.com/web/consumer/support/ open_source.html**. Once at the site, search for the product listing and click on the related items identified. If you have any questions or problems accessing any of the links, please contact: **spvtg-external-opensource-request@cisco.com**.