![Cisco Systems logo]

Product Bulletin No. EOL4004

End-of-Sale and End-of-Life Announcement for the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.0

Cisco Systems[©] announces the end-of-sale and end-of life dates for the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.0. The last day to order the affected product is September 6, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until September 5, 2009. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series release 4.0 customers are encouraged to migrate to Cisco the Service Manager Series release 4.1. The replacement products offer many new features and improvements over past releases. These details are listed in individual data sheets, available at http://www.cisco.com/go/mwc-cmx. Table 3 provides relevant information for migrating to the replacement product.

Table 1.   End-of-Life Milestones and Dates for the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.0.

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 8, 2006
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 6, 2006
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 5, 2006
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	September 6, 2007
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 6, 2007
End of service contract renewal date	The last date to extend or renew a service contract for the product.	December 2, 2008
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 5, 2009

Table 2.   Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
MWCX-CSGSM-4.0	Cisco CSG Service Manager 4.0, Solaris	MWCX-CSG-4.1-BASE	Software License for CSG SM 4.1. 1 License per Sol Server
MWCX-CSGSM-4.0	Cisco CSG Service Manager 4.0, Solaris	MWCX-CSG-4.1-RTU	CSG SM 4.1 RTU. 1 License per CSG 6.x or 7.x new license

MWCX-CSGSM-4.0	Cisco CSG Service Manager 4.0, Solaris	MWCX-CSUP-4.1-RTU	CSG SM 4.1 RTU. 1 License per CSG R7.x UPGRADE Lic from R6.x
MWCX-CSGSM4.0-UP	CW4MW 3.0 or MWC 2.0 to CSG SM 4.0, Solaris	MWCX-CSG-4.1-BASE	Software License for CSG SM 4.1. 1 License per Sol Server
MWCX-CSGSM4.0-UP	CW4MW 3.0 or MWC 2.0 to CSG SM 4.0, Solaris	MWCX-CSG-4.1-RTU	CSG SM 4.1 RTU. 1 License per CSG 6.x or 7.x new license
MWCX-CSGSM4.0-UP	CW4MW 3.0 or MWC 2.0 to CSG SM 4.0, Solaris	MWCX-CSUP-4.1-RTU	CSG SM 4.1 RTU. 1 License per CSG R7.x UPGRADE Lic from R6.x
MWCX-GGSN-4.0	Cisco GGSN Service Manager 4.0, Solaris	MWCX-GGS-4.1-BASE	Software License for GGSN SM 4.1. 1 License per Sol Server
MWCX-GGSN-4.0	Cisco GGSN Service Manager 4.0, Solaris	MWCX-GGSN-4.1-RTU	GGSN SM 4.1 RTU. 1 Lic per MWAM card GGSN 5.x/6.x
MWCX-GGSN-4.0	Cisco GGSN Service Manager 4.0, Solaris	MWCX-GGUP-4.1-RTU	GGSN SM 4.1 RTU. 1 Lic per MWAM card GGSN 6.x UPG from 5.x
MWCX-GGSN4.0-UP	CW4MW 3.0 or MWC 2.0 to GGSN-SM 4.0, Solaris	MWCX-GGS-4.1-BASE	Software License for GGSN SM 4.1. 1 License per Sol Server
MWCX-GGSN4.0-UP	CW4MW 3.0 or MWC 2.0 to GGSN-SM 4.0, Solaris	MWCX-GGSN-4.1-RTU	GGSN SM 4.1 RTU. 1 Lic per MWAM card GGSN 5.x/6.x
MWCX-GGSN4.0-UP	CW4MW 3.0 or MWC 2.0 to GGSN-SM 4.0, Solaris	MWCX-GGUP-4.1-RTU	GGSN SM 4.1 RTU. 1 Lic per MWAM card GGSN 6.x UPG from 5.x
MWCX-HA-4.0	Cisco HA Service Manager 4.0, Solaris	MWCX-HA-4.1-BASE	Software License for HA SM 4.1. 1 License per Sol Server
MWCX-HA-4.0	Cisco HA Service Manager 4.0, Solaris	MWCX-HA-4.1-RTU	HA SM 4.1 RTU. 1 Lic per MWAM card or 5 7206 HA 3.x
MWCX-HA-4.0	Cisco HA Service Manager 4.0, Solaris	MWCX-HAUP-4.1-RTU	HA SM 4.1 RTU. Lic per MWAM or 5 7206 HA 3.x UPG from 2.x
MWCX-HA4.0-UP	CW4MW 3.0, MWC 2.0 or MWC CMX to HA-SM 4.0, Solaris	MWCX-HA-4.1-BASE	Software License for HA SM 4.1. 1 License per Sol Server
MWCX-HA4.0-UP	CW4MW 3.0, MWC 2.0 or MWC CMX to HA-SM 4.0, Solaris	MWCX-HA-4.1-RTU	HA SM 4.1 RTU. 1 Lic per MWAM card or 5 7206 HA 3.x
MWCX-HA4.0-UP	CW4MW 3.0, MWC 2.0 or MWC CMX to HA-SM 4.0, Solaris	MWCX-HAUP-4.1-RTU	HA SM 4.1 RTU. Lic per MWAM or 5 7206 HA 3.x UPG from 2.x
MWCX-PDSN-4.0	Cisco PDSN Service Manager 4.0, Solaris	MWCX-PDS-4.1-BASE	Software License for PDSN SM 4.1. 1 License per Sol Server
MWCX-PDSN-4.0	Cisco PDSN Service Manager 4.0, Solaris	MWCX-PDSN-4.1-RTU	PDSN SM 4.1 RTU. 1 Lic per MWAM card or 5 7206 PDSN 3.x

MWCX-PDSN-4.0	Cisco PDSN Service Manager 4.0, Solaris	MWCX-PDUP-4.1-RTU	PDSN SM 4.1 RTU. Lic per MWAM or 5 72x PDSN 3.x UPG from 2.x
MWCX-PDSN4.0-UP	CW4MW 3.0, MWC 2.0 or MWC CMX to PDSN-SM 4.0, Solaris	MWCX-PDS-4.1-BASE	Software License for PDSN SM 4.1. 1 License per Sol Server
MWCX-PDSN4.0-UP	CW4MW 3.0, MWC 2.0 or MWC CMX to PDSN-SM 4.0, Solaris	MWCX-PDSN-4.1-RTU	PDSN SM 4.1 RTU. 1 Lic per MWAM card or 5 7206 PDSN 3.x
MWCX-PDSN4.0-UP	CW4MW 3.0, MWC 2.0 or MWC CMX to PDSN-SM 4.0, Solaris	MWCX-PDUP-4.1-RTU	PDSN SM 4.1 RTU. Lic per MWAM or 5 72x PDSN 3.x UPG from 2.x

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.0 is the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.1.

Customers are encouraged to migrate to the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.1. Information about this product can be found at: http://www.cisco.com/go/mwc-cmx.

FOR MORE INFORMATION

For more information about the Cisco Mobile Wireless Center for Cisco Mobile Exchange Service Manager Series 4.0, visit http://www.cisco.com/en/US/products/ps6401/prod_eol_notices_list.html or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice.

CISCO SYSTEMS

C51-338171-00 03/06