# End-of-Sale and End-of-Life Announcement for the Cisco IPICS CIS-7825-H2-K9 & CIS-7845-H2-K9 bundles for Cisco IPICS1.0

EOL5454

Cisco Systems® announces the end-of-sale and end-of life dates for the CIS-7825-H2-K9 & CIS-7845-H2-K9 bundles. The last day to order the CIS-7825-H2-K9 & CIS-7845-H2-K9 is February 08, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the CIS Bundles. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the separate hardware and software part numbers, MCS-7845-H2-S31 & CIS-IPICS-K9 respectively. Information about the replacement product can be found at:

MCS-7845-H2-S31: http://www.cisco.com/en/US/products/ps6867/index.html

MCS-7825-H2-S31: http://www.cisco.com/en/US/products/ps6863/index.html

CIS-IPICS-K9:
http://www.cisco.com/en/US/prod/collateral/ps6712/ps6718/product_data_sheet0900aecd8034fd94.html

**Table 1.**    End-of-Life Milestones and Dates for CIS-7825-H2-K9 & CIS-7845-H2-K9 bundles

| Milestone | Definition | Date |
|---|---|---|
| **End-of-Life Announcement Date** | The date the document that announces the end of sale and end of life of a product is distributed to the general public. | December 04, 2006 |
| **End-of-Sale Date** | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | February 08, 2007 |
| **Last Ship Date:** | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | June 03, 2007 |

**Table 2.**    Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description |
|---|---|---|---|
| **CIS-7845-H2-K9** | Cisco IPICS Server SW w/MCS 7845H2, 4 channels, 4 PMCs, 10 IP phone license | CIS-IPICS-K9 (SW only) with MCS-7845-H2-S31 (HW only) | Cisco IPICS Server SW, 4 channels, 4 PMCs, 10 IP phone license. No MCS Hardware included. |
| **CIS-7825-H2-K9** | Cisco IPICS Server SW w/MCS 7825H2, 4 channels, 4 PMCs, 10 IP phone license | CIS-IPICS-K9 (SW only) with MCS-7825-H2-S31 (HW only) | Cisco IPICS Server SW, 4 channels, 4 PMCs, 10 IP phone license. No MCS Hardware included. |

## Product Migration Options

Information about the replacement product can be found at:
http://www.cisco.com/en/US/products/hw/voiceapp/ps378/index.html.

## For More Information

For more information about the Cisco CIS-IPICS-K9 Cisco IPICS Server SW w/MCS 7845H2 or MCS 7825H2, visit http://www.cisco.com/en/US/products/ps6712/index.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:
http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:
http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice

**Americas Headquarters**
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

**Asia Pacific Headquarters**
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

**Europe Headquarters**
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at **www.cisco.com/go/offices.**