END-OF-LIFE NOTICE, NO. 2362

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 7505 CHASSIS

Cisco Systems® announces the end of life of the Cisco® 7505 Series Router chassis. Note: This end-of-life announcement does not affect the Cisco 7507 (CHAS-7507) *, 7513 (CHAS-7513)* chassis and their associated bundles. The Cisco 7507 and 7513 will remain orderable. The last day to order the Cisco 7505 is June 30, 2004. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until June 30, 2009. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco 7505. Table 2 lists the part numbers for affected products.

Customers are encouraged to migrate to Cisco 7200 VXR Series Router or Cisco 7304 Series Router. The Cisco 7200 VXR and Cisco 7304 Series help protect investments. Port adapters on the Cisco 7500 may be used on the Cisco 7200 VXR and Cisco 7304 Series.

* April 12, 2005- Added the product Identification for clarification

Table 1. End-of-Life Milestones and Dates for the Cisco 7505 Chassis

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 31, 2003
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 30, 2004
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 31, 2004
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 30, 2005
End of routine failure analysis date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	June 30, 2005
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 30, 2005
End of service contract renewal date	The last date to extend or renew a service contract for the product.	March 30, 2009
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 30, 2009

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
CISCO7505/4	Cisco 7505 5-Slot, 1 CyBus, 1RSP4, Single Power Supply
CHAS-7505	7505 Chassis and AC Power
CHAS-7505=	Cisco 7505 Chassis and AC Power Supply
CHAS-7505-DC	Cisco 7505 DC Power Supply
CHAS-7505-DC=	Cisco 7505 Chassis and DC Power Supply
PWR/5-DC=	Cisco 7010/7505 DC Power Supply (Spare)

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

End-of-Sale Product Part Number	Product Description
PWR/5-AC=	Cisco 7010/7505 AC Power Supply, U.S.
PWR/5-ACA=	Cisco 7010/7505 AC Power Supply, Australia
PWR/5-ACE=	Cisco 7010/7505 AC Power Supply, Europe
PWR/5-ACI=	Cisco 7010/7505 AC Power Supply, Italy
PWR/5-ACU=	Cisco 7010/7505 AC Power Supply, UK
MAS/5-FAN=	Cisco 7010/7505 Blower Assembly (Spare)
ACS/5-RMK=	Cisco 7010/7505 Rack-Mount Kit (Spare)
ACS/5-CBLM=	Cisco 7010/7505 Cable Management Bracket (Spare)
PKG/5=	Cisco 7010/7505 Spare System Packaging Material

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco 7505 is the Cisco 7200 VXR Series or Cisco 7304 Series routers.

For more information about the Cisco 7200 VXR, visit: http://www.cisco.com/en/US/products/hw/routers/ps341/index.html.

For more information about the Cisco 7304, visit: http://www.cisco.com/en/US/products/hw/routers/ps352/index.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: http://www.cisco.com/go/tradein/.

The Cisco TMP application requires all users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive EOL/EOS information, please go to: http://www.cisco.com/pcgi-bin/Support/FieldNoticeTool/field-notice.

Cisco Systems, Inc.
All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R)

Pa/LW8278 04/05

Printed in USA

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.