# End-of-Sale and End-of-Life Announcement for the Model 6940/6942/6944 Node Accessories

EOL7483 - Amended

Cisco announces the end-of-sale and end-of life dates for the Model 6940/6942/6944 Node Accessories. The last day to order the affected product(s) is October 14, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.**   End-of-Life Milestones and Dates for the Model 6940/6942/6944 Node Accessories

| Milestone | Definition | Date |
|---|---|---|
| **End-of-Life Announcement Date** | The date the document that announces the end of sale and end of life of a product is distributed to the general public. | April 15, 2011 |
| **End-of-Sale Date** | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | October 14, 2011 |
| **Last Ship Date:** **HW** | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | January 12, 2012 |
| **End of Routine Failure Analysis Date:** **HW** | The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect. | October 13, 2012 |
| **End of New Service Attachment Date:** **HW** | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | October 13, 2012 |
| **End of Service Contract Renewal Date:** **HW** | The last date to extend or renew a service contract for the product. | January 9, 2016 |
| **Last Date of Support:** **HW** | The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete. | October 31, 2016 |

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

**Table 2.**   Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 4004094 | 6940/42/44 Std Chromate Hsg,2/AC,RF Entry Bds | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4005176 | 6944 Fwd 2:2 Router Module | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4005540 | 6942/44 8p Opt Intfc Module (OIB) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4006451 | 6940 6p OIB,2/AC Kit (w/bracket) | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 4006452 | 6944 6p OIB,2/AC Kit (w/bracket) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4006453 | 6944 8p OIB,2/AC Kit (w/bracket) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4006750 | ASSY,6940L 870MHZ LAUNCH AMP 65/86 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4007717 | 69XX Crowbar for 6940/6942/6944 Nodes (Pkg/10) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 4007718 | 69XX Pwr Director Kit (Pkg/20) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 565238 | Pad,PP-7.5dB (Mult=5) | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590902 | Pwr Supply,40-90VAC | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590905 | 6940 Launch Amp Assy,870MHz,42/54 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590920 | 6940/6944/GM Node 1310/1550nm Rx,870MHz,FA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590922 | 6940/6944/GM Node 1310/1550nm Rx,870MHz,SA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590923 | 6940/6944/GM Node 1310/1550nm Rx,870MHz,SP | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590924 | 6940/6944/GM Node 1310/1550nm HG Rx,870MHz,FA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590926 | 6940/6944 Node 1310/1550nm HG Rx,870MHz,SA | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590927 | 6940/6944 Node 1310/1550nm HG Rx,870MHz,SP | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590945 | 6940 6p Intfc Module,Red-rdy | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590954 | 6940 Fwd Red Cntrl Module | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 590955 | 6940 Status Monitor Signal Director | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590956 | Bridger Switch,On/Off/-6dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590960 | SMB/SMB Coax Jmpr | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590961 | SMB/F Coax Jmpr Test Cbl | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590968 | Fiber Tray,6p | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590976 | Fwd Linear Equalizer,750MHz,1.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590977 | Fwd Linear Equalizer,750MHz,3dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590978 | Fwd Linear Equalizer,750MHz,4.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590979 | Fwd Linear Equalizer,750MHz,6dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590980 | Fwd Linear Equalizer,750MHz,7.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590981 | Fwd Linear Equalizer,750MHz,9dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590982 | Fwd Linear Equalizer,750MHz,10.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590983 | Fwd Linear Equalizer,750MHz,12dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590984 | Fwd Linear Equalizer,750MHz,13.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590985 | Fwd Linear Equalizer,750MHz,15dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590986 | Fwd Linear Equalizer,870MHz,1.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 590987 | Fwd Linear Equalizer,870MHz,3.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590988 | Fwd Linear Equalizer,870MHz,4.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590989 | Fwd Linear Equalizer,870MHz,6.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590990 | Fwd Linear Equalizer,870MHz,7.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590991 | Fwd Linear Equalizer,870MHz,9.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590992 | Fwd Linear Equalizer,870MHz,10.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590993 | Fwd Linear Equalizer,870MHz,12.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590994 | Fwd Linear Equalizer,870MHz,13.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 590995 | Fwd Linear Equalizer,870MHz,15dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591010 | Fwd Cbl Simulator,870MHz,1.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591011 | Fwd Cbl Simulator,870MHz,3.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591012 | Fwd Cbl Simulator,870MHz,4.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591013 | Fwd Cbl Simulator,870MHz,6.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591014 | Fwd Cbl Simulator,870MHz,7.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591015 | Fwd Cbl Simulator,870MHz,9.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591016 | Fwd Cbl Simulator,870MHz,10.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 591017 | Fwd Cbl Simulator,870MHz,12dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591018 | Fwd Cbl Simulator,870MHz,13.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591019 | Fwd Cbl Simulator,870MHz,15dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591020 | Fwd Cbl Simulator,870MHz,16.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591022 | Fwd Cbl Simulator,870MHz,19.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591023 | Fwd Cbl Simulator,870MHz,21dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591056 | Rev Equalizer,42MHz (Cbl Slope),0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591057 | Rev Equalizer,42MHz (Cbl Slope),1.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591058 | Rev Equalizer,42MHz (Cbl Slope),3.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591059 | Rev Equalizer,42MHz (Cbl Slope),4.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591060 | Rev Equalizer,42MHz (Cbl Slope),6dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591061 | Rev Equalizer,42MHz (Cbl Slope),7.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591062 | Rev Equalizer,42MHz (Cbl Slope),9dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591063 | Rev Equalizer,42MHz (Cbl Slope),10.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591064 | Rev Equalizer,42MHz (Cbl Slope),12dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591065 | Rev Equalizer,42MHz (Cbl Slope),13.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 591066 | Rev Equalizer,42MHz (Cbl Slope),15dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591067 | Rev Equalizer,42MHz (Cbl Slope),16.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591068 | Rev Equalizer,42MHz (Cbl Slope),18dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591069 | Rev Equalizer,42MHz (Cbl Slope),19.5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591070 | Rev Equalizer,42MHz (Cbl Slope),21.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591071 | Rev Equalizer,55MHz (Cbl Slope),0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591072 | Rev Equalizer,55MHz (Cbl Slope),1dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591073 | Rev Equalizer,55MHz (Cbl Slope),2dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591074 | Rev Equalizer,55MHz (Cbl Slope),3dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591075 | Rev Equalizer,55MHz (Cbl Slope),4dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591076 | Rev Equalizer,55MHz (Cbl Slope),5dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591077 | Rev Equalizer,55MHz (Cbl Slope),6dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591078 | Rev Equalizer,55MHz (Cbl Slope),7dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591079 | Rev Equalizer,55MHz (Cbl Slope),8dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591080 | Rev Equalizer,55MHz (Cbl Slope),9dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591081 | Rev Equalizer,55MHz (Cbl Slope),10dB | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 591082 | Rev Equalizer,55MHz (Cbl Slope),11dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591083 | Rev Equalizer,55MHz (Cbl Slope),12dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591085 | Rev Equalizer,65MHz (Cbl Slope),1.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591086 | Rev Equalizer,65MHz (Cbl Slope),2.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591087 | Rev Equalizer,65MHz (Cbl Slope),3.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591088 | Rev Equalizer,65MHz (Cbl Slope),4.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591089 | Rev Equalizer,65MHz (Cbl Slope),5.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591090 | Rev Equalizer,65MHz (Cbl Slope),6.0dB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591097 | 6940 Left Entry Module Replacement | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591098 | 6940 Right Entry Module Replacement | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591118 | 6940 Launch Amp Assy,870MHz,55/70 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591120 | 6940 Launch Amp Assy,870MHz,65/86 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591129 | 6942/44 6p Intfc Module | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591133 | 75ohm Tx Terminator | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591134 | 75ohm SMB Terminator | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591137 | 6944 Launch Amp Assy,870MHz,65/86 | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 591138 | 6944,870MHz 1x Fwd Seg Mod | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591141 | 6944,870MHz 2x Fwd Seg Mod | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591144 | 6944,870MHz 4x Fwd Seg Mod | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591148 | Fwd Router Plug-In Module | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591150 | 6944 Fwd Plug-in A/D Tiering Module,No Fltr/Crossover Freq | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591151 | 6942/44 Ret Seg Mod,1xRv Seg,5-42MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591152 | 6942/44 Ret Seg Mod,1xRv Seg,5-55MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591153 | 6942/44 Ret Seg Mod,1xRv Seg,5-65MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591154 | 6942/44 Ret Seg Mod,2xRv Seg,5-42MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591155 | 6942/44 Ret Seg Mod,2xRv Seg,5-55MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591156 | 6942/44 Ret Seg Mod,2xRv Seg,5-65MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591157 | 6942/44 Ret Seg Mod,4xRv Seg,5-42MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591158 | 6942/44 Ret Seg Mod,4xRv Seg,5-55MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591159 | 6942/44 Ret Seg Mod,4xRv Seg,5-65MHz,for 8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591160 | 6942/44 Ret Seg Mod,1xRv Seg,Red Rev Tx,5-42MHz,6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591161 | 6942/44 Ret Seg Mod,1xRv Seg,5-55MHz,for 6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 591162 | 6942/44 Ret Seg Mod,1xRv Seg,5-65MHz,for 6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591164 | 6942/44 Ret Seg Mod,2xRv Seg,5-55MHz,for 6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591165 | 6942/44 Ret Seg Mod,2xRv Seg,5-65MHz,for 6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591170 | 6940 TRANSPONDER 5.5-8/50-53c | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591172 | 6940 TRANSPONDER 5.5-8/107-110 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591174 | 6940/44 Node Xpdr,12-18/73-76MHz | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591178 | 6940 TRANSPONDER 27-40/107-110 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591193 | 4 Cbl Rtn Harness for 6944/6942 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591194 | 6944 Fwd 4x Cbl Harness | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591195 | 6944 Fwd 2x Cbl Harness | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591196 | 6944 Fwd 1x Cbl Harness | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 591639 | Finger Loop,XMTR-6940 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 716025 | ASSY,PWB,42/54 1GHZ DIPLEX FILTER MIRROR | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 716187 | 6940 XPNDR AM 8-12/89-93 MHZ | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 717092 | Pwr Cbl Assy | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 717600 | 6940/44 Node Xpdr,Agile 5-65/45-174MHz | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 731067 | ASSY,6944,4XN RTN CNFG 8POS,42 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 735936 | Quad Coax Cbl w/Protective Tube | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 736253 | Crowbar Surge Protector | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 736817 | ASSY,MOD,6940 LAUNCH AMP 42/54 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 741448 | ASSY,PWB,53/862 11DB SLOPE MFN/6940 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 741509 | 6944 Fwd RCM | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 741977 | 6940 Fwd Tiering Module,550/570MHz | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 744207 | ASSY,MOD,6940 LAUNCH AMP 55/70 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 746916 | 694X AC Pwr Jmpr | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 747901 | 6940/6942 bdr Launch Amp Assy,870MHz,42/54 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 747951 | 6944 2way RF Spltr | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748132 | 6944 Seg UPG Kit,1x1 to 2x2,42/54,SA,DFB Tx,6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748135 | 6942/44 Ret Seg Mod,1xRv Seg,5-42MHz,for 6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748136 | 6944 Seg UPG Kit,1x1 to 2x2,42/54,SA,FP Tx,8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748140 | 6944 Seg UPG Kit,1x1 to 4x4,42/54,SA,FP Tx,8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748143 | Fiber Tray,4x4,8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---|---|---|---|---|
| 748144 | 6944 Seg UPG Kit,2x2 to 4x4,42/54,SA,FP Tx,8p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748148 | 6944 Seg UPG Kit,1x1 to 2x2,42/54,SA,FP Tx,6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748868 | 6944 Cover,42/54 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748869 | 6944 Cover,55/70 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 748870 | 6944 Cover,65/86 | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 751382 | Assy,Sub,MFLEXII Dual AC/RF Entry L | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 751383 | ASSY,SUB,MFLEXII DUAL AC/RF ENTRY R | See the Product Migration Options section below for detailed information on replacing this product. | | |
| 753346 | 6942/44 Ret Seg Mod,2xRv Seg,5-42MHz,for 6p OIB | See the Product Migration Options section below for detailed information on replacing this product. | | |

## Product Migration Options

Customers are encouraged to migrate to either the GainMaker 4-port node to replace the 6940 node or the GS7000 Segmentable Node to replace the 6942 and 6944 nodes. Information about these products can be found at: http://www.cisco.com/en/US/products/ps8945/index.html for the GainMaker 4-port node and at http://www.cisco.com/en/US/products/ps8952/index.html for the GS7000 Segmentable Node.

Customers can use the Cisco Technology Migration Program (TMP) to trade-in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html

Customers may be able to continue to purchase the Model 6940/6942/6944 Node Accessories through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

**For More Information**

For more information about the GainMaker 4-Port Node or GS7000 Segmentable Node, visit
http://www.cisco.com/en/US/products/ps8952/index.html or http://www.cisco.com/en/US/products/ps8945/index.html,
or contact your local account representative.

To request information about the GainMaker 4-Port Node or GS7000 Segmentable Node, send an e-mail to
leray@cisco.com.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html

To subscribe to receive end-of-life/end-of-sale information, go to:
http://www.cisco.com/cisco/support/notifications.html

**Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices**

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:
http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.