


# Cisco IOS X-Release 12.2(11)CY

## Introduction

This Product Bulletin describes the content and delivery information concerning Cisco IOS(TM) software release 12.2(11)CY. It should be used in conjunction with Product Product Bulletin, No. 1639 Cisco IOS Early Deployment Release Train 12.2BC. 12.2(11)CY is a short lived Early Deployment (ED) release parented to 12.2(11)BC1 and supporting the Cisco ubr10k. . This release contains all new features delivered in 12.2BC up to and including 12.2(11)BC1.

The platform and features delivered with this ED release will be immediately incorporated into Cisco IOS 12.2(13)BC1 and subsequent Cisco IOS 12.2BC releases. **It is important to note that there are no planned maintenance releases for this ED release. In addition, please note the migration path to the latest T release. Customers should prepare to upgrade using this migration path**

Diagram 1: Cisco IOS Release 12.2(11)CY Release Train and Migration Guide



## New Features in Cisco IOS Release 12.2(11)CY

The following features will be delivered in the initial release of 12.2(11)CY

- **Support for Cisco ubr10012 MC5x20S DOCSIS Line Card**
- **PBR Support for the Cisco ubr10012**
- **VLAN support for the Cisco ubr10012**

For more detailed information about the platforms and features being delivered in 12.2(11)CY, please reference the 12.2(11)CY Release Notes, available at this link:

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122relnt/ubr10000/index.htm>



## Support

Cisco IOS software release 12.2(11)CY follows the standard Cisco support policy as indicated in the following link.

<http://www.cisco.com/warp/public/437/27.html>

## Product Numbers

Table 1. Cisco IOS Release 12.2(11)CY Feature Sets, Images, and Memory Recommendations

Platform	Software Feature Set	Product Code	Image	Flash	DRAM
Ubr10k	DOCSIS BPI IP+	SU10Z6K8-12211CY	Ubr10k-k8p6-mz	40MB	128MB
Ubr10k	DOCSIS IP+	SU10KZ6-12211CY	Ubr10k-p6-mz	40MB	128MB

## Download Information

Users can download release notes for the 12.2(11)CY software from Cisco Connection Online (CCO) at the following link:

<http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122relnt/ubr10000/index.htm>

The IOS software images can be downloaded for the 12.2(11)CY release from Cisco Connection Online (CCO) at the following link:

<http://www.cisco.com/cgi-bin/Software/Iosplanner/Planner-tool/iosplanner.cgi?>

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
Capital Tower  
168 Robinson Road  
#22-01 to #29-01  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 317 7777  
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

**Cisco Web site at [www.cisco.com/go/offices](http://www.cisco.com/go/offices)**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco *Powered* Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(0206R)