

Release Notes for Cisco RV180 and RV180W Firmware Version 1.0.1.9

May 2012

These Release Notes describe the changes in Cisco RV180 and RV180W firmware version 1.0.1.9.

Contents

This document includes the following topics:

- [Enhancements](#)
- [Issues Resolved Since Cisco RV180 and RV180W Firmware Version 1.0.0.30](#)
- [Related Information](#)

Enhancements

- Boot time optimizations
- CoC requirement changes
- PPPoE support
- Removed SSH server support
- Software acceleration of IPsec performance
- Codenomicon HTTP server suite fix

- Remove the automatic reboot that takes place when the LAN configuration is modified. Although the system doesn't reboot, there is about 10 seconds of down time affecting all traffic for the LAN and VLAN.

Issues Resolved Since Cisco RV180 and RV180W Firmware Version 1.0.0.30

- PPPoE fix for HTTP browsing
- Manufacturing command support for firmware version, reset to default
- Fixed an issue in which web pages were not loading properly in Internet Explorer 8. (CSCtq58125)

Known Issues in Firmware Version 1.0.1.9

- Traffic does not follow the bandwidth limit when the traffic selector is set to VLAN, DSCP or SSID. (CSCtr24497)
Work Around: Use an IP range instead. To edit a profile binding rule, go to the *QoS > Profile Binding* page, find the rule in the table, and then click **Edit**. On the *Add / Edit Profile Binding Configuration* page, Traffic Selector Match Type field, select IP Address Range, and then enter the starting and ending addresses.
- On the *Status > Port Statistics* page, the statistics in the Packets column are not updating to show the current number of transmitted and received packets. (CSCtt41705)
- Enabling or disabling multiple SSIDs at once is taking longer than 1 minute. (CSCtq78773)
- The DHCP server is taking more than 2 minutes to assign IP addresses when the router is configured in non-routing mode. (CSCtq52971)

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/sbsc
Cisco Small Business Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco Small Business RV Series Routers: Resources	www.cisco.com/go/smallbizrouters
Open Source Documentation	Click the Release Notes link at www.cisco.com/go/smallbizrouters
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2012 Cisco Systems, Inc. All rights reserved.