

Release Notes for Cisco RV315W Broadband Wireless VPN Router Firmware Version 1.01.03

July 2013

These Release Notes describe the known issues in the Cisco RV315W Broadband Wireless VPN Router firmware version 1.01.03.

To obtain the complete list of mobile broadband USB modems that are compatible with the RV315W running the firmware version 1.01.03 or later, go to www.cisco.com/go/rv315w and see the *Mobile Broadband USB Modem Compatibility Matrix (Cisco RV315W Broadband Wireless VPN Router)*.

Contents

This document includes the following topics:

- [Known Issues](#)
- [Related Information](#)

Known Issues

The following table lists the known issues in firmware version 1.01.03:

Ref Number	Description
CSCui06174	<p>Unable to upload the configuration file through the English web-based Configuration Utility with Mozilla Firefox 22.0 and Mac OS 10.6.</p> <p>Workaround 1) Upload the configuration file through the Chinese web-based Configuration Utility, or 2) through the English web-based Configuration Utility with Microsoft Internet Explorer and/or Windows operation system.</p>
CSCug33830	<p>The VPN connection can be established successfully even though the advanced VPN settings such as authentication algorithm, encryption algorithm, and/or DH Group on both VPN peers do not match.</p> <p>Workaround None.</p>
CSCug36036	<p>IPsec VPN cannot work when the Interest traffic settings of an IPsec VPN policy configured via TR-069 are incomplete.</p> <p>Workaround Configure all required parameters of Interest traffic via TR-069.</p>
CSCug53323	<p>The VPN connection status shown on the RV315W is still up when the remote VPN peer running the Shrewsoft VPN client is down.</p> <p>Workaround Save the VPN policy settings again and reconnect.</p>
CSCug58648	<p>The PC running the Shrewsoft VPN client cannot access the devices in a non-native VLAN of the RV315W over the VPN tunnel.</p> <p>Workaround None.</p>

Ref Number	Description
CSCuh83160	<p>The USB LED on the front panel of the RV315W is solid green when the USB port on the back panel detects a USB device and has read and write operations. It should flash green.</p> <p>Workaround None.</p>
CSCuh88238	<p>All four SSIDs will use the same security key when they use WEP as the security mode at the same time. The security key that you configure on the last SSID will be used for all SSIDs.</p> <p>Workaround None.</p>

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Small Business Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco RV315W	www.cisco.com/go/rv315w
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2013 Cisco Systems, Inc. All rights reserved.

OL-29992-01