

# Release Notes for SGE2010/2010P

## August, 2009

These Release Notes describe the recommended practices and known issues that apply to the SGE2010/2010P for the following software versions:

### Firmware

Firmware Version	3.0.0.17
Firmware Image Name	ros_cisco_bp_ge_bx-30017.ros
Firmware Release Date	June, 2009

### Bootcode

Boot Code Version	2.0.0.03
Boot Code Image Name	cisco_bp_sge_boot-20003.rfb
Boot Code Release Date	June, 2009

## Contents

- “New and Changed Information,” on page 2
- “Limitations and Restrictions,” on page 2
- “Where to Find Support,” on page 3

## New and Changed Information

Firmware versions 3.0.0.17

- Supports new GUI style
- Uses "admin" as the default user name, and "admin" as the default password.
- Uses enterprises(1),cisco(9).otherEnterprises(6).ciscosb(1) as the MIB root OID for private MIB(s)

## Limitations and Restrictions

- Devices that are upgraded or factory loaded with phase 3 firmware version 3.0.0.17 cannot be downgraded to earlier versions of the firmware and boot code.
- Devices running phase 1 firmware (1.0.x.y) can be upgraded to firmware version 3.0.0.17 using the Easy Upgrade Utility.
- Devices running phase 2 firmware (2.0.x.y) can be upgraded to firmware version 3.0.0.17 using regular upgrade procedures. When upgrading, both firmware images must be upgraded.
- Mixing the stack of devices running phase 3, phase 2, and/or phase 1 firmware are not supported.
- Devices running phase 1 and phase 2 firmware must be upgraded separately before stacking with phase 3 devices.
- When browsing using Internet Explorer 8, some ports in the ZOOM web page might flash for a second and not be presented properly. Refreshing the ZOOM web page or moving to another web page and back will resolve this issue.
- If a device is configured to advertise its services using Bonjour, its System Name must contain only upper case characters 'A' to 'Z', lower case characters 'a' to 'z', numbers 0 to 9, and the character '-'.
- Changing the default HTTP service port number (80) will make the Bonjour service \_cisco-sb on the switch inaccessible

## Where to Find Support

To obtain current support information for Cisco Small Business products, visit the following URLs:

[www.cisco.com/en/US/products/ps9967/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps9967/tsd_products_support_series_home.html)

[www.cisco.com/go/smallbizsupport](http://www.cisco.com/go/smallbizsupport)

---

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0809R)

© 2009 Cisco Systems, Inc. All rights reserved.