



Cisco D9865 Satellite Receiver Software Version 2.15 Release Note

Overview

This document describes the new feature and improvements included in software version 2.15 for the Cisco® D9865 Satellite Receiver since the previous version 2.01.

New Feature

The following new feature is included in software version 2.15:

- Support for PowerVu Simulcrypt.

Improvements

The following improvements are included in software version 2.15:

- 1 Subtitles were set to a fixed position in previous releases. This release supports the movement of DVB® subtitles, as per the positioning information in the DVB subtitle stream.
- 2 Resolved an issue where event information is blocked when rating information is present on units that support EPG.
- 3 Corrected an issue where Imitext subtitle positioning could be too high when compared with an older D9850 product.
- 4 Corrected an issue with Low Speed Data (D9865-D units only). Low speed data packets with fewer than four data bytes are now transmitted correctly.

For Information

Cisco provides its customers who have purchased support agreements with telephone support from anywhere in the world. If you require technical telephone assistance or product training support, or if you have any questions concerning the Cisco product, you may contact the appropriate Customer Support Center from those listed below. Charges may apply for customers without a current and applicable product support agreement.

| Customers | Location | Phone Number |
|------------------------------------|----------------|--|
| Programmers and Broadcasters | USA and Canada | Toll-Free: 1.888.949.4786 +1.770.236.4786 dmn_support@cisco.com |
| Telcos and Cable Service Providers | Cisco Services | Toll-Free: 1.800.722.2009 Local: 770.236.6900 (press 2 at the prompt) customer-service@cisco.com |
| All Customers | Europe | +32.56.445.155 or +32.56.445.197 saemea-support@cisco.com |
| All Customers | Asia | +852.2588.4746 saapac-support@cisco.com |

Customers who call a Customer Support Center are asked specific questions in order to identify their needs. In this way, each call can be directed to the customer support representative most experienced with their Cisco product.



Cisco Systems, Inc.
5030 Sugarloaf Parkway, Box 465447
Lawrenceville, GA 30042

678 277-1120
800 722-2009
www.cisco.com

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks.

The DVB logo is a registered trademark of the DVB project.

Other third party trademarks mentioned are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2011 Cisco and/or its affiliates. All rights reserved.
October 2011

Printed in USA
Part Number 4043074 Rev A