··|/··//·· cisco

Release Note – Cisco D9850 PowerVu Program Receiver Software Release Version 2.61

Overview

Introduction

This document describes the changes included in software release version 2.61 for the Cisco[®] D9850 PowerVu Program Receiver since the previous release version, 2.60.

New Features

The following new features are included in this software release version, 2.61.

Live Event Control with DPR – D9850 Program Receivers that support Digital Program Replacement (DPR) will now use DPR during LEC tuning. This allows the ASI output to maintain the source program's PMT and remap the PIDs of the newly tuned program to those of the source program.

For Information

Cisco provides customers with telephone support from anywhere in the world. If you require technical telephone assistance or product training support, or if you have any questions concerning your Cisco product, you may contact the appropriate Customer Support Center from those listed below. Charges may apply for customers without a current and applicable product support agreement.

Customers	Location	Phone Number
Programmers and Broadcasters	USA and Canada	Toll-free: 1.888.949.4786 +1.770.236.4786 <u>dmn_support@cisco.com</u>
Telcos and Cable Service Providers	Cisco Services	Toll-free: 1.800.722.2009 Local: 678.277.1120 (Press 2 at the prompt) <u>customer-service@cisco.com</u>
All customers	Europe	+32.56.445.155 or +32.56.445.197 <u>saemea-support@cisco.com</u>
All customers	Asia	+852.2588.4746 saapac-support@cisco.com

Customers who call a Customer Support Center are asked specific questions in order to identify their needs. In this way, each call can be directed to the customer support representative most experienced with your Cisco product.



5030 Sugarloaf Parkway, Box 465447 Lawrenceville, GA 30044 678.277.1000

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and certain other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks.

Third party trademarks mentioned in this document are the property of their respective owners.

The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1009R)

Product and service availability are subject to change without notice.

© 2010 Cisco and/or its affiliates. All rights reserved. October 2010 Printed in United States of America Part Number 7021914 Rev A