



# Release Notes for Cisco D9865 Satellite Receiver Software Version 2.20

---

**First Published:** December, 2013

**Release:** 2.20

**OL-31164-01**

## Contents

[Introduction, page 1](#)

[New and Changed Information, page 1](#)

[Caveats, page 2](#)

[Related Documentation, page 2](#)

## Introduction

This document describes the new feature and resolved issues in software version 2.20 for the Cisco D9865 Satellite Receiver since the previous 2.15 version.

## New and Changed Information

### New Features in Version 2.20

The following new feature is included in software Version 2.20:

- Support for OSD subtitle messaging (requires PowerVu Network Centre Control System Version 11.6).



---

**Cisco Systems, Inc.**  
[www.cisco.com](http://www.cisco.com)

# Caveats

## Open Caveats - Version 2.20

There are no open caveats for Version 2.20.

## Resolved Caveats - Version 2.20

This section includes the following resolved caveats:

- CSCuj26447  
Corrected an issue that caused horizontal lines to be visible when displaying Chinese or Korean subtitles.
- CSCui94339  
Component video output now remains enabled if a non-authenticated, or switched off, HDMI device is connected to the D9865 unit.

## Related Documentation

Refer to the following documents for additional information about Cisco D9865 Satellite Receiver Software Version 2.20:

- Cisco D9865 Satellite Receiver Software Version 2.20 Installation and Configuration Guide  
[www.cisco.com/go/receivers\\_guides](http://www.cisco.com/go/receivers_guides)
- Open Source Used In Cisco D9865 Satellite Receiver Software Version 2.20  
[www.cisco.com/go/receivers\\_licensing](http://www.cisco.com/go/receivers_licensing)

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation* at: <http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>.

If you have technical questions, contact Cisco Services at the following URL:

<http://www.cisco.com/web/services>

---

This document is to be used in conjunction with the documents listed in the “[Related Documentation](#)” section.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2013 Cisco Systems, Inc. All rights reserved.