



PRODUCT BULLETIN NO. 2781

NEW CISCO IOS SOFTWARE RELEASE 12.2(20)EX FOR CISCO CATALYST 3560 SERIES SWITCHES

OVERVIEW

Cisco Systems® announces Cisco IOS® Software updates for the Cisco® Catalyst® 3560 Series intelligent Ethernet switches. This new release furthers Cisco leadership in providing secure, reliable, and easily managed LAN switching solutions.

This product bulletin describes the content and delivery information concerning Cisco IOS Software Release 12.2(20)EX. For more information about the Cisco IOS Software release process, see Product Bulletin 537.

The Cisco Catalyst 3560 SFP Interconnect Cable provides for a low-cost, point-to-point, Gigabit Ethernet connection between Catalyst 3560 Series switches. The 50-centimeter (cm) cable is an alternative to using Small Form-Factor Pluggable (SFP) transceivers when interconnecting Catalyst 3560 Series switches through their SFP ports over a short distance. All Cisco Catalyst 3560 Series switches support the SFP Interconnect Cable.

NEW FEATURES IN CISCO IOS SOFTWARE RELEASE 12.2(20)EX

Table 1 shows the features included in Cisco IOS Software Release 12.2(20)EX.

Table 1. Cisco IOS Software Release 12.2(20)EX New Features

Feature	Cisco Catalyst 3560 EMI	Cisco Catalyst 3560 SMI
SFP Interconnect Cable	X	X

SMI—Standard Multilayer Image **EMI**—Enhanced Multilayer Image

Table 2 lists the fixed-configuration Cisco Catalyst switches supported with this software release.

Table 2. Supported Cisco Catalyst Switches

Cisco Catalyst 3560 Series EMI Models	Cisco Catalyst 3560 Series SMI Models
Catalyst 3560-48PS	Catalyst 3560-48PS
Catalyst 3560-24PS	Catalyst 3560-24PS
Catalyst 3560-48TS	Catalyst 3560G-48TS
Catalyst 3560-24TS	Catalyst 3560G-24TS

ADDITIONAL RESOURCES

Software Download Available Now

Cisco Catalyst 3560 Series software download is available at <http://www.cisco.com/cgi-bin/tablebuild.pl/cat3560>.

Because of export restrictions on strong cryptography software, a separate image is required for the cryptographic features (Secure Shell [SSH] Protocol, Simple Network Management Protocol Version 3 [SNMPv3], and Kerberos Protocol). These software images can be downloaded from the corresponding Triple Data Encryption Standard (3DES) area of the preceding links.

Additional product information is available at the following Websites:

Cisco Catalyst 3560 Series product information

<http://www.cisco.com/go/catalyst3560>

Cisco Catalyst 3560 Series release notes

<http://www.cisco.com/univercd/cc/td/doc/product/lan/cat3560/index.htm>

Support


Cisco IOS Software Release 12.2(20)EX follows the standard Cisco support policy as indicated at

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

Software Image Migration Guide

Figure 1 displays Cisco IOS Software Release 12.2(20)EX functions relative to the 12.2S and 12.2SE releases. This diagram identifies the recommended migration path. For more information about the Cisco IOS Software release process, please see Product Bulletin 537.

Figure 1. Cisco IOS Software Release 12.2 Release Train



**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0501R)

204189.bf_ETMG_JR_2.05

