

## End-of-Sale and End-of-Life Announcement for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J)

EOL5470—Amended

Cisco Systems<sup>®</sup> announces the end-of-sale and end-of life dates for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J). The last day to order the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J) is January 12, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin.

Table 1 describes the end-of-life milestones, definitions, and dates for the Access Point HWIC Supporting Japanese 5-GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J). Table 2 lists the product part numbers affected by this announcement.

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 12, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 8, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service- and-support contract or add the equipment and/or software to an existing service-and- support contract.	July 8, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service October 4, 2011 contract for the product.	
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 7, 2012

Table 1.End-of-Life Milestones and Dates for the Access Point HWIC Supporting Japanese 5-GHz Radio<br/>Regulatory Requirements (with part number HWIC-AP-AG-J).

HW = Hardware, OS SW = Operating System Software, App. SW = Application Software

End-of-Sale Product Part	Product Description	Replacement Product	Replacement Product
Number		Part Number	Description

HWIC-AP-AG-J	AP HWIC, 2 radios (2.4/5Ghz Radios for 802.11 a/b/g) Japan	HWIC-AP-AG-P	AP HWIC, 2 radios(2.4/5GHz radios for 802.11a/b/g) Japan
HWIC-AP-AG-J=	AP HWIC, 2 radios (2.4/5Ghz Radios for 802.11 a/b/g) Japan	HWIC-AP-AG-P=	AP HWIC, 2 radios(2.4/5GHz radios for 802.11a/b/g) Japan

## **Product Migration Options**

Customers are encouraged to migrate to the access point HWIC with part number HWIC-AP-AG-P. Information about this product can be found at: <u>http://www.cisco.com/en/US/products/ps6246/index.html</u>.

Table 3. Product Comparisons

Feature Access Point HWIC Supporting Japanese   5 GHz Radio Regulatory Requirements (with part number HWIC-AP-AG-J)	Access Point HWIC Supporting 2.4- and 5 GHz Radios (with part number HWIC- AP AG-P)
--	---

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <a href="http://www.cisco.com/go/tradein/">http://www.cisco.com/go/tradein/</a>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order refurbished equipment program description. html

## For More Information

For more information about the Access Point HWIC Supporting 2.4- and 5-GHz Radios (with part number HWIC-AP-AG-P), <u>http://www.cisco.com/en/US/products/ps6246/index.html</u> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod\_end\_of\_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <a href="http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice">http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice</a>



Americas Headquarters Capo, Systems, as 170 Weat Baman Otvo Sah Jusé, DA&S (34-1783 USA seatolace.com Tel. 406, 520-4900 500 563-10215 (5530)

7822.4938-527-06839

Pada Pacific Handiquerrane Class Bysterie, Inc. 199 Robinson Rossi Singenore Diff912 www.class.com Singenore Diff912 www.class.com Singenore Diff912 Singenore Diff912 Singenore Diff912 Rossie Singenore Singenore Diff912 Rossie Singenore Singenore Diff912 Rossie Singenore Sing Europe, Headquarten Disco Systems International SY Headlandschung 1978 1101 CH Asselectors The Welhoestols International State International State Part Action 2020/2017 Fair Action 2020/2017

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Wabsite at www.cisco.com/go/offices.

(920)7 Clace Systems, Inc. All rights isserved. CCVP, the Clace login, and the Clace Square Bridge logic are tradements of Clace Systems, Inc. Changing the Wark, Like, Play, and Learn it a service mark of Clace Systems, Inc. and Accuss Register Alcoset, BPX, Catalyst, CCOA, CODP, COE, COP, COE, COP, Clace (the Clace Cartified Intensitiver's Expertilety, Clace NS, Clace Press, Clace Systems, Clace Systems Capital, the Clace Systems logic Olice Unity, Entroprise/Solver, ElterChannel, EtherCatal, Red Step, Follow Ma Browsing, FormShave, SigaDrive, Clace Systems, Clace Sy

All other trademarks mentioned in this document or Webelta are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Claco and any other company, (0701R)

Printed in USA

C51-388298-00 1/07