

End-of-Sale and End-of-Life Announcement for the Cisco MDS 9513 Crossbar Switching Fabric Module

EOL6631

Cisco® announces the end-of-sale and end-of life dates for the Cisco MDS 9513 Crossbar Switching Fabric Module. The last day to order the affected product(s) is July 8, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9513 Crossbar Switching Fabric Module

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 7, 2009
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 8, 2009
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 6, 2009
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	July 8, 2010
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 8, 2010
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	October 3, 2013
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	

HW = Hardware
OS SW = Operating System Software
App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
DS-13SLT-FAB1	MDS 9513 Crossbar Switching Fabric Module	DS-13SLT-FAB2	MDS 9513 Crossbar Switching Fabric Module 2
DS-13SLT-FAB1=	MDS 9513 crossbar switching fabric module, Spare	DS-13SLT-FAB2=	MDS 9513 Crossbar Switching Fabric Module 2

Product Migration Options

Customers are encouraged to migrate to the Cisco MDS 9513 Crossbar Switching Fabric2 Module. Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet09_00aecd80446023.html.

Customers may purchase the Cisco MDS 9513 Crossbar Switching Fabric2 Module from EMC Corporation, IBM Corporation, Hitachi Data Systems, Hewlett-Packard, Xiotech, Sun, Network Appliance, Dell, NEC, or Fujitsu, all of whom are designated original storage manufacturer (OSM) or solution technology integrator (STI) partners, or from any of these companies' resellers. Cisco does not offer trade-in credits or a trade-in program.

For More Information

For more information about the Cisco MDS 9513 Crossbar Switching Fabric2 Module, visit http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet09 https://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet09 https://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet09 https://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet09 https://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet09 https://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps6780/product_data_sheet09 <a href="https://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps6780/p

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company, (0809R)

Printed in USA C51-509525-00 12/08