



End-of-Sale and End-of-Life Announcement for the Cisco MDS 9513 Crossbar Switching Fabric Module 2

EOL8785—Amended

Cisco announces the end-of-sale and end-of life dates for the Cisco MDS 9513 Crossbar Switching Fabric Module 2. The last day to order the affected product(s) is April 19, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9513 Crossbar Switching Fabric Module 2

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 19, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 19, 2013
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 18, 2013
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	April 19, 2014
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 19, 2014
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 15, 2017
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2018

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
DS-13SLT-FAB2	MDS 9513 Crossbar Switching Fabric Module 2	DS-13SLT-FAB3	MDS 9513 Crossbar Switching Fabric3 Module	—
DS-13SLT-FAB2=	MDS 9513 Crossbar Switching Fabric Module 2	DS-13SLT-FAB3=	MDS 9513 Crossbar Switching Fabric3 Module	—
DS-13SLT-FAB2HP=	MDS 9513 Crossbar Switching Fabric Module 2 for HP, Promo	DS-13SLT-FAB3NH=	MDS 9513 Crossbar Switching Fabric3 Module for HP, Spare	—
DS-13SLT-FAB2P=	MDS 9513 Crossbar Switching Fabric Module 2, Promo Spare	DS-13SLT-FAB3=	MDS 9513 Crossbar Switching Fabric3 Module	—
DS-C9513-3AHK9	MDS 9513: Chassis, 2x(Sup2A, FAB2, 6K PS) for HP and Service	DS-C9513-4AHK9	MDS 9513: Chassis, 2x(Sup2A, FAB3, 6K PS) for HP with Service	—
DS-C9513-3AK9	MDS 9513 Base Config: Chassis, 2 Sup-2A, 2 Fabric2, 2 6K AC PS	DS-C9513-4AK9	MDS 9513 Base Config: Chassis, 2 Sup-2A, 2 Fabric3, 2 6K PS	—
DS-C9513-3ANH9	MDS 9513: Chassis, 2x(Sup2A, FAB2, 6K PS) for HP	DS-C9513-4ANH9	MDS 9513: Chassis, 2x(Sup2A, FAB3, 6K PS) for HP	—

Product Migration Options

Customers are encouraged to migrate to the Cisco MDS 9513 Crossbar Switching Fabric 3 Module. Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet0900aecd80446023_ps5990_Products_Data_Sheet.html.

Customers may be able to continue to purchase the Cisco MDS 9513 Crossbar Switching Fabric Module 2 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the Cisco MDS 9513 Crossbar Switching Fabric 3 Module, visit http://www.cisco.com/en/US/prod/collateral/ps4159/ps6409/ps5990/ps6780/product_data_sheet0900aecd80446023_ps5990_Products_Data_Sheet.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA

© 2012 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public.

C51-718688-01 11/12

Page 3 of 3