

Cisco 1-Port Channelized OC-12/STM-4 Shared Port Adapter

The Cisco® I-Flex design combines shared port adapters (SPAs) and SPA interface processors (SIPs) using an extensible design that enables service prioritization for voice, video, and data services. Enterprise and service provider customers can use the improved slot economics resulting from modular port adapters that are interchangeable across Cisco routing platforms. The I-Flex design maximizes connectivity options and offers superior service intelligence through programmable interface processors that deliver line-rate performance. I-Flex enhances speed-to-service revenue and provides a rich set of quality-of-service (QoS) features for premium service delivery while effectively reducing the overall cost of ownership. This data sheet contains the specifications for the Cisco 1-Port Channelized OC12/STM-4 SPA (refer to Figure 1).

Figure 1. Cisco 1-Port Channelized OC-12/STM-4 Shared Port Adapter



Product Overview

The Cisco 1-Port Channelized OC-12/STM-4 SPA is available on high-end Cisco routing platforms offering the benefits of network scalability with lower initial costs and ease of upgrades. The Cisco SPA/SIP portfolio continues the Cisco focus on investment protection along with consistent feature support, broad interface availability, and the latest technology. The Cisco SPA/SIP portfolio allows different interfaces (Packet over SONET/SDH [POS], ATM, Ethernet, etc.) to be deployed on the same interface processor.

Applications

Internet traffic continues to grow at an explosive rate – with the number of users doubling each year. This unsurpassed growth is increasing the demand for higher-capacity interfaces from OC-3/STM-1 to OC-48/STM-16. In addition, POS enables efficient transport of IP traffic and uses SONET/SDH concatenated payloads (that is, STS-3c/VC-4, STS-12c/VC-4-4c, or STS-48c/VC-4-16c) to achieve a higher order of statistical multiplexing. At present, concatenated services at VC-4 rates are available only in some parts of the world (for example, Europe), with higher rates not yet readily available. The new Channelized OC-12/STM-4 SPA provides customers in these areas with an STM-4 POS interface that can be provisioned through the traditional network. The Channelized OC12/STM-4 SPA builds on the SONET/SDH channelization capability.

Features at a Glance

- 1-port Channelized OC-12/STM-4 port per SPA
- SONET VT 1.5 mapping: STS-1<>VTG<>VT1.5<>DS1<>
- SONET PDH-DS-3 (M13 and C-bit) mapping: STS-1<>DS3<>DS1<>nxDS0
- SDH VC-12 mapping (AU-4<>TUG3<>TUG2<>VC-12<>E1<>nxE0
- SDH VC-11 mapping (AU-3<>TUG2<>VC-11<>DS1<>nxDS0)
- SONET DS-3 mapping: STS-1<>DS3 (clear channel)
- SDH DS-3 mapping: AU-4<>TUG3<>VC-3<>DS3 or AU-3<>VC-3<>DS3
- SDH E3 mapping: AU-4<>TUG3<>VC-3<>E3 or AU-3<>VC-3<>E3
- Bit Error Rate Test (BERT) support for T3/E3 channels
- Channelization support for 4 OC-3 or 12 DS-3 or 336 DS-1 or 2K DS-0 or n x DS-0 channels, or any combination of these
- Multilink bundling on T1/E1 channels as per RFC 1990
- Subrate DS-3
- BERT support for T1/E1 channels

Product Specifications

Table 1 shows the hardware specifications for the Channelized OC-12/STM-4 SPA.

Table 1. Hardware Specifications for the Cisco 1-Port Channelized OC-12 SPA

Features	Descriptions
Product compatibility	Cisco 7600 Series Routers Cisco XR 12000 Series Routers Cisco ASR 1000 Series Router Cisco CRS
Port density per SPA	1-port Channelized OC-12/STM-4
Physical interface (Channelized OC-12)	OC-12c/STM-4 Small Form-Factor Pluggable (SFP) optics module (refer to optical parameters in Table 2) Visual status indicators (LEDs): SPA status LED Per-port LEDs Carrier and alarm Active and loopback
Protocols	IETF RFC 1490, Frame Relay Encapsulation RFC 1662, Point-to-Point Protocol (PPP) in High-Level Data Link Control (HDLC)-like framing Cisco HDLC Multilink PPP (RFC 1990) (as applicable for 1-port Channelized OC-12c/STM-4 (DS-1/E1) FRF.12, link fragmentation and interleaving (LFI) PPP, HDLC, and Frame Relay User Network Interface (UNI) encapsulations
Features and functions	 DS-3 Full- and half-duplex connectivity at DS-3 rate (44.736 MHz) Scrambling and subrate support of major data-service-unit (DSU) vendors C-bit or M23 framing (software selectable) MDL Support for 16- and 32-bit cyclic redundancy check (CRC) (16-bit default) 24-hour history maintained for error statistics and failure counts

Features	Descriptions
	 DS-3 alarm and event detection (once-per-second polling) Alarm indication signal (AIS) Out of frame (OOF) Far-end receive failure (FERF) DS-1 Superframe (SF) and Extended Superframe (ESF) support ANSI T1.403 FDL support Internal or line-derived (loop) clocking, independently selectable on each T1 tributary Error and alarm detection: CRC errors, framing errors, loss of frame (red), AIS (blue), remote alarm indication (yellow) Alarm reporting: 24-hour history maintained, 15-minute intervals on all errors BERT at T1 level Loopback capabilities: local, network line and network payload, remote network line, and remote network payload at the T1 level
SONET errors, alarms, and performance monitoring	Synchronization Local (internal) or loop timed (recovered from network) Pointer activity monitoring Local (diagnostic) and line (network) loopback Payload mapping POS with 1 + X'43 self-synchronous scrambler SONET/SDH compliance Telcordia (Bellcore) GR-253-CORE (as applicable) ANSI T1.105, T1.231 ITU-T G.707, G.957, G.825 (as applicable) Supported SONET/SDH alarm and signal events Signal failure bit error rate (SF-ber) Signal label payload construction (C2) Path trace byte (J1) Section Loss of signal (LoS) Loss of frame (LoF) Error counts for B1 Threshold crossing alarms (TCA) for B1 Line Line alarm indication signal (LAIS) Line remote defect indication (LRDI) Line remote defect indication (LRDI) Error counts for B2 TCA for B2 Path Path alarm indication signal (PAIS) Path remote defect indication (PRDI) Path remote defect indication (PRDI) Path remote defect indication (PRDI) Path remote error indication (PRDI) Path remote sufficiation (PRDI) Path remote error indication (PRDI) Path remote error indication (PRDI) Path remote suffing event (PSE) Negative stuffing event (NSE) Path unequipped indication signal (PUNEQ) Path payload mismatch indication signal (PPLM)
Network management	SONET-MIB (RFC 3592) SONET/SDH-MIB (RFC 2558) CISCO-SONET-MIB DS-3/E3-MIB (RFC 3896) DS-1/E1-MIB (RFC 2496)

Features	Descriptions
	Simple Network Management Protocol (SNMP)
Reliability and availability	Online insertion and removal (OIR) Field-replaceable SFP optical modules 1+1 SONET Automatic Protection Switching (APS) and SDH Linear Multiplexer Section Protection (MSP) protocols Single SPA software reset
Physical specifications	Weight: 1.27 lb (0.57 kg) Height: 1.56 in. (3.96 cm) (double height) Width: 6.75 in. (17.15 cm) Depth: 7.28 in. (18.49 cm)
Power	1-port Channelized OC-12/STM-4 = 41.3W (with optics)
Environmental specifications	Operating temperature: 41 to 104年 (5 to 40℃) Storage temperature: –38 to 150年 (–40 to 70℃) Operating humidity: 5 to 85% relative humidity Storage humidity: 5 to 95% relative humidity
Compliance and agency approvals	Safety UL 60950 CSA 22.2-No.60950 EN60950 IEC 60950 CB Scheme ACA TS001 AS/NZS 3260 EN60825\IEC60825 laser safety (SR, IR-Class 1) (VSR-Class 1M)1 21CFR1040 -FDA Code of Federal Regulations (USA) laser safety (SR, IR-Class 1) (VSR-Class 1M)1 EMC FCC Part 15 (CFR 47) ICES 003 EN55022 CISPR 22 AS/NZS CISPR22 VCCI EN55024 EN61000-6-1 EN61000-6-1 EN61000-3-2 EN61000-3-3 Network Equipment Building Standards (NEBS) This product is designed to meet the following requirements (official qualification may be in progress): SR-3580 – NEBS: Criteria levels (Level 3 compliant) GR-63-CORE – NEBS: Physical protection GR-1089-CORE – NEBS: EMC and safety

 Table 2.
 Optical Specifications for the Cisco 1-Port Channelized OC-12 SPA

SFP Optics	Maximum Distance
Multimode (MM)	Up to 0.25 mi (500m)
Single-mode (SM)	Up to 1.2 mi (2 km)
SM intermediate reach (IR-1)	Up to 9 mi (15 km)
SM long reach (LR-1)	Up to 25 mi (40 km)
SM extended reach (LR-2)	Up to 50 mi (80 km)

Power and Environmental Requirements

When installed in Cisco routers, these SPAs do not change the power or environmental requirements and standards of the router platform itself. Refer to the platform-specific data sheets for more information.

Ordering Information

To place an order, visit the Cisco Ordering Homepage and refer to Table 3.

Table 3. Ordering Information

Product Name	Part Number
Cisco 1-port Channelized OC12/STM-4 SPA	SPA-1xCHOC12/DS0
OC12/STM-4, OC12/STM-4 SFP, MM	SFP-OC12-MM
OC12/STM-4, OC12/STM-4 SFP, SM, SR	SFP-OC12-SR
OC12/STM-4, OC12/STM-4 SFP, SM, IR-1	SFP-OC12-IR1
OC12/STM-4, OC12/STM-4 SFP, SM, LR-1	SFP-OC12-LR1
OC12/STM-4, OC12/STM-4 SFP, SM, LR-2	SFP-OC12-LR2

Service and Support

Cisco offers a wide range of services programs to accelerate customer success. These innovative services programs are delivered through a unique combination of people, processes, tools, and partners, resulting in high levels of customer satisfaction. Cisco services help you protect your network investment, optimize network operations, and prepare your network for new applications to extend network intelligence and the power of your business. For more information about Cisco services, refer to <u>Cisco Technical Support Services</u> or <u>Cisco Advanced Services</u>.

For More Information

For more information about the Cisco SPA/SIP portfolio, visit www.cisco.com/go/spa or contact your local Cisco account representative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA C78-396175-01 09/11