

## End-of-Sale and End-of-Life Announcement for the Cisco Bandwidth Quality Manager 3.1 and 3.2

EOL6198

Cisco® announces the end-of-sale and end-of life dates for the Cisco Bandwidth Quality Manager 3.1 and 3.2. The last day to order the affected product(s) is January 30, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1

**Table 1.** End-of-Life Milestones and Dates for the Cisco Bandwidth Quality Manager 3.1 and 3.2

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 31, 2007
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 30, 2008
<b>Last Ship Date: App. SW, HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 29, 2008
<b>End of SW Maintenance Releases Date: App. SW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 29, 2009
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	January 29, 2009
<b>End of New Service Attachment Date: App. SW, HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 29, 2009
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	April 27, 2012
<b>End of Service Contract Renewal Date: App. SW</b>	The last date to extend or renew a service contract for the product.	April 30, 2010
<b>Last Date of Support: HW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 28, 2013
<b>Last Date of Support: App. SW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 29, 2011

HW = Hardware    OS SW = Operating System Software    App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
<b>CBQME-1180-K9</b>	Cisco Bandwidth Quality Manager Engine 3.1 -100 remote sites	See the Product Migration Options section below for detailed information on replacing this product.	Replaced by ADE 2130 platform
<b>CBQME-1180-UP-K9</b>	Cisco BQM Engine 3.1 Upgrade -100 remote sites	See the Product Migration Options section below for detailed information on replacing this product.	Replaced by ADE 2130 platform
<b>CBQME-1180T-K9</b>	Cisco BQM 3.1 Telepresence-10 remote sites	See the Product Migration Options section below for detailed information on replacing this product.	Replaced by ADE 2130 platform
<b>CBQME-3.1-SW-K9</b>	Cisco BQM Engine 3.1 software loaded on Cisco 1180	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.1-SWT-K9</b>	Cisco BQM 3.1-Telepresence software	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.1-SWUP-K9</b>	Cisco BQM Engine 3.1 software loaded on Cisco 1180 Upgrade	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-10-LC</b>	Cisco BQM License - for additional 10 sites	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-10-LC=</b>	Cisco BQM License - for additional 10 sites	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-100MLC</b>	Cisco BQM 100Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-100MLC=</b>	Cisco BQM 100Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-10MLC</b>	Cisco BQM 10Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-10MLC=</b>	Cisco BQM 10Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-1GLC</b>	Cisco BQM 1Gb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-1GLC=</b>	Cisco BQM 1Gb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-500MLC</b>	Cisco BQM 500Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-500MLC=</b>	Cisco BQM 500Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	

<b>CBQME-3.2-50MLC</b>	Cisco BQM 50Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-50MLC=</b>	Cisco BQM 50Mb/s Bandwidth Processing License	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-3.2-SW10-K9</b>	Cisco BQM SW lic - 10Mbps of monitored BW, 10 remote sites	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI</b>	Cisco BQM Engine-Fixed PCI card with 4 port 10/100/1000 Mbps	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-2</b>	Cisco BQM Engine-PCI card 2 active + 2 SFP optional	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-2=</b>	Cisco BQM Engine-PCI card 2 active + 2 SFP optional	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-4</b>	Cisco BQM Accelerator card - fixed PCI card, four 1Gbps port	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-4=</b>	Cisco BQM Accelerator card - fixed PCI card, four 1Gbps port	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-4M</b>	Cisco BQM Accelerator card - Modular PCI card, needs 4 SFPs	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-4M=</b>	Cisco BQM Accelerator card - Modular PCI card, needs 4 SFPs	See the Product Migration Options section below for detailed information on replacing this product.	
<b>CBQME-PCI-M</b>	Cisco BQM Engine- Modular PCI card requires SFPs purchase	See the Product Migration Options section below for detailed information on replacing this product.	

## Product Migration Options

Customers are encouraged to migrate to the Cisco Bandwidth Quality Manager 4.0 release and the Application Deployment Engine series of hardware platforms. Information about these products can be found in the BQM 4.0 product bulletin at:

[http://www.cisco.com/en/US/prod/collateral/netmgtsw/ps6341/ps6385/ps8796/prod\\_bulletin0900aecd806d3acb.html](http://www.cisco.com/en/US/prod/collateral/netmgtsw/ps6341/ps6385/ps8796/prod_bulletin0900aecd806d3acb.html)

## For More Information

For more information about the Cisco Bandwidth Quality Manager 4.0, visit <http://www.cisco.com/en/US/products/ps6385/index.html>, or contact your local account representative.

To request information about the Cisco Bandwidth Quality Manager 4.0, send an e-mail to [bgm-product-info@external.cisco.com](mailto:bgm-product-info@external.cisco.com)

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



**Americas Headquarters**  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 527-0883

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 6317 7777  
Fax: +65 6317 7799

**Europe Headquarters**  
Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www-europe.cisco.com](http://www-europe.cisco.com)  
Tel: +31 0 800 020 0791  
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, IQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0710R)