



## PRODUCT BULLETIN NO. 2575

# END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 15600-R1.1.1SWCD, 15600-LIC-R1.1.1, & SF15600-R1.1.1

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® 15600-R1.1.1SWCD, 15600-LIC-R1.1.1 and SF15600-R1.1.1. The last day to order the Cisco 15600-R1.1.1SWCD, 15600-LIC-R1.1.1, and SF15600-R1.1.1 is February 28, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until February 28, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco 15600-R1.1.1SWCD, 15600-LIC-R1.1.1, and SF15600-R1.1.1. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco 15600-R1.1.2SWCD, 15600-LIC-R1.1.2, and SF15600-R1.1.2, which is the next release of software for the ONS15600. Information about the replacement product can be found at:

<http://www.cisco.com/univercd/cc/td/doc/product/ong/15600/index.htm> (will be added when FCS'd) Table 3 provides relevant information for migrating from the Cisco 15600-R1.1.1SWCD, 15600-LIC-R1.1.1, and SF15600-R1.1.1 to the 15600-R1.1.2SWCD, 15600-LIC-R1.1.2 and SF15600-R1.1.2 respectively.

**Table 1.** End-of-Life Milestones and Dates for the Cisco [Product Name]

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	August 30, 2004
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 28, 2005
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 30, 2005
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 28, 2006
End of routine failure analysis date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	February 28, 2006
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 28, 2006
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	November 30, 2009
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 28, 2010

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15600-R1.1.1SWCD	Rel 1.1.1 AE Feature Pkg, CD
15600-LIC-R1.1.1	Right to use sw license R1.1.1
SF15600-R1.1.1	Rel 1.1.1 SW, Pre-Loaded on TSC

## PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco 15600-R1.1.1SWCD, 15600-LIC-R1.1.1, and SF15600-R1.1.1 is to 15600-R1.1.2SWCD, 15600-LIC-R1.1.2 and SF15600-R1.1.2 (Table 3). The migration for existing R1.1.1 customers is to upgrade to R1.1.2 software. This can be accomplished by downloading the maintenance release and following the software update procedure. R1.1.2 is being provided to eliminate the required R1.1.1 cisco15 user account and 15600-FTA2 functionality.

**Table 3.** Product Comparisons

Cisco [End-of-Life Product Name]	Cisco [Replacement Product Name]
15600-R1.1.1SWCD	15600-R1.1.2SWCD
15600-LIC-R1.1.1	15600-LIC-R1.1.2
SF15600-R1.1.1	SF15600-R1.1.2

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers can simply order 1560015600-R1.1.2SWCD, 15600-LIC-R1.1.2, and SF15600-R1.1.2 or 15600-LIC-UPG software.

## FOR MORE INFORMATION

For more information about the Cisco ONS 15600, visit <http://www.cisco.com/en/US/products/hw/optical/ps4533/index.html> and/or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International  
BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland  
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland  
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden  
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0403R)