



END-OF-LIFE NOTICE, NO. 2403

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 15600-R1.0.0SWCD

Cisco Systems® announces the End-of-Life of the Cisco® 15600-R1.0.0SWCD. The last day to order the Cisco 15600-R1.0.0SWCD is December 31, 2003. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until December 31, 2003. Table 1 describes the End-of-Life milestones, definitions, and dates for the Cisco 15600-R1.0.0SWCD.

Customers are encouraged to migrate to the 15600-LIC-UPG, which is the next release of software for the ONS 15600. Information about this product can be found at: http://www.cisco.com/en/US/products/hw/optical/ps4533/tsd_products_support_series_home.html. Table 3 provides relevant information for migrating from the Cisco 15600-R1.0.0SWCD to the 15600-LIC-UPG.

Table 1. End-of-Life Milestones and Dates for the Cisco 15600-R1.0.0SWCD

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the End-of-Sale and End-of-Life of a product is distributed to the general public.	June 30, 2003
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 31, 2003
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	March 31, 2004
End Of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 31, 2004
End Of Routine Failure Analysis Date	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	December 31, 2004
End Of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 31, 2004
End Of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	September 30, 2005
Last Date Of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2005

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15600-R1.0.0SWCD	Rel 1.0.0 AE Feature Pkg, CD

Required:

Product Migration Options

There is only one migration plan for existing Release 1.0.0 customers, upgrading to R1.1.0 software. The recommended replacement for the Cisco 15600-R1.0.0SWCD is the 15600-LIC-UPG (Table 3). The 15600-LIC-UPG is the next available release of software R1.1.0 for the ONS 15600. Added to this release is full support of R1.0.0, 2F BLSR, and support for new OC-48/OC-192 SR modules and bug fixes for R1.0.0. 15600-LIC-UPG also contains code to support the new AMCC nP3400 Rev C3C chip on the 15600-TSC module as well as the exiting AMCC nP3400 Rev C2C chip.

Table 3. Product Comparisons

	Cisco 15600-R1.0.0SWCD	Cisco 15600-LIC-UPG
Feature	320 Gbps 128-port single shelf system.	320 Gbps 128-port single shelf system.
Feature	OC-192 LR module support	OC-192 LR module support
Feature	OC-48 LR module support	OC-48 LR module support
Feature	UPSR, 1+1 APS and PPMN	UPSR, 1+1 APS and PPMN
Feature		2F BLSR
15600-48L16LR1550	16-Port OC-48 LR module	16-port OC-48 LR module
15600-192L4LR1550	4-Port OC-192 LR module	4-port OC-192 LR module
15600-192S4SR1310		4-port OC-192 SR module
15600-48S16SR1310		16-port OC-48 SR module

INSTRUCTIONS: Customers can use the Class B ECO (needs to be created) to upgrade to 15600-LIC-UPG software.

ADDITIONAL INFORMATION

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive End-of-Life/End-of-Sale information, please go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R)
VS/LW8343 04/05

