

End-of-Sale and End-of-Life Announcement for the Cisco ONS 15310-MA SDH Multiservice Platform

EOL9121

Cisco announces the end-of-sale and end-of-life dates for the Cisco ONS 15310-MA SDH Multiservice Platform. The last day to order the affected product(s) is April 12, 2014. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco ONS 15310-MA SDH Multiservice Platform

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	April 12, 2013
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 12, 2014
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 11, 2014
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 12, 2014
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	April 12, 2015
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	April 12, 2015
End of New Service Attachment Date: OS SW, HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 12, 2015
End of Service Contract Renewal Date: OS SW, HW	The last date to extend or renew a service contract for the product.	July 11, 2018
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2019

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
15310-BP-COVER-A	15310-MA BLANK Backplane Cover, Side A
15310-BP-COVER-A=	15310-MA BLANK Backplane Cover, Side A
15310-BP-COVER-B	15310-MA BLANK Backplane Cover, Side B

End-of-Sale Product Part Number	Product Description
15310-BP-COVER-B=	15310-MA BLANK Backplane Cover, Side B
15310-CBLMGT=	MA Optical and Front Access Electrical cable management.
15310-CE-MR-6	Carrier Ethernet card - 6 port Multirate 10/100/1000 Mbps
15310-CE-MR-6=	Carrier Ethernet card - 6 port Multirate 10/100/1000 Mbps
15310-CTX-FILLER	CTX Filler Module
15310-CTX-FILLER=	CTX Filler Module
15310-DOOR-KIT	15310-MA Door Kit
15310-DOOR-KIT=	15310-MA Door Kit
15310-EXP-FILLER	15310 blank expansion module
15310-EXP-FILLER=	15310 blank expansion module
15310-MA-DS1-PLUG=	15310 MA DS1 CABLE PLUG
15310-MA-FTA	MA Shelf Fan Tray Assembly, Includes Fan Tray Filter
15310-MA-FTA=	MA Shelf Fan Tray Assembly, Includes Fan Tray Filter
15310-MA-FTF=	MA Shelf Fan Tray Filter
15310-MA-REAR-CVR=	15310 MA REAR CONNECTIONS PROTECTION COVER, PLEXIGLAS
15310-MA-SHIPKIT	Shelf Install Accessories
15310-MA-SHIPKIT=	Shelf Install Accessories
15310-MA-WMB=	15310 MA WALL MOUNT BRACKET
15310-P-ML-100T-8	15310 ML series 10/100 Ethernet
15310-P-ML-100T-8=	15310 ML series 10/100 Ethernet
15310E-28WBE-3BBE=	15310E E1/E3/DS3 TRIBUTARY CARD-LOW DENSITY PORTS
15310E-84WBE-3BBE=	15310E E1/E3/DS3 TRIBUTARY CARD-HIGH DENSITY PORTS
15310E-CTX-K9=	MA CONTROL, SYNC, XCONNECT 160 AU4 5G LO
15310E-DOC9.0.0CD=	15310E Sys Doc R9.0.0 English, CD
15310E-E1-120-7=	7.6 meter cable for 120 Ohm E1
15310E-EIA-HDA	15310E E1/E3 BIC WITH 120 OHMS TERMINATION A SIDE
15310E-EIA-HDA=	15310E E1/E3 BIC WITH 120 OHMS TERMINATION A SIDE
15310E-EIA-HDB	15310E E1/E3 BIC WITH 120 OHMS TERMINATION B SIDE
15310E-EIA-HDB=	15310E E1/E3 BIC WITH 120 OHMS TERMINATION B SIDE
15310E-LIC-UPG	15310E Software Upgrade License (ATO)
15310E-MA-19I-KIT=	15310E EAR MOUNTS FOR 19 IEC RACK MOUNT AND SHIP KIT
15310E-MA-600-KIT=	15310E EAR MOUNTS FOR 600X600 ETSI RACK MOUNT AND SHIP KIT
15310E-MA-SA=	15310E MA CHASSIS WITH 120 OHMS BITS TERMINATION
15310E-P-CE-100T=	15310E 8 PORT 10/100 ETHERNET L1 ONLY, ETSI VERSION
15310EM-DOC9.1.0C=	15310 Sys Doc R9.1.0 English, CD
15310EM-DOC9.2.0C	15310E MA Sys Doc R9.2.0 English, CD
15310EM-DOC9.2.0C=	15310E MA Sys Doc R9.2.0 English, CD
15310EM-DOC9.2.1C=	15310E MA Sys Doc R9.2.1 English, CD
15310EM-LIC9.0.1K9	15310E MA ETSI Upgrade License for R9.0.1, Right to Use Lice
15310EM-LIC9.1.0K9	15310 MA ETSI Upgrade License for R9.1.0, Right to Use Licen
15310EM-LIC9.2.0K9	15310E MA ETSI Upgrade License for R9.1.0, RTU LIC
15310EM-LIC9.2.1K9	15310 MA ETSI Upgrade License for R9.1.1, RTU LIC
15310EM-R9.0.0SK9=	15310E REL 9.0.0 SDH FEATURE PKG. CD, RIGHT TO USE
15310EM-R9.0.1SK9	15310E MA ETSI Rel. 9.0.1 Feature Pkg., CD, Right to Use Lic

End-of-Sale Product Part Number	Product Description
15310EM-R9.0.1SK9=	15310E MA ETSI Rel. 9.0.1 Feature Pkg., CD, Right to Use Lic
15310EM-R9.1.0SK9	15310 MA ETSI Rel. 9.1.0 Feature Pkg., CD, Right to Use Lice
15310EM-R9.1.0SK9=	15310 MA ETSI Rel. 9.1.0 Feature Pkg., CD, Right to Use Lice
15310EM-R9.2.0SK9	15310E MA Rel. 9.2.0 Feature Pkg., DVD, Right to Use License
15310EM-R9.2.0SK9=	15310E MA Rel. 9.2.0 Feature Pkg., DVD, Right to Use License
15310EM-R9.2.1SK9	15310E MA Rel. 9.2.1 Feature Pkg., DVD, Right to Use License
15310EM-R9.2.1SK9=	15310E MA Rel. 9.2.1 Feature Pkg., DVD, Right to Use License
15310M-WW-DB9BIT	15310 MA DB9 TO WIRE WRAP BITS ADAPTOR
15310M-WW-DB9BIT=	15310 MA DB9 TO WIRE WRAP BITS ADAPTOR
SF15310EM-R9.0.0K9	15310E REL 9.0.0 SDH SW, PRE-LOADED ON CTX (MA)
SF15310EM-R9.0.1K9	15310E MA ETSI Rel. 9.0.1 SW, Pre-loaded on 15310-MA ETSI
SF15310EM-R9.1.0K9	15310E MA ETSI Rel. 9.1.0 SW, Pre-loaded on 15310-MA ETSI
SF15310EM-R9.2.0K9	15310E MA Rel. 9.2.0 SW, Pre-loaded on 15310-MA
SF15310EM-R9.2.1K9	15310E MA Rel. 9.2.1 SW, Pre-loaded on 15310-MA

Product Migration Options

There is no replacement available for the Cisco ONS 15310-MA SDH Multiservice Platform at this time.

Customers are encouraged to migrate to the Cisco ONS 15454 MSTP portfolio with legacy services cards. Information about this product can be found at:

http://www.cisco.com/en/US/products/hw/optical/ps2006/ps5320/index.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives and promotions/tmp.html.

Customers may be able to continue to purchase the Cisco ONS 15310-MA SDH Multiservice Platform through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ www.cisco.com/go/offices.$

Gisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-727559-00 04/13