



## End-of-Sale and End-of-Life Announcement for the Cisco TelePresence System Integrator Package 6000 MXP and Codec 6000 MXP

EOL8855

Cisco announces the end-of-sale and end-of-life dates for the Cisco TelePresence System Integrator Package 6000 MXP and Codec 6000 MXP. The last day to order the affected product(s) is May 14, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco TelePresence System Integrator Package 6000 MXP and Codec 6000 MXP

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 13, 2012
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 14, 2013
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	August 12, 2013
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 14, 2014
<b>End of Vulnerability/Security Support: HW</b>	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	May 13, 2016
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	May 14, 2014
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	May 14, 2014
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	August 9, 2017
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 31, 2018

HW = Hardware    OS SW = Operating System Software    App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CAB-ISDN1-5M	111890M1 ISDN 1 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN1-5M=	111890M1 ISDN 1 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN2-5M	111890M1 ISDN 2 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN2-5M=	111890M1 ISDN 2 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN3-5M	111890M1 ISDN 3 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN3-5M=	111890M1 ISDN 3 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN4-5M	111890M1 ISDN 4 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN4-5M=	111890M1 ISDN 4 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN5-5M	111890M1 ISDN 5 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN5-5M=	111890M1 ISDN 5 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN6-5M	111890M1 ISDN 6 Cable 5M	There is currently no replacement product available for this product.		
CAB-ISDN6-5M=	111890M1 ISDN 6 Cable 5M	There is currently no replacement product available for this product.		
CAB-T1-PRI-5M=	T1/PRI CABLE (5M)	There is currently no replacement product available for this product.		
CTS-6000-K9	Codec 6000 - Rackmt Kit, Rmt Cntrl and Pwr Cbl	CTS-C40-K9	Codec C40 - NPP, Rackmt Kit, Rmt Cntrl, HDMI And Pwr Cbl	-
CTS-6000-K9	Codec 6000 - Rackmt Kit, Rmt Cntrl and Pwr Cbl	CTS-C60-K9	Codec C60-Incls NPP, Rackmt Kit, Rmt Cntrl, HDMI And Pwr Cbl	-
CTS-6000-WP-K9	Codec 6000 - PAL, Encrypted, Rackmt Kit, Rmt Cntrl	There is currently no replacement product available for this product.		
CTS-6000CODEC-K9	6000 MXP Codec	There is currently no replacement product available for this product.		
CTS-6000CODEC-K9=	SPARE 6000 MXP Codec	CTS-C40CODEC-K9=	Codec C40 Unit - Spare	-
CTS-6000CODEC-K9=	SPARE 6000 MXP Codec	CTS-C60CODEC-K9=	C60 Unit Codec - SPARE	-
CTS-6000CODEC=	6000 CODEC Non Encrypted Version Spare	CTS-C40CODEC=	C40 CODEC Non Encrypted Version Spare	-
CTS-6000CODEC=	6000 CODEC Non Encrypted Version Spare	CTS-C60CODEC=	C60 CODEC Non Encrypted Version Spare	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-INTP6000-K9	6000 MXP - BW, PreHDCam, 2 Mics, Cbbs and Trackers 2M/6M	CTS-INTP-C40-K9	IntPkg C40 - NPP, Rmt Cntrl, 1 Mic, Cbbs ++	-
CTS-INTP6000-K9	6000 MXP - BW, PreHDCam, 2 Mics, Cbbs and Trackers 2M/6M	CTS-INTP-C60-K9	IntPkg C60 - NPP, PHD 1080p Cam, Rmt Cntrl, 1 Mic, Cbbs ++	-
L-6000-BW1	Order L-MXP-PAKforE-deliveryCodec6000MXP BW768 ISDN/3MIP	There is currently no replacement product available for this product.		
L-6000-BW2	Order LMXP-PakforE-delivery-6000MXP BW2M ISDN/4MExt/6MIP	There is currently no replacement product available for this product.		
L-6000-MS	Order L-MXP-PAKforE-delivery of LicnseKeyCodec 6000 Multisit	There is currently no replacement product available for this product.		
L-6000-NPP	Order L-MXP-PAK for E-delivery-Lic Key Codec6000 NPP Upgrade	There is currently no replacement product available for this product.		
L-6000MXP-BW1	Order L-MXP-PAK For 768 ISDN/3M IP Legacy 6000 MXP sys	There is currently no replacement product available for this product.		
L-6000MXP-BW2	Ord L-MXP-PAK for 2M ISDN/4M Ext/6M IP Legcy 6000 MXPsys	There is currently no replacement product available for this product.		
L-6000MXP-MS	Order L-MXP-PAK For MS Upg Legacy 6000 MXP sys (req NPP)	There is currently no replacement product available for this product.		
L-6000MXP-NPP	Order L-MXP-PAK For NPP Upg For Legacy 6000 MXP systems	There is currently no replacement product available for this product.		
LIC-6000-BW1	Codec 6000 MXP Bandwidth Option 768 ISDN/3M IP	There is currently no replacement product available for this product.		
LIC-6000-BW2	Codec 6000 MXP bw option 2M ISDN/4M Ext/6M IP	There is currently no replacement product available for this product.		
LIC-6000-BWD	Codec 6000 MXP 384/1.5M Bandwidth Option	There is currently no replacement product available for this product.		
LIC-INTP6000	License Key Codec IntPkg 6000 (Product ID)	There is currently no replacement product available for this product.		
LIC-INTP6000-BW	License Key Codec 6000 Bandwidth Option	There is currently no replacement product available for this product.		
LIC-INTP6000-MS	License Key Codec 6000 Multisite - MS Option	There is currently no replacement product available for this product.		
LIC-INTP6000-NPP	Lic Key Codec 6000 Natural Presenter Package (NPP) Option	There is currently no replacement product available for this product.		

---

## Product Migration Options

Customers using IP are encouraged to migrate to the Cisco TelePresence System Integrator C Series C40/C60. Customers using ISDN are encouraged to migrate to the Cisco TelePresence System Integrator C Series C40/C60 with Cisco TelePresence ISDN Link. Information about these products can be found at:

<http://www.cisco.com/en/US/products/ps11422/index.html> and

<http://www.cisco.com/en/US/products/ps12504/index.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

[http://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco TelePresence System Integrator Package 6000 MXP and Codec 6000 MXP through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to:

<http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco TelePresence System Integrator C Series C40/C60 and Cisco TelePresence ISDN Link, visit <http://www.cisco.com/en/US/products/ps11422/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)