

# End-of-Sale and End-of-Life Announcement for the Tandberg A/V Cart

#### EOL7891

Cisco announces the end-of-sale and end-of-life dates for the Tandberg A/V Cart. The last day to order the affected product(s) is January 1, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Tandberg A/V Cart

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 3, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 1, 2009
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	April 1, 2009
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 1, 2010
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 1, 2010
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 29, 2013
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2013

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
ACC-PWRSTRIP=	5 OUTLET POWER STRIP W/15ft AC CORD, NEMA
CTS-AVC-B5010502N	B5010502N Tandberg A/V Cart with Elmo High Res
CTS-CAB-5S1180240	5S118-0240 20 ft TOTAL VCR/DOC CAM EXTERNAL CABLE
CTS-CAB-5S1330048	5S133-0048 VCR/DOC CODEC BREAKOUT CABLE
CTS-ELMO-500866=	500866 Elmo high Resolution Doc Cam
CTS-SONY-502061	502061 Sony VCR/DVD combo

# **Product Migration Options**

There is no replacement available for the Tandberg A/V Cart at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives\_and\_promotions/tmp.html.

Customers may be able to continue to purchase the Tandberg A/V Cart through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <a href="http://www.cisco.com/go/eos">http://www.cisco.com/go/eos</a>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about\_cisco\_takeback\_recycling.html.

## For More Information

For more information about the Cisco End-of-Life Policy, go to: <a href="http://www.cisco.com/en/US/products/products/products-policy.html">http://www.cisco.com/en/US/products/products-policy.html</a>.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod\_warranties\_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: <a href="http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml">http://www.cisco.com/web/feeds/products/end\_of\_life\_rss.xml</a>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

 $Cisco\ has\ more\ than\ 200\ offices\ worldwide.\ Addresses,\ phone\ numbers,\ and\ fax\ numbers\ are\ listed\ on\ the\ Cisco\ Website\ at\ {\bf www.cisco.com/go/offices.}$ 

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA C51-688054-00 09/11