



## End-of-Sale and End-of-Life Announcement for the Tandberg 550 MXP

EOL7895

Cisco announces the end-of-sale and end-of-life dates for the Tandberg 550 MXP. The last day to order the affected product(s) is October 1, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Tandberg 550 MXP

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	April 2, 2009
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 1, 2009
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 30, 2009
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	October 1, 2010
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 1, 2010
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	December 27, 2013
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 30, 2014

HW = Hardware    OS SW = Operating System Software    App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-550-113539E0=	113539N SetTop 550 MXP NTSC Unit, SCCP, Encryption Rev 0-6	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-113539P=	113539P SetTop 550 MXP PAL Unit, Non-Encrypt Rev 0-6	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTS-550-113539PS=	113539P SetTop 550 MXP PAL Unit, SCCP, Encrypted Rev 0-6	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-NTSC	114135N, 114135ROK 550 MXP NTSC	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-NTSC-K9=	113539N SetTop 550 MXP NTSC Unit, Encrypted	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-PAL	114135P, 114135CN - 550 MXP PAL	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-PAL-K9=	113539P TANDBERG SetTop 550 MXP PAL Unit, Encrypted, Rev 0-6	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-SCCP-NTSC	114138N - 550 SCCP MXP, NTSC	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550-SCCP-PAL	114138P - 550 SCCP MXP PAL	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-
CTS-550PP-PAL	114130P - 550 MXP PP	CTS-EDGE75-K9	Edge75MXP Incl mic, NPP, 128 kbps ISDN/768 kbps IP, PHD Cam	-

## Product Migration Options

Customers are encouraged to migrate to the Cisco TelePresence System Edge 75 MXP. Information about this product can be found at: <http://www.cisco.com/en/US/products/ps11382/index.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at [http://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Tandberg 550 MXP through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: [http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

---

## For More Information

For more information about the Cisco TelePresence System Edge 75 MXP, visit <http://www.cisco.com/en/US/products/ps11382/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to: [http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: [http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA

C51-688149-00 09/11