



## End-of-Sale and End-of-Life Announcement for Cisco 10720 Router-Specific GE SFPs

Cisco Systems® announces the end-of-sale and end-of-life dates for the Gigabit Ethernet (GE) Small Form-Factor Pluggables (SFPs) specific to the Cisco® 10720 Router. The last day to order the affected products is December 30, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until December 30, 2010. Table 1 describes the end-of-life milestones, definitions, and dates for the affected products. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the extended-temperature GE SFPs, which are functionally equivalent to the current SFPs specific to the Cisco 10720. In addition, these SFPs support extended temperatures and are supported in a number of other Cisco products. Information about the replacement product is at: [http://www.cisco.com/en/US/products/hw/modules/ps5000/products\\_data\\_sheet0900aecd80285547.html](http://www.cisco.com/en/US/products/hw/modules/ps5000/products_data_sheet0900aecd80285547.html).

Table 3 provides relevant information for migrating to the replacement products.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 10720-Specific GE SFPs

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 30, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 30, 2005
Last Ship Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 30, 2006
End of SW Maintenance Release Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 30, 2005
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	December 30, 2006
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 30, 2006
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	June 30, 2008
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 30, 2010

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
10720-GE-SFP-SX	GE SFP—Short Reach 550m LC	SFP-GE-S	1000BASE-SX SFP
10720-GE-SFP-LH	GE SFP—Intermediate Reach 10 km LC	SFP-GE-L	1000BASE-LX/LH SFP

## Product Migration Options

The recommended replacements for the GE SFPs specific to the Cisco 10720 are the extended-temperature GE SFPs (Table 3).

**Table 3.** Product Comparisons

Feature	GE SFPs Specific to the Cisco 10720	Cisco Extended-Temperature GE SFPs
Temperature range	0°C to 70°C	–5 °C to 85°C

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about the Cisco TMP, go to: <http://www.cisco.com/go/tradein>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

[http://www.cisco.com/en/US/ordering/or6/or17/order\\_refurbished\\_equipment\\_program\\_description.html](http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html).

## For More Information

For more information about the Cisco 10720, visit: <http://www.cisco.com/en/US/products/hw/routers/ps147/index.html> or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica  
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR  
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico  
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia  
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R)  
Pa/LW9734 11/05

Printed in the USA

