



PRODUCT BULLETIN NO. 2491

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 10720 SPECIAL CISCO IOS SOFTWARE RELEASE 12.0SP TRAIN

Cisco Systems® announces the end of life of the Cisco IOS® Software Release 12.0SP Train of the Cisco® 10720 Router. Table 1 describes the end-of-life milestones, definitions, and dates. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the images based on the latest Cisco IOS Software Release 12.0S Train. Please note that the new version of the Gigabit Ethernet/Fast Ethernet TX module is only supported in Cisco IOS images based on Release 12.0(25)S or higher. The end-of-sale date for the older version of this card is June 30, 2004.

Table 1. End-of-Life Milestones and Dates for Cisco IOS Software Release 12.0SP Train

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	May 15, 2004
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 15, 2004
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 15, 2005
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 15, 2009

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
S107Z-12.0.20SP(=)	Cisco 10700 Series IOS Service Provider
S107K5Z-12.0.20SP(=)	Cisco 10700 Series IOS Service Provider/Secured Shell
S107Z-12.0.21SP(=)	Cisco 10700 Series IOS Service Provider
S107K5Z-12.0.21SP(=)	Cisco 10700 Series IOS Service Provider/Secured Shell

PRODUCT MIGRATION OPTIONS

The recommended replacement is Cisco IOS software Release 12.0S, which contains all new features as well as supports newer hardware modules.

Table 3. Product Comparisons

	12.0SP	12.0S
Number of releases	2	7
Release numbers	12.0(20)SP 12.0(21)SP	12.0(22)S 12.0(23)S 12.0(24)S 12.0(25)S 12.0(26)S 12.0(27)S 12.0(28)S
Features supported (major categories)	IPv4 basic features L2VPN based on UTI	IPv4 and MPLS features including L3VPN QoS enhancements L2VPN based on L2TPv3 and EoMPLS IPv6 features
Hardware modules supported	AC and DC chassis 24-port Fast Ethernet access module 4-port Gigabit Ethernet and 8-port Fast Ethernet access module—older version (EoS – June 30, 2004) 2XOC-48 DPT uplink modules 2XOC-48 POS uplink modules Console and auxiliary module	AC and DC chassis 24-port Fast Ethernet access module 4-port Gigabit Ethernet and 8-port Fast Ethernet access module—both older version and version B 2XOC-48 DPT uplink modules 2XOC-48 POS uplink modules Console and auxiliary module

ADDITIONAL INFORMATION

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive EOL/EOS information please go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0403R)

Gr/LW-6299 05/04