

End-of-Sale and End-of-Life Announcement for Select Cisco 1803W and 1811W Integrated Services Routers and the Cisco 802.11g/a High-Speed WAN Interface Cards for the Americas

EOL5834

Cisco Systems® announces the end-of-sale and end-of life dates for select Cisco 1803W and 1811W Integrated Services Routers and select Cisco 802.11g/a High-Speed WAN Interface Card for the Americas. The last day to order these select Cisco 1803W and 1811W Integrated Services Routers and the Cisco 802.11g/a High-Speed WAN Interface Card for the Americas is June 29, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the select Cisco 1803W and 1811W Integrated Services Routers and the Cisco 802.11g/a High-Speed WAN Interface Card for the Americas. Table 2 lists the product part numbers affected by this announcement.

Cisco announces the end-of-sale and end-of life dates for the Cisco 1803 Integrated Services Router model 1803W-AG-A/K9, the Cisco 1811 Integrated Services Router model 1811W-AG-A/K9, and the High-Speed WAN Interface Card model HWIC-AP-AG-A, which operates in the 5 GHz UNII-2 band in North America. The A version models (designated in the product number) are being replaced, and customers are encouraged to migrate to the B version models. The new models are fully compliant with FCC regulations for operations in the 5 GHz UNII-2 band. Migration to the new models is required to meet FCC wireless specifications that become effective in July 2007. Customers with existing products can continue to use their equipment; the FCC requirements apply only to new product shipments based on the dates in this bulletin.

Table 1. End-of-Life Milestones and Dates for the Select Cisco 1803 and 1811 Integrated Services Routers and Select Cisco 802.11 High-Speed WAN Interface Card for the Americas

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 29, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 20, 2007
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	June 29, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 29, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 7, 2012
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 29, 2012

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CISCO1803W-AG-A/K9	G.SHDSL Router with 802.11a+g FCC Compliant and Security	CISCO1803W-AG-B/K9	G.SHDSL Router with 802.11a+g FCC Compliant and Security
CISCO1811W-AG-A/K9	Security Router with 802.11a+g FCC Compliant and Analog B/U	CISCO1811W-AG-B/K9	Security Router with 802.11a+g FCC Compliant and Analog B/U
HWIC-AP-AG-A	AP HWIC, 2 radios(2.4/5Ghz Radios 802.11 a/b/g) Americas	HWIC-AP-AG-B	AP HWIC, 2 radios(2.4/5Ghz Radios 802.11 a/b/g) FCC
HWIC-AP-AG-A=	AP HWIC, 2 radios(2.4/5Ghz Radios 802.11 a/b/g) Americas	HWIC-AP-AG-B=	AP HWIC, 2 radios(2.4/5Ghz Radios 802.11 a/b/g) FCC

Product Migration Options

Customers are encouraged to migrate to the Cisco 1803 Integrated Services Router model W-AG-B/K9, the Cisco 1811 Integrated Services Router model W-AG-B/K9, and the Cisco High-Speed WAN Interface Cards HWIC-AP-AG-B and HWIC-AP-AG-B=. Information about these products can be found at

http://www.cisco.com/en/US/prod/collateral/routers/product_promotion0900aecd8017150a.html.

Table 3. Product Comparisons

Feature	CISCO1803W-AG-A/K9, CISCO1811W-AG-A/K9, HWIC-AP-AG-A, HWIC-AP-AG-A=	CISCO1803W-AG-B/K9, CISCO1811W-AG-B/K9, HWIC-AP-AG-B, HWIC-AP-AG-B=
802.11a operation in the 5 GHz UNII-2 band	Meets FCC compliance from previous 5 GHz UNII-2 band specifications	Meets FCC compliance for new 5 GHz UNII-2 band specifications

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_program_description.html.

For More Information

For more information about the Cisco 1803W and 1811W Integrated Services Routers (models 1803W-AG-B/K9 and 1811W-AG-B/K9) and the Cisco 802.11g/a High-Speed WAN Interface Cards for the Americas (HWIC-AP-AG-B and HWIC-AP-AG-B=), visit http://www.cisco.com/en/US/prod/collateral/routers/product_promotion0900aecd8017150a.html, contact your local account representative, or send an e-mail to cs-isrwireless@cisco.com.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0889

Asia Pacific Headquarters
Cisco Systems, Inc.
16B Robinson Road
#29-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7769

Europe Headquarters
Cisco Systems International BV
Hendrikweg 13-19
1011 CA Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 20 620 6791
Fax: +31 0 20 657 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CDP®, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc. Changing the Way We Work, Live, Play and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCA, CDR, CDR, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, IPPhone, IPTV, IQ Expertise, the IQ logo, IQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (070529)