

## New Fan and Air Filter Kit for Cisco 3825-DC Integrated Services Router

PB521786

## Overview

As of February 10, 2009, Cisco is announcing support for a fan and air filter and 23-inch center rack-mount kit for the Cisco 3825-DC Integrated Services Router only. The two new product part numbers are ACS-3825-FILTRKIT= and the ACS-3825-FILTER=. The Cisco 3825-DC Air Filter (part number ACS-3825-FILTRKIT=) includes a single, center-mounted, 23-in. rack-mount kit and a side-mounted air and fan filter element. The CISCO3825 air filter (ACS-3825-FILTER=) includes the air and fan filter element only. This product is intended for use in Data Communications Network (DCN) environments, specifically for AT&T and other U.S service providers for deployment in central-office locations. The CISCO 3825-DC Air Filter kit (ACS-3825-FILTRKIT=) was tested in accordance with Network Equipment Building Standards (NEBS) and Telcordia GR-63-CORE operating temperature standards with the filter in place, including limited short-term excursions of temperatures beyond 40°C.

List price for the Cisco 3825-DC Air Filter kit (ACS-3825-FILTRKIT=) is \$350.00. List price for the Cisco 3825-DC Air Filter (ACS-3825-FILTER=) is \$100.

## **Related Links**

Cisco 3800 Data Sheet:

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product\_data\_sheet0900aecd8016a8e\_8.html

Cisco Integrated Services Routers

## For More Information

For more information about the Cisco 3825 Air Filter kit, please send an email message to the Cisco 3800 Series Product alias: <u>cs-3800@cisco.com</u>.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systoms (USA) Pic. Ltd. Singapore Europe Headquarters Cisco Systema International BV Arnsterdam, The Netherlands

Clace has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Clace Website at www.cisco.com/go/offices.

CODE, CODE, Class East Class Health Presence, the Class Clas

All other trademarks mentioned in this document or website are the property of their respective eremere. This use of the word permer does not imply a permerable relationship between Cisco and any other company, (9812H).

Printed in USA C25-521786-00 02/09